



# Framework Plan

The MSP Redevelopment Project

M S P




Bob Holden, Governor



*“Make no little plans; they have no magic to stir men’s blood and probably themselves will not be realized. Make big plans; aim high in hope and work, remembering that a noble, logical diagram once recorded will never die, but long after we are gone will be a living thing, asserting itself with ever growing insistency. Remember that our sons and grandsons are going to do things that would stagger us. Let your watchword be order and your beacon beauty.”*

*Daniel Burnham - 1907*



# Framework Plan

The MSP Redevelopment Project

M S P



October 2003

## Acknowledgements

The Parsons Project Team wishes to give special thanks to the following individuals, committees and agencies for their participation and support during the preparation of the **Framework Plan**.

### **Governor**

**Bob Holden**

### **MSP Redevelopment Commission**

**William J. Carr**, Chairman

**John Sheehan**, Member

**Duane Weaver**, Member

**Jim Wunderlich**, Member

**Sarah Riddick**, Member

**Kathleen Mahfood**, Member

**Robert Meyer**, Member

**Mark Schreiber**, Member

**James Callis**, Member

**John Landwehr**, Member

### **Executive Advisory Committee**

**John Bain**, Co-Chairman, Office of Administration

**Katherine Conner**, OA Division of Budget & Planning

**Jim Grothoff**, Department of Corrections

**Paul Caspari**, Department of Corrections

**Dave Dormire**, Department of Corrections

**Mark Schreiber**, Department of Corrections

**Jane Beetem**, Department of Natural Resources

**Brian Fawks**, Department of Natural Resources

**Earl Pabst**, Department of Natural Resources

**Booker Rucker**, Department of Natural Resources

**Marty Romitti**, Department of Economic Development

**Jim Riley**, Joint Committee on Capitol Improvements

**Rich Mays, Co-Chairman**, City Administrator, City of Jefferson

**Carol Blaney**, City Councilwoman, City of Jefferson

**Charles Jackson**, City Councilman, City of Jefferson

**Mike Forck**, Cole County Commissioner

**Chris Yarnell**, Cole County Public Works

**John Hemeyer**, Sheriff, Cole County

**Betty Jo DeLong**, Member, Jefferson City Chamber of Commerce (City Resident)

**Jeanie Moore**, Member, Jefferson City Chamber of Commerce (Modern Litho Print)

**Mark Towner**, Member, Jefferson City Chamber of Commerce (Towner Electronics)

**Keith Fuller**, Member, Jefferson City Chamber of Commerce (Lincoln University)

## Acknowledgements

### Support Staff

**Randy Allen**, Director  
Division of Design and Construction  
**Charlie Brzuchalski**, Project Manager  
Division of Design and Construction

### The Planning Advisory Committee

**Randy Allen**, Division Of Design & Construction  
**Charles Brzuchalski**, Division Of Design & Construction  
**Mark Schreiber**, Department of Corrections  
**Chris Yarnell**, Cole County Public Works  
**Jack Kramer**, Public Works, City of Jefferson  
**Janice McMillan**, City Planner, City of Jefferson

### Others

**Jackie White**, Office of Administration  
**Gary Kempker**, Department of Corrections  
**Joe Driskill**, Department of Economic Development  
**Steve Mahfood**, Department of Natural Resources  
**Senator Larry Rohrbach**  
**Representative Bill Gratz**  
**Representative Carl Vogel**  
**Tom Rackers**, Former Mayor, City of Jefferson  
**Bob Jones**, Cole County  
**Don Shinkle**, Jefferson City Area Chamber of Commerce

### The Planning Team

**Parsons**, Dan Bockert, Project Manager  
**Development Strategies**, Bob Lewis  
**Trivers Associates**, Jeff Morrisey  
**TSi Engineering**, Sylvester Douglas  
**William Tao & Associates**, Bruce Levitt  
**George Dickie Associates**, George Dickie

### The Citizens of Jefferson City, Cole County and The State Of Missouri

## Table of Contents

<i>Chapter</i>	<i>Pages</i>		
<b>Executive Summary</b>	<b>ES – 1</b>	<b>to</b>	<b>ES - 6</b>
<b>The Master Plan</b>	<b>MP - 1</b>	<b>to</b>	<b>MP – 50</b>
<b>Master Plan Amendments</b>	<b>PA - 1</b>	<b>to</b>	<b>PA - 3</b>
<b>Market Analysis</b>	<b>MA – 1</b>	<b>to</b>	<b>MA -15</b>
<b>Architecture</b>	<b>AR – 1</b>	<b>to</b>	<b>AR - 40</b>
<b>Building Systems</b>	<b>BS – 1</b>	<b>to</b>	<b>BS - 14</b>
<b>Environmental Summary</b>	<b>ES – 1</b>	<b>to</b>	<b>ES - 5</b>

### Appendices (Under Separate Cover)

#### **Appendix A**

Phase I Environmental Assessment – Jefferson City Correctional Facility (MSP) June 3, 2002

Phase I Environmental Assessment – State Agency for Surplus Property June 29, 2001

#### **Appendix B**

Observations of the Enclosure Walls

#### **Appendix C**

PowerPoint Handout - Public Presentation - February 11, 2003

#### **Appendix D**

Existing Buildings To Remain - Drawing

The Master Plan - Drawing

Master Plan Sketch Looking East

Master Plan Sketch Looking West



# Executive Summary

**M S P**

## Executive Summary

### Introduction

#### *Background & History*

The Jefferson City Correctional Center (JCCC) is located in the central east end of Jefferson City, within the city limits. The site is bounded on the north by the Missouri River and the Union Pacific Railroad; on the east by a privately owned parcel of land and Riverside Park; on the south by Riverside Drive, Capitol Avenue, Lafayette St. and East State St; and on the west by a parcel of land owned by the Jefferson City Housing Authority.

The Missouri State Penitentiary (later named Jefferson City Correctional Center) was the first prison built west of the Mississippi River. It was authorized in 1832 and approved by the General Assembly in 1833. By the time the first prisoner arrived in 1836, it covered a four-acre tract on the eastern edge of Jefferson City. Today, the entire site of the Jefferson City Correctional Center covers approximately 142 acres (47 acres within the perimeter walls) of river bluff land, seven blocks east of the State Capitol. Some of the area outside the walls is undeveloped wooded ridges and valleys along the Missouri River. The character of the adjoining neighborhoods range




View of JCCC Looking to the Northeast

## Executive Summary

from the well-maintained historic renovation of the “Marmaduke House,” the former warden’s house at Capitol and Lafayette, to a number of aging, poorly maintained houses found within the area. The area is included in a district classified as “distressed.”

Currently (2003) a new Missouri State Corrections Facility is under construction. When the new facility is complete, the current operations of the Jefferson City Correctional Center will be moved to the new facility. The decommissioning and subsequent redevelopment of the Jefferson City Correctional Center site provides both a unique challenge and a rare opportunity. It is not often that such a large site so close to the center of a state capital becomes available. The range of redevelopment options offered for the site is wide and quite varied. The site also includes a widely diverse array of existing land uses and facilities.

In July of 1999, the State of Missouri, through the Division of Design & Construction, developed a task list to address the upcoming decommissioning of the Jefferson City Correctional Center (JCCC). By the end of 1999, a newly formed Task Force had started the preparation of an evaluation of its concepts, values and priorities. After successfully conducting a statewide design charrette for the JCCC in April 2000, the State of Missouri began the initial planning effort, titled the **Process Definition Plan** or Consensus Plan.



The Consensus Plan

## Executive Summary

The plan was started in late August 2000 and completed in 100 days with general consensus from the Oversight Committee, Task Force and citizens that participated in the public input sessions. The Process Definition Plan was presented to a joint meeting of the Oversight Committee and Task Force at a public forum on November 16, 2000.

### The Framework Plan

The Framework Plan (master plan) presented herein is the culmination of the creative design synthesis of data analysis, program development and site planning that has resulted in a distinct vision for the MSP Redevelopment Project (renamed from “the Jefferson City Correctional Center - JCCC”). Founded on the functional relationships achieved in the Process Definition Plan and confirmed throughout the planning process, the Framework Plan illustrates decisions that will guide the ultimate redevelopment of the Missouri State Penitentiary (MSP) for years to come.

### **Basis of the Master Plan**

The Process Definition Plan (Consensus Plan) is the basis and beginning point of the Master Plan, a plan which has emerged illustrating a great amount of detail, while maintaining previously established planning principles. In addition, formulation of the




The Master Plan

## Executive Summary

Master Plan has been based on extensive data collection, interviews with community leaders, workshops with the Planning Advisory Committee and real-time development opportunities (i.e. DNR Green Building). The formulation of the MSP Redevelopment Commission has greatly increased the reality factor of the project and has also maintained the Project’s momentum, guaranteeing the planning and development process will continue, moving the Master Plan recommendations forward to fruition. The Master Plan has been presented to: the Task Force that participated in the Process Definition Plan; two separate sessions of the MSP Redevelopment Commission; and two separate public forums. The Planning Advisory Committee also conducted a workshop to review planning concepts and refine the details contained in this Master Plan.

While each presentation has generated much discussion and revealed new aspects of the master plan to ponder, the plan presented herein has been generally understood, accepted and embraced as a vision for the future of The MSP Redevelopment Project. During the interview process, one community leader summed up the project by saying “someday this will be a cool place to go!”



The Master Plan Districts

## Executive Summary

### The Program Statement

The Consensus Plan established seven primary land use areas that identified the redevelopment potential within the context of the historical, cultural and functional aspects of the existing MSP site. These elements have formed the basis of the program statement, evolving from seven land use classifications to five Master Plan districts. The terminology has been refined, the project vision sharpened and the level of conceptual detail has begun to illustrate the physical components of the plan.

<u>Master Plan District</u>	<u>Proposed/Reuse Area</u>	<u>Master Plan Parking</u>	
❖ Public Service Campus	225,000 Gross Floor Area (GFA)	485 Structured Spaces	P-1
❖ MSP Historic Area	310,048 GFA	600 Structured Spaces	P-2
❖ Public Assembly Campus	605,500 GFA	650 Structured Spaces	P-2
		100 Structured Spaces	P-3
		300 Structured Spaces	P-3
		250 Surface Spaces	P-4
❖ Office Campus	1,000,000 GFA	850 Structured Spaces	P-5
		600 Structured Spaces	P-7
❖ Natural Resources Area NA		15 Surface Spaces	P-6
Total	<b>2,105,548 GFA</b>	<b>3,850 Space</b>	


## Executive Summary

### Summary

The elements of the Framework Plan presented herein have been discussed, pondered, refined, even implemented from the first planning efforts of 1999 to the completion of this report. The Framework Plan has been generally endorsed by all who have reviewed its content and vision. It is a plan prepared on the basis of consensus and a rigorous planning process. The MSP Redevelopment Commission should, with all confidence, immediately move forward with implementing the recommendations contained herein. All who have participated in this planning process are reminded of the philosophy that linked each step of preparing this plan:

*“Make no little plans; they have no magic to stir men’s blood and probably themselves will not be realized. Make big plans; aim high in hope and work, remembering that a noble, logical diagram once recorded will never die, but long after we are gone will be a living thing, asserting itself with ever growing insistency. Remember that our sons and grandsons are going to do things that would stagger us. Let your watchword be order and your beacon beauty.” Daniel H. Burnham - 1907*

**Daniel Hudson Burnham** (September 4, 1846 - June 1, 1912) was an American architect and urban planner. He was the Director of Works for the World's Columbian Exposition and designed several famous buildings, including the Flatiron Building in New York City and Union Station in Washington D.C.





# The Master Plan

**M S P**

# The Master Plan

## Introduction


The Master Plan presented herein is the culmination of the creative design synthesis of data analysis, program development and site planning that has resulted in a distinct vision for the MSP Redevelopment Project. Founded on the functional relationships achieved in the Process Definition Plan and confirmed throughout the planning process, The Master Plan illustrates decisions that will guide the ultimate redevelopment of the Missouri State Penitentiary (MSP) for years to come.

## Basis of the Master Plan

The Process Definition Plan (Consensus Plan) prepared in March 2001 is the basis and beginning point of The Master Plan. Since the final Process Definition Plan was presented to the public on November 6, 2000, the Master Plan has emerged, illustrating a great amount of detail, while maintaining the principles previously established by the Process Definition Plan. In addition, formulation of The Master Plan has been based on extensive data collection, interviews with community leaders, workshops with the Planning Advisory Committee and real-time development opportunities (i.e. DNR Green Building). The formulation of the MSP Redevelopment Commission has greatly increased the reality factor of the project and has also maintained the Project's momentum, guaranteeing the planning and development process will continue to move The Master Plan recommendations forward to fruition. The Master Plan has been presented to: the Task Force that participated in the Process Definition Plan; two separate sessions of the MSP Redevelopment Commission; and two separate public forums. The Planning Advisory Committee also conducted a



The Consensus Plan



The Master Plan

## The Master Plan

### Introduction *(continued)*

workshop to review planning concepts and refine the details contained in The Master Plan.

While each presentation has generated much discussion and revealed new aspects of the master plan to ponder, the plan presented herein has been generally understood, accepted and embraced as a vision for the future of The MSP Project. During the interview process, one community leader summed up the project by saying “someday this will be a cool place to go!”

### The Program Statement

The Consensus Plan established seven primary land use areas that identified the redevelopment potential within the context of the historical, cultural and functional aspects of the existing MSP site. These elements have formed the basis of the program statement, evolving from seven land use classifications to five master plan districts. The terminology has been refined, the project vision sharpened and the level of conceptual detail has begun to illustrate the physical components of the plan.


The Consensus Plan land use categories are now Master Plan Districts:

- Historic Area is now the MSP Historic Area
- Judicial Center Area is now the Public Service Campus
- Community Area is now A part of the MSP Historic Area
- Office Area is now the Office Campus
- Entertainment Area is now the Public Assembly Campus
- Landing Area is now a part of the Public Assembly Campus
- Natural Resources Area is now the Natural Resources Area

The Master Plan Program Statement is the narrative interpretation of the Process Definition Plan, founded on market analysis, user potential, community needs and an understanding of the MSP site and architectural resources. Not all the ideas suggested have made it into The Master Plan, but the ideas put into The Master Plan will.... “assert itself with ever growing insistency.” (Daniel Burnham – 1907).

# The Master Plan

## The Program Statement



# The Master Plan

## The Program Statement Summary

<u>Master Plan District</u>	<u>Proposed/Reuse Area</u>	<u>Master Plan Parking</u>	
❖ Public Service Campus	225,000 GFA	485 Structured Spaces	P-1
❖ MSP Historic Area	310,048 GFA	600 Structured Spaces	P-2
❖ Public Assembly Campus	605,500 GFA	650 Structured Spaces	P-2
		100 Structured Spaces	P-3
		300 Structured Spaces	P-3
		250 Surface Spaces	P-4
❖ Office Campus	1,000,000 GFA	850 Structured Spaces	P-5
		600 Structured Spaces	P-7
❖ Natural Resources Area NA		15 Surface Spaces	P-6
<b>Total</b>	<b>2,105,548 GFA</b>	<b>3,850 Spaces</b>	

**The Master Plan**

**MSP Historic Area Program Statement**

<b>Administration Building</b>	26,300 GFA
Housing Unit #1 (26,300 sf)	
Historic Site, Museum/Interpretative	
MSP Commission Offices	
Redevelopment Office	
Support Retail / Commercial	
Tourist Information Center	
Film Site or Studio	
Educational	
<b>Office Building</b>	72,000 GFA
Housing Unit #2 (72,000 sf)	
Corrections Offices	
<b>Office Building</b>	48,000 GFA
At Housing Unit #2 – New	
Building Addition (48,000 sf)	
Corrections Offices	
<b>Centennial Cells</b>	
Historic Display	None
<b>Office Building</b>	
Housing Unit #3 (75,600 sf)	
State Offices	15,600 GFA
Record Storage	30,000 GFA
Prison Museum (40%)	30,000 GFA

**The Master Plan**

**MSP Historic Area Program Statement** *(continued)*

**MSP Museum**

Housing Unit #4 (43,000 sf) 43,000 GFA

**Conference Center**

Historic Dining Hall Basement (11,100 sf)

Power Plant (Basement) 11,100 GFA  
 Dining Rooms & Kitchen 11,100 GFA  
 Conference Center 11,100 GFA  
 Conference Center 11,100 GFA

**The Wall**

None

The Perimeter Wall  
 Guard Tower Reconstruction  
 The Old Wall  
 Pedestrian Openings  
 Vehicular Openings

**The Gas Chamber** (748 sf)

748 GFA

**Community Area**

None

MSP Interpretative Garden  
 Pedestrian Linkages  
 Open Space  
 Urban Plaza (interpretative plaza)  
 Office Space (see Housing Unit #2 Bldg Addition)

**Total MSP Historic Area 310,048 GFA 600 Structured Spaces P-2**

**The Master Plan**

**Public Service Campus Program Statement**

<b>Justice/Office Center</b>	150,000 GFA		
Court Rooms			
Offices			
Holding Space			
<b>Public Service Office Building</b>	50,000 GFA		
Private Office Space			
Support Retail/Commercial			
Art Gallery			
Science Center			
<b>Justice/Office Center Annex</b>	25,000 GFA		
Administrative Offices			
Library			
Museum			
<b>Other</b>	None		
Streetscape			
Pedestrian Entry Plaza			
Pedestrian Linkages			
Transportation Linkages			
Access to Adrian’s Island			
<b>Total Public Service Campus</b>	<b>225,000 GFA</b>	<b>485 Structured Spaces</b>	<b>P-1</b>



**The Master Plan**

**Public Assembly Campus Program Statement (continued)**

<b>Potato House (24,000 sf)</b>	24,000 GFA		
Commercial / Retail			
Farmers Market			
Interpretative Center			
Trail Head			
Greenway Trail Connection			
<b>Other</b>	None		
Streetscape			
Public Plaza			
Pedestrian Linkages			
Transportation Linkages			
Access to Adrian’s Island			
<b>Total Public Assembly Campus</b>	<b>605,500 GFA</b>	<b>650 Structured Spaces</b>	<b>P-2</b>
		<b>100 Structured Spaces</b>	<b>P-3</b>
		<b>300 Structured Spaces</b>	<b>P-3</b>
		<b><u>250 Structured Spaces</u></b>	<b>P-4</b>
		<b>1,300 Spaces Total</b>	

**The Master Plan**

**Office Campus Program Statement**

<p><b>State Government Office</b></p> <ul style="list-style-type: none"> <li>General Office Space (550,000 sf)</li> <li>DNR Green Building (120,000 sf)</li> <li>Health Lab (80,000 sf)</li> <li>Support Commercial / Retail</li> <li>Service Area</li> <li>Shuttle Access</li> </ul>	<p>750,000 GFA</p>		
<p><b>Private Business Office</b></p> <ul style="list-style-type: none"> <li>General Office Space</li> <li>Support Commercial / Retail</li> <li>Service Area</li> <li>Shuttle Access</li> </ul>	<p>250,000 GFA</p>		
<p><b>Other</b></p> <ul style="list-style-type: none"> <li>Streetscape</li> <li>Public Plaza</li> <li>Pedestrian Linkages</li> <li>Transportation Linkages</li> </ul>	<p>None</p>		
<p><b>Total – Office Campus</b></p>	<p><b>1,000,000 GF</b></p>	<p><b>850 Structured Spaces</b></p> <p><b><u>600 Structured Spaces</u></b></p> <p><b>1,450 Spaces</b></p>	<p><b>P-5</b></p> <p><b>P-7</b></p>

## The Master Plan

### Natural Resource Area Program Statement

Riverfront Park	None		
Active and Passive Recreation			
Picnic Areas			
Public Land Open Space			
Greenway Trail Connection			
Botanical Gardens			
Amphitheater			
Build & Ground Maintenance			
Reserve Land For Future			
<b>Total – Natural Resource Area</b>	<b>0 GF</b>	<b>15 Surface Spaces</b>	<b>P-6</b>

## The Master Plan

### The Master Plan Overview

The Master Plan for The MSP Redevelopment Project is a further refinement of the Consensus Plan, illustrating a greater level of detail than previously presented. The Master Plan will change over time as development opportunities arise with more detailed programmatic statements, detailed designs and more extensive site investigations. While the graphic illustration of the Master Plan will likely change, the design principles on which it is based should be vigorously defended and preserved.

The following descriptions include:

- Circulation and Parking
- Pedestrian Circulation and Linkages
- MSP Historic Area
- Public Service Campus
- Public Assembly Campus
- Office Campus
- Natural Resources Area



Proposed Master Plan Looking East

**The Master Plan**

**The Master Plan Overview (continued)**




**Legend**

<b>PUBLIC SERVICE CAMPUS</b>	<b>OFFICE CAMPUS</b>
J-1 Justice / Office Center	O-1 Office Building
J-2 Public Service Office Building	O-2 Office Building
J-3 Pedestrian Plaza above Structured Parking	O-3 Office Building
J-4 Justice / Office Center Annex	O-4 Office Building
J-5 Pedestrian/Auto Plaza	O-5 Office Building
	O-6 Office Building
	O-7 Office Building
	O-8 Courtyard/Plaza
	O-9 Motor Court
	O-10 Pedestrian Plaza above Structured Parking
	O-11 Office Building
	O-12 Water Feature
<b>MSP HISTORIC AREA</b>	<b>NATURAL RESOURCES AREA</b>
H-1 MSP Office Building (Housing Unit 1)	N-1 Wooded Area
H-2 Office Building (Housing Unit 2)	N-2 Open Prairie/Meadow
H-3 Office Building (Housing Unit 3)	N-3 Recreation Trail
H-4 MSP Museum (Housing Unit 4)	N-4 Restoration Pavilion
H-5 Hotel 1 (Housing Unit 5)	N-5 Grounds Maintenance
H-6 Conference Center	
H-7 Quadrangle	
H-8 Centennial Cells Excavation	
H-9 Gas Chamber	
H-10 MSP Interpretative Garden	
H-11 Wall Penetration	
H-12 Wall	
H-13 Guard Tower	
H-14 Ramport Wall	
H-15 Slaughter House Smoke Stack	
H-16 Potato House	
H-17 Water Tower	
H-18 Historic Stone Retaining Wall	
<b>PUBLIC ASSEMBLY CAMPUS</b>	<b>PARKING</b>
E-1 Hotel 2	P-1 Structured Parking
E-2 Pedestrian Plaza above Structured Parking	P-2 Structured Parking
E-3 Elevated Link to Rivers' Edge	P-3 Surface Grade Parking
E-4 Excursion Boat Landing	P-4 Surface Parking
E-5 Hotel 3	P-5 Structured Parking
E-6 Water Feature and Pedestrian Plaza	P-6 Surface Parking
E-7 Retail/Commercial at the Landing	P-7 Structured Parking
E-8 Public Assembly Facility	
E-9 Auditorium	
E-10 Exhibition	
E-11 Multi-Purpose	
	<b>ROADWAY CLASSIFICATION</b>
	R-1 Parkway
	R-2 Round-about
	R-3 Secondary Roadway

The Master Plan

# The Master Plan

## The Master Plan Overview (continued)



Proposed Master Plan Looking West

# The Master Plan

## Circulation and Parking

The roadway system depicted in The Master Plan is a combination of new roadways within the MSP site and utilization of the existing street network. The MSP Parkway (yellow) extends in an east-west direction from East State Street at Marshall Street, through the prison site, east to East Capitol Street near Dawson Street. The Chestnut Street Parkway (purple) will connect into the MSP Parkway as will the Office Campus Loop Road (red), which will also connect The MSP Parkway to Riverside Drive.

In order to provide the appropriate level of “curb appeal” to the MSP Redevelopment Project, the parkways and roadways must provide direct and attractive access to the various components of The Master Plan. The parkways and roadways should contain a center planter island, left turn lanes, bicycle lanes, pedestrian sidewalks, street lighting and banners, and be wide enough to accommodate infrastructure such as water, gas, storm and sanitary sewer, underground electrical, etc. The existing streetscape surrounding the project area should be enhanced. Street trees, lighting, sidewalks, signage and other similar elements should be incorporated into the street system surrounding the project area.



Typical Parkway

# The Master Plan

## Circulation and Parking *(continued)*

The MSP Parkway as well as The Chestnut Street Parkway connector will serve as entrance gateways to the redevelopment project. Signage, plantings and gateway features should be incorporated into the intersections at East State Street, East Capitol Street and Riverside Drive.

The new roadways will converge east of the prison wall at Chestnut Street. Rather than a four way lighted intersection, The Master Plan proposes a round-a-bout at the intersection of the MSP Parkway, the Chestnut Street Parkway and the Office Campus Loop Road. The round-a-bout will efficiently distribute traffic, provide for traffic calming and create an opportunity for aesthetic enhancements such as decorative paving, lighting, signage, art work, water features, monuments, etc.



Typical Roadway



Round-A-Bout



Entrance Feature

## The Master Plan

### Circulation and Parking (continued)

The Master Plan provides for 3,850 parking spaces within the MSP site. The parking is distributed throughout the MSP site as shown below, the numbers in the circle represent parking spaces. Because of the density of the proposed development, the physical topographic site features and a desire to preserve open space, The Master Plan recommends the majority of parking to be structured spaces. The structured spaces should be low profile, blend into the site and inviting to visitors. Surface Parking should avoid large expanses of asphalt and should incorporate site amenities such as signage, plantings, lighting, banners and pedestrian walkways. On the diagram below all parking is structured spaces except for the 250 and 15 space indicators.



Structured Parking



Surface Parking

## The Master Plan


### Pedestrian Circulation and Linkages

The Master Plan provides pedestrian access between the various districts within the MSP project area as well as to land uses surrounding the MSP site. The campus planning principle which has guided the development of The Master Plan places great emphasis on consolidated perimeter parking, direct service/emergency access and extensive pedestrian connections. Vehicular movements and vehicular/pedestrian conflicts should be minimized with “shuttle bus” connections to the Capitol Complex, downtown, and other business/entertainment/education venues.

Connections to the neighborhood will be reinforced with “wagon gate” openings in the existing wall that remains, located at Cherry Street and at the intersection of East State Street and Lafayette Street. In addition there will be open pedestrian access where the wall will be removed at the extension of Lafayette Street to the MSP Parkway and along the western side of the Chestnut Street Parkway.

Internally, pedestrians will have safe access throughout the site with designated pedestrian crossings and internal walkways and corridors, free of vehicular conflicts. The Natural Resource Area will contain an extensive “nature trail” system that will serve the working population, the neighborhood and the entire community. The Natural Resource Area trail system will provide the opportunity to connect Ellis Porter Riverside Park ,through the MSP site to the Capitol Complex via a combination of trails and urban sidewalks.

Bicycle connections and access through the existing and proposed streets system will be critical in maximizing the potential of reducing vehicular movements, saving energy and creating an environment commensurate with the “smart growth” principles that have guided the master plan development.




Wagon Gate at Lafayette Street

# The Master Plan

## MSP Historic Area

The MSP Historic Area is generally located on the upper yard, inside the existing prison wall. The Master plan calls for extension of Lafayette Street (after the existing Administration Building is razed) to the MSP Parkway. This area contains the core group of historic buildings that have been incorporated into the master plan for adaptive reuse, preservation or restoration. The MSP Historic Area is intended to represent a time spectrum of prison environments, creation of theme opportunities for interpretation and the reconstruction of buildings lost or “covered up” by newer construction over time. Housing Unit #5 (H-5) is discussed in the Public Assembly Campus chapter.

The MSP Historic Area is focused around several outdoor pedestrian spaces; a pedestrian quadrangle (H-7) formed by Housing Units 4, 3 and 1; and an interpretative garden (H-10) between Housing Unit 2 and the Wall. These community park spaces will serve the working population within this district and provide access and green space to the adjoining neighborhood. Visitors to the points of interest such as the Prison Museum (H-4) located in Housing Unit 4 will use these outdoor spaces for resting, enjoying the views, contemplative space and enjoying the spatial quality formed by the historic buildings.



## The Master Plan

### MSP Historic Area *(continued)*

Several remote site features have been included in the MSP Historic Area, even though not immediately adjacent to the core redevelopment area, they are closely aligned to the history of the prison operations. The Gas Chamber (H-9), Slaughter House Smokestack (H-15), Potato House (H-16), Water Tower (H-17) and Historic Stone Retaining Wall (H-18) are important historical features of the site that will provide important interpretative opportunities as visitors explore the site.

The Gas Chamber (H-9) is located on the lower yard at its original site, remote from the former housing units. The Master Plan retained this location to convey the separation and isolation inmates must have felt toward the chamber. This location will also promote visitors to move out into the site and explore other features such as the Potato House. Each of the remote features will encourage visitors to explore the site and discover the uniqueness of the project area.

Parking for the MSP Historic Area will be primarily from the proposed parking structure P-2 located “behind the wall” at the intersection of East Capitol and the Chestnut Street Parkway.




## The Master Plan

### MSP Historic Area *(continued)*

**The MSP Office Building (H-1)** contains 26,300 GFA and is also known as Housing Unit #1. A portion of this building is encased by the existing Administrative Building. After the existing Administration Building is removed and Lafayette Street is extended to the MSP Parkway, the MSP Office Building will regain its' status as one of the site's main architectural features, serving as the architectural gateway to the redevelopment. Anticipated uses for the MSP Office Building include:

- Historic Site, Museum/Interpretative
- MSP Commission Offices
- Redevelopment Office
- Support Retail / Commercial
- Tourist Information Center
- Film Site or Studio
- Educational




## The Master Plan

### MSP Historic Area *(continued)*

**Office Building (H-2)** is known as Housing Unit #2 and contains 72,000 GFA. The master Plan calls for the existing building to receive a 48,000GFA **Office Building** addition. Currently the office space is slated for the State of Missouri, Department of Corrections for administrative functions. The addition would be a low rise structure that would contrast and complement the existing “bookend” Housing Unit #2. Other features associated with the renovation of this project include a second story pedestrian link to Housing Unit #3 (H-3) and development of the MSP Interpretative Garden (H-10) immediately adjacent to Housing Unit #2. The Interpretative Garden could be the beginning point of interpretative walks throughout the site, could explain past prison events (i.e. 1954 prison riots) and provide a transition green space between the redevelopment project and the adjoining neighborhood.


**The Centennial Cells (H-8)** are located beneath and covered by an asphalt hardstand between Housing Unit #2 and Housing Unit #3. After the surprise discovery of these cells in the early 1980s, they were “resealed” for preservation and future excavation. The interpretative potential for excavation and display of these historic cells is in the demonstration of both the incarceration story as well as the archeological dig process and findings.



## The Master Plan

### MSP Historic Area *(continued)*

**The Office Building (H-3)**, Housing Unit #3 contains 75,600 GFA and will contain 3 primary functions. First, the existing structure will house 15,600GFA of State office space. Approximately 30,000 GFA will be allocated to records storage, while the remaining 30,000 GFA will be preserved as cell blocks for interpretative purposes. The office space will connect to Office Building (H-2) via the second story sky walk and will support the interpretative museums’ administrative needs. The history of the building is rich in content, the 1954 riots started and ended in this housing unit and the interior stairwell and gun walk are historic features and should be preserved. The existing structure offers good delivery access and compatible use for record storage.




## The Master Plan

### MSP Historic Area *(continued)*

**The MSP Museum (H-4)** is the oldest building (1868) within the MSP site. Also known as Housing Unit # 4, the 43,000 GFA historic structure has been a continued favorite of committees, taskforce members and citizens who have participated in the redevelopment planning process. The preservation/ reuse of Housing Unit #4 will consist of a prison museum theme. The multiple level interior cellblock floors may offer the opportunity to interpret a “prison life” era on each floor level, starting with 1868 on the first floor up to decommissioning on the top floor level.

The outdoor space between H-3 and H-4 forms two sides of a pedestrian quadrangle that will conveying the spatial quality created by the buildings at the prison site, and experienced by so many inmates. A place where a prisoner could go to reflect or scheme, depending on his plan to do good or evil on society. A place where post prison visitors will feel the scale of the “yard”; imagine what it must have been like in the heat of summer or cold of winter and at the same time wonder how the architecture detailing was accomplished. The quadrangle will be formed through the reconstruction of the proposed Conference Center (H-6).



## The Master Plan


### MSP Historic Area *(continued)*

**The Conference Center (H-6)** will be located on the historic foundation of the former Dining Hall. Currently the historic foundation and basement are capped with a “contemporary” structure that is known as the Education Building. The existing structure is not compatible with the historic architecture surrounding the quadrangle and will be replaced (keeping the historic foundation and basement) with a new structure that will replete the character of the original Dining Hall. The proposed 4 story structure (including basement) will total 44,400 GFA and serve as the MSP Historic Area’s Conference Center. The basement of the conference center(11,100 GFA) will house the power plant for the MSP Historic Area. The first floor will contain the kitchen and food service facilities that will serve the day workers, tourists, conference attendees and the general public. The top two floors (22,200 GFA) will serve as the conference space. As a stand alone conference center the facility will service not only the MSP Historic Area but the surrounding master plan districts as well.

**The Wall (H-12)** contains contains a variety of construction dates, materials and existing conditions. The master plan incorporates a majority of the existing stone wall with minor modifications. From the renovated MSP Office Building (H-1) the wall will be extended and reattached to the existing wall when the existing administration building is removed. A “wagon gate” (H-11) will be added to allow direct public access to the MSP Historic Area and the guard towers will be reconstructed to their original “castle” motif. The wall will be rebuilt along East Capitol Street and visible piping, conduit or other non-appropriate appurtenances will be removed from the face of the wall. The wall will remain in place along East Capitol Street, an additional wall penetration (H-11) will be





Original Stone Dining Hall



# The Master Plan

## MSP Historic Area (continued)

added near Cherry Street, allowing direct access to the MSP Historic Area. The wall will continue along East Capitol Street to the Chestnut Street Parkway, there turning northward, visually screening the parking structure (P-2) on the other side of the wall. The wall will contain pedestrian and vehicular openings for access to the parking structure. At the northeast corner of the proposed parking structure (P-2), the stone wall will begin to quickly diminish in height down to a field stone remnant wall (H-14) with pedestrian access openings. The wall will continue in this fashion in



## The Master Plan

### MSP Historic Area (continued)

front of the Gas Chamber, continuing northward into a water feature pond, the wall height at one foot height above the water elevation.

At the northern edge of the pond the wall becomes a symbolic stone line in the lawn and paved areas.


The remnants of the stone wall terminate on the north side of the MSP Parkway in an architectural rendition of a guard tower. Several other guard towers along the riverside of the project area should be considered for retention, for visitor access, theme development and for display of the evolution of architectural tower styles.

**The Gas Chamber (H-9)** is located on the lower yard in its original location, providing an excellent stopping point on the historic walking tour of the site. As the site is opened to the public and visible from the Chestnut Street Parkway, the gas chamber is destined to become a local landmark.

### Summary

**The MSP Historic Area** will contain something for everyone. From office space to adaptive reuse of historic buildings; from visitors touring a one-of-a-kind museum to green space for the neighborhood. The district will be a dynamic mix of commerce, tourist attraction, education and cultural understanding that will ensure the long term success of the MSP Redevelopment Project.

The total MSP Historic Area will contain 310,048 GFA and will be served primarily by parking structure P-2 offering approximately 600 spaces.



## The Master Plan

### Public Service Campus

The Public Service Campus is located along East State Street from Jackson Street on the west to Lafayette Street on the east to the railroad tracks on the north. The extension of Lafayette Street to the MSP Parkway will define the distinct difference between this district and the adjoining architectural character and density of the MSP Historic Area. In addition, Lafayette Street will be pedestrian friendly with good access between The Public Service Campus and the MSP Historic Area. The Public Service Campus will serve as the front door to the MSP Redevelopment Project, making this district very important in establishing a worker/visitor environment that will convey quality, culture and capitalize on the proximity to adjoining features such as the Capitol Complex, downtown and the views to the Missouri River.

The **Justice/Office Center (J-1)** contains approximately 150,000 GFA within a four to five story building. The Justice/Office Center includes potential for holding space, offices and court rooms. This location will accommodate below structure parking, sally port, passenger drop-off and excellent



## The Master Plan

### Public Service Campus (continued)

vehicular access. The site location is in close proximity to the Capitol Complex with a commanding view of the Missouri River and supported by several other features contained in the Public Service Campus. A “time line walk” between the Justice/Office Center (J-1) and the MSP Museum (H-4) is approximately 200 feet and spans a time frame of 135 years. With this portion of the existing wall removed there will be open access and sightline connection between the Justice/Office Center and the MSP Museum.

The **Justice/Office Center Annex (J-4)** will provide 25,000 GFA support for the Justice/Office Center including administrative offices and records storage. This location also offers an excellent opportunity for related community activities such as a branch library, community meeting space or specialized museum with focus on the interrelationship between the judicial system and MSP as a prison.

The **Public Service Office Building (J-2)** will contain approximately 50,000 GFA. The proposed facility is located at the intersection of East State Street and the entrance to the MSP Parkway, clearly making this a highly visible site



## The Master Plan

### Public Service Campus *(continued)*

with good vehicular access and pedestrian access to the surrounding neighborhood and other MSP features. Potential uses for the Public Service Office Building include private office space, best suited to support legal/judicial activities of the district. A support retail/commercial function within this facility would serve off-hour needs of the district while providing little competition to other retail/commercial business. The street front nature of this facility can also serve niche markets such as gallery space for art collections and sales; education/ science center novelty; natural resource display, sales or tours.

**The Pedestrian Plaza** is located at the intersection of East Capitol and Lafayette Street adjacent to and above the structured parking (P-1) that serves parking needs for this district. The Pedestrian Plaza will provide a multitude of activities for the Public Service Campus as well as the total redevelopment project. The plaza will first set the standard to provide quality outdoor space for the day-to-day work force, visitors, tourist and to the ongoing revitalization of the surrounding neighborhood. The plaza will accommodate public gatherings such as commemoration, sun lunching and neighborhood/cultural/ patriotic celebrations. The plaza can also serve as a tourist staging area where buses could drop visitors, instructions delivered, tours disperse to points of interest and likewise to gather visitors at the end of the day.




## The Master Plan

### Public Service Campus (continued)

The **Structured Parking (P-1)** is intended to be low profile to facilitate the transition between the Public Service Campus and the surrounding land uses. It is expected that the plaza, streetscape treatment and plantings will also help to blend the structured parking into the neighborhood. The structure of the parking area will provide the cap for the pedestrian plaza increasing the efficiency of the available land in proximity to the other planned features.

### Summary

The **Public Service Campus** will provide 225,000 GFA and 485 structured parking spaces in a full-service business and judicial setting with outstanding site attributes and in close proximity to where the decisions are made.




## The Master Plan

### Public Assembly Campus

The Public Assembly Campus is centrally located within the built environment of the MSP Redevelopment Project, transitioning between inside and outside “the wall” character of the site. Opportunities will exist to incorporate historic structures such as Housing Unit #5 (H-5) together with contemporary design solutions, contrasting and complementing one another. The district will provide the lodging, entertainment and assembly opportunities for the project area, community and region.

Significant site features will be incorporated into the design solutions within the district. The elevation transition from the upper yard to the lower yard will provide opportunities for architectural features to link the elevation differences via multi-story structures. Incorporating remnants of the original (pre-1885) prison wall separating the upper and lower yards, will provide potential design lines, linkages and interpretative opportunities as the design of various features are accomplished. The existing wall along Chestnut will fall in height from East Capitol to a remnant (H-14) wall through a water feature then crossing the MSP Parkway as a symbolic line in the pavement. This district will provide visual and pedestrian access to the Missouri River by way of the pedestrian plaza (E-2) and the elevated link to the rivers’ edge (E-3).

The Public Assembly Campus will be oriented to serving regional guests that come to visit and work in the central location that Jefferson City offers. This same uniqueness will provide “close in” lodging, conferencing, gathering and entertainment venues to the workforce and citizens of Cole County, all within a campus setting, steeped in historic values and one of a kind features.



## The Master Plan


### Public Assembly Campus (continued)

**Hotel 1 (H-5)** is located in Housing Unit #5 and contains 102,500 GFA. It is estimated that approximately 250 hotel rooms could be accommodated within the existing structure. On the south side of Hotel 1, the master plan includes a proposed expansion of the existing structure to include meeting rooms, guest services and recreation services associated with the proposed hotel. The addition would be a low rise, low profile structure suitably compatible with the historic character of Housing Unit #5. The 50,000 GFA addition would also contain 100 structured parking spaces located below the addition.

**Hotel 2 (E-1)** is located immediately north of Hotel 1, across the MSP Parkway. Hotel 2 contains 144,000 GFA and is connected to Hotel 1 by a second story pedestrian skywalk. Hotel 2 was programmed to provide 275 hotel rooms in a multiple-story structure. The character of Hotel 2 may eventually contain some architectural elements/structure of the existing Shoe Factory that occupies the Hotel 2 site today. Hotel 2 will contain direct access off of the MSP Parkway and will provide a guest drop-off and motor court at the front door. The site of the hotel will provide great views to the river and back to the Capitol Complex to the west.

The third hotel site in the Public Assembly Campus is located immediately east of Hotel 2. **Hotel 3 (E-5)**, will be a medium rise, 100,000 GFA hotel with 275 rooms. The hotel will share structured parking located below each hotel.

Hotel 3 and Hotel 2 also share a common **Pedestrian Plaza (E-2)** that offers outdoor space for gatherings, social events and provides pedestrian access to the riverfront and the **Excursion Boat Landing (E-4)**. The Excursion Boat Landing, is envisioned as a mooring barge with pedestrian access via




## The Master Plan

### Public Assembly Campus (continued)

elevated walkway (E-3), ramped gangplank and floating dock for excursion boats to board and unload passengers in a safe and convenient location. There is also a small transient marina located at the landing for boaters to land in the proximity of the redevelopment project. The Excursion Boat Landing site will also be served by ground access with an at-grade crossing of the railroad tracks from the redevelopment. The at-grade crossing will not be a public crossing.

**Public Assembly Facility (E-8)** is the feature attraction of the Public Assembly Campus, which could emerge as the commerce and cultural center of Mid-Missouri. The convention center setting contains 125,000 GFA on two floors, connecting the upper and lower yards. The facility will contain a 25,000 GFA Auditorium for performing arts. There will be two 35,000 GFA Exhibition Centers, providing a





## The Master Plan

### Public Assembly Campus (continued)

maximum of 70,000 GFA for a single convention event. The Public Assembly Facility will also contain 25,000 GFA allocated to Multi-Purpose Space for community events or convention activities. Support services within the facility account of 5,000 GFA.

The Public Assembly Facility is located literally and figuratively in the center of the project's redevelopment opportunities. The facility has direct access off the MSP Parkway to a large motor court/pedestrian drop/urban plaza that defines the front door to the facility. The entry plaza on the upper level will collect the walking visitors from the hotel complex and provides an outdoor staging area for queuing facility access. The pedestrian plaza will contain seating areas, artwork display areas, civic displays and water features. The change in elevation may provide an opportunity to develop a cascading waterfall along the north and east side of the facility. The water feature would calm at the lower



# The Master Plan

## Public Assembly Campus (continued)

pool providing visual relief between the round-a-bout and the facility. As the central feature of this district, the Public Assembly Facility will set the standard for civic development on this highly visible site.

**The Landing (E-7)** is located on the north side of the MSP Parkway immediately east of the Hotel 3 (E-5) complex. The area will contain 60,000 GFA in a series of small buildings clustered around the Water Feature and Pedestrian Plaza (E-6). The area will be served by the P-4 surface parking area and will be interconnected with the walkway system that extends to the other districts within the project. Potential uses within The Landing include support Retail Shops for tourist, Winery, Restaurants and Brewery. The landing will serve the working population within the redevelopment project, will serve as a gathering/resting space for visitors and will serve the public as a potential evening entertainment district.

Immediately adjacent to The Landing are two site features that support the district’s activities. The **Potato House (H-16)** and the **Slaughter House Smoke Stake (H-15)**. The Potato House is a unique, earth-covered structure containing 24,000 GFA. As a former farm food product storage facility, the Potato House will attract visitors and should be considered as a farmers market, greenhouse, café/food/drink service and trail head. The Smoke Stack site will become a resting spot along the trail system, offering the potential as an




## The Master Plan

### Public Assembly Campus (continued)

interpretative site and will become a visual icon for the district.

### Summary

The **Public Assembly Campus** will provide 605,500 GFA catering to the commerce, cultural and entertainment needs of the region. The district will provide numerous opportunities for rest, comfort and entertainment to the working population as well as the visitors to the project. There will be 1,300 parking spaces to support the multitude of events and activities that will be possible in the district.





# The Master Plan

## Office Campus

The Office Campus is located east of The Chestnut Street Parkway to the eastern slope of Minor’s Hill, site of the DNR Green Building. The Office Campus is easily accessible from the proposed Chestnut Street Parkway, The MSP Parkway and The Office Campus Loop Road. The district is served by parking areas P-6 and P-7 providing 1,450 structured spaces. The Office Campus is expected to be a combination of State Government Office space and Private sector office space.

The State of Missouri, following Governor Holden’s executive order promoting “smart growth”, has already began the redevelopment process within the Office Campus. **Office Building (O-1)** is the DNR Green Building that is approximately 120,000 GFA and is located atop Minor’s Hill, overlooking the Missouri River. The Green Building has set a high standard for distinctive architecture, that standard will be expected with other office building developments. The second **State Office Building (O-11)** to be relocated to

the MSP Redevelopment Project is the State Health Lab. This facility will be located East of The Chestnut Street Parkway, one block north of East Capitol Street. The State Health Lab is approximately 80,000 GFA and is at the upper




# The Master Plan

## Office Campus (continued)

end of the water feature ponds that flow through the project area.

The remaining 550,000 GFA of state **Office Building** and 250,000 GFA of private **Office Building (O-2 thru O-7)**, is programmed to be located in the center of the Office Campus within the Office Campus Loop Road and the MSP Parkway. While the building footprints appear to be finalized, the master plan represents the space requirements and not the building configurations. In the Master Plan Scenario, the office buildings have been divided into five separate buildings with multiple building heights. The primary concepts contained in the master plan that should be followed are:

- Multiple smaller buildings rather than one large building the size of the Truman Building
- Consider high density development with open space conserved and pedestrian plazas established throughout the building clusters
- Provide a central Motor Court (O-9) to accommodate mass transit and reduce driving and parking needs
- The building complex should have pedestrian links to all adjacent areas



## The Master Plan

### Office Campus (continued)

- There should be a consistent theme of architectural design and consistent use of building materials throughout the office complex
- Site amenities such as streetscape improvements, signage, entry features, water features, ponds, seasonal plantings must be a part of each building program, coordinated with other improvements
- Low profile structured parking should be utilized in lieu of surface parking to conserve open space and sprawl

If the Redevelopment Project is to succeed there must be high architectural and site development standards established to create the kind of aesthetic environment demanded by employers to attract the best employees, customers and visitors.



# The Master Plan

## Office Campus (continued)


### Summary

The Office Campus plan provides 1,000,000 GFA in a setting that is easily accessible, within walking distance of food, lodging, conference, cultural and entertainment venues. With continued leadership and support from State Government and the Commission’s commitment to provide quality facility development, the MSP Redevelopment Project offers a potential work environment second to none.

The Office Campus is served by parking area P-5 containing 850 spaces and P-7 containing 600 structured parking spaces.



**The Master Plan**



Proposed Master Plan Looking West

## The Master Plan

### Natural Resource Area

From the beginning of the planning process that began in 1999, the majority of participants generally concurred that the eastern half of the MSP Property should be preserved in its current condition and used as a natural area. The master plan reflects that general principle as important to the long term success of the redevelopment project. Preservation of this open space will support “smart growth” through:

- The provision of green space in close proximity to a large working population
- The preservation of urban wildlife habitat
- Creating denser development on appropriate sites and avoiding sprawl onto sites with unique natural resources
- The preservation of views and vistas
- Retaining unique landscapes for all to enjoy

The **Natural Resources Area** is located immediately east of the Office Campus and consists of approximately 50 acres of typical Missouri oak-hickory forest with man cleared and shaped ridge tops (former prison farmland), steep wooded side slopes, steep narrow drainage ravines with shallow rock and highly erodible soils.



## The Master Plan

### Natural Resource Area *(continued)*

The **Wooded Areas (N-1)**, will provide enormous benefits to the workers and visitors to the MSP site as well as the wildlife that currently inhabit the area. Passive recreation in the form of walking/hiking, bird watching, sightseeing, picnicking will all be enhanced through preservation and resource management of the existing wooded areas of the site.

The **Open Prairie (N-2)** grasslands of the Natural Resources Area are the most vulnerable to development pressure. These open spaces are highly desirable development sites that are, and will be under constant pressure to “be developed”. These sites possess outstanding spatial attributes and afford some of the most spectacular views of the Missouri River Valley in the region. The open prairie should be preserved and used for the benefit of the total citizenry and wildlife habitat. The prairie /open space offer opportunities for open field research, natural science education and resource management demonstration.

**Recreation Trails (N-3)** have been incorporated into the plan to provide walkers, hikers and bikers (on selected trails) a variety of natural experiences and access to the natural features of the site without excessive impact to the resource. The walks will be



## The Master Plan

### Natural Resource Area *(continued)*

made of natural materials, suitable for handicapped accessibility and bicycle access on selected routes. The sharing of trails with equestrian use is generally deemed acceptable, while the use of motorized vehicles (such as ATV's) anywhere on site should not be allowed.

Throughout the site along the trail system there are several **Recreation Pavilions (N-4)** that will provide walkers/hikers shelter during inclement weather, rest stops, shade and picnicking opportunities.

The **Grounds Maintenance (N-5)** complex is located on the east side and adjacent to the bottom floor of the Office Campus parking area (P-7) that borders the Natural Resources Area. The Grounds Maintenance area will serve the Capitol Complex maintenance operations that occur on the MSP site currently. This location has good access, is out of public view and compatible with the surrounding land use. The P-7 structure can provide



## The Master Plan

### Natural Resource Area *(continued)*

secured storage and office space required by the grounds maintenance operations.

A majority of the visitors to the Natural Resources Area will originate from other districts within the project area such as the Office Campus, and thus the other districts will be connected via trails and walks to the Natural Resources Area. A small parking lot (P-6) will provide 15 surface parking spaces located off Riverside Drive.

### Summary

**The Natural Resources Area** will contribute to the success of the MSP Redevelopment Project by preserving open space, protecting our natural resources and improving the quality of life for the citizens of Missouri. Workers will have a place to go at lunch, visitors can view the river corridor from the bluff tops and school kids can learn about Missouri’s flora and fauna. The Natural Resource Area must be buffered from development pressures and protected for the greater good of current and future generations.



# The Master Plan



## The Master Plan

### The Next Steps

The planning, design and development process for the MSP Redevelopment Project started in July of 1999 with the formulation of a high level Task Force assigned to think through and begin the redevelopment process. Since that time hundreds of citizen, agency and consultant man-hours have been focused on achieving various redevelopment tasks. Major accomplishments thus far, include:

- Task Force & Oversight Committee appointed
- Public input received and public awareness increased
- Completion of The Process Definition Plan and approval of the Consensus Plan
- The new JCCC is under construction (off-site) and on schedule for 2005 opening
- Planning, design and construction of the DNR Green Building (first new building of the redevelopment)
- The MSP Commission is authorized, appointed and functioning
- The Executive Advisory Committee has been appointed by the MSP Commission
- Public input received on the Framework Plan
- Planning and design underway for the new State Health Laboratory
- The Framework Plan completed



## The Master Plan

### The Next Steps *(continued)*

- The Master Plan receives a planning & design award from the St. Louis Chapter of ASLA
- Utility companies contacted and developing long range planning strategies
- On-going environmental, archeological, site feasibility studies for potential development sites
- Preparation of the redevelopment Design Guidelines started
- Infrastructure planning and design started
- Decommissioning planning started

The detailed list of accomplishments is much longer than the summary list above. The development process has passed the test of changing administrations at the local, county and state level. Past, current and future political and community leaders continue to participate in the planning and redevelopment process.

### Future Activities

Following is a list of activities that will be accomplished in the short term future in order for the redevelopment process to move forward. The items have not been prioritized, defined or scheduled.

- **Phase I Archeological Investigations**
  - DNR Site
  - Lab Site

- Remaining Site
- **Phase II Archeological Investigations**
  - Remaining Site
- **Phase II Environmental Investigation**
  - Remaining Site
- **Existing Facility Protection/Disposition**
  - Demolition Phasing Plan (timeline / strategies)
  - Site & Building Demolition Plan
  - Demolition Material Recycle
  - Wall Stabilization
- **New & Existing Infrastructure**
  - New & Existing Infrastructure Implementation Plan
  - Historic District Heating/Cooling



## The Master Plan

### The Next Steps *(continued)*

- **Site Improvements**
  - On-site Road Plan
  - Parking Plan
  - Grading Plan
  - Landscape Plan
- **Natural Resource Analysis**
  - Flora & Fauna
  - Threatened & Endangered
- **Historic Designations**
  - Section 106 - Districts, Buildings & The Wall
- **Surplus Property Relocation**
  - Relocation Program
  - Site Selection
- **Implementation Strategies & Planning**
  - Site & Architectural Design Guidelines
  - Delivery Systems Guidelines - Design / Build - Lease Purchase - Conventional
  - Phasing Plan / Facility Interim Use / Public Access / Decision Timeline
- **Financial Guidelines & Planning**
  - Project Feasibility
  - Development Fees
  - Development Incentives
  - Funding
  - Revenue Generation

These activities will be coordinated with other planning and design events scheduled to take place in the project area. The City, Housing Authority, Cole County, State and Federal government agencies all have ongoing projects in or immediately adjacent to the MSP Redevelopment Project. Efforts will continue to be made to share information, vision and resources to best serve the citizens of Missouri.





# Master Plan Amendments

M S P

## Master Plan Amendments

### Introduction

As predicted in the previous chapter “The Master Plan will change over time as development opportunities arise”, several key changes to the Master Plan have occurred during finalization of the plan. These plan modifications reflect changed conditions or program clarifications and generally improve or enhance the quality of the design principles contained within the Master Plan.

### The Lafayette Street Entrance

The Original Master Plan located the western entrance of the redevelopment project at the intersection of East State Street and Marshal Street. From there the proposed MSP Parkway would traverse the site from west to east. After further consideration the west entrance to the MSP Redevelopment Project was realigned along Lafayette Street and the Marshal Street connection was abandoned. The reasons for this change include:



## Master Plan Amendments

- Lafayette Street appears to be a more desirable traffic connection to the west, south and east via the existing City street pattern.
- Sight distances and terrain are better at Lafayette Street than at Marshal Street.
- The Public Service Campus is no longer divided into two small parcels, but one larger tract making it more desirable for redevelopment.
- Lafayette Street was the original front door to the site.

### The Health Lab Site Development

The Master Plan has been updated to illustrate the final design footprint of the new State Health Lab located northeast and east of the intersection of Chestnut Street and East Capitol Street. The related changes include:

- Modified building footprint.
- Vehicular Circulation pattern modified to reflect functional aspects of the new building.
- The vehicular entrance to the P-2 structured parking has been moved south.
- A service drive has been added to the north side of the new building.



Original Plan





## Master Plan Amendments

### The Waterfront Modifications

The riverfront connection as shown on the Master Plan has been slightly refined to accomplish the following:

- The pedestrian skyway over the railroad tracks has been shortened.
- The revised plan holds the riverboat landing structure closed to the shoreline.
- The plan is intended to provide pedestrian access to Adrian's Island.





# Market Analysis



**M S P**

## Market Analysis

### Methodology and Rationale

The basis for planning any changes in land use must include an analysis of the ability of the market to need and absorb that land. This creates an understanding for a realistic plan and opportunities for financing the plan's implementation.

The U.S. economy is primarily market-based. This economy relies on the creativity, risk-taking, and energy of the private market to create value in the economy. Almost always, of course, there is public involvement through incentives and/or regulation in order to attract and manipulate market forces for the benefit of the larger community.

The Missouri State Prison site does not exist in a vacuum. It is part of the regional, state, and national economies and should take advantage of opportunities within that context. Thus, the economic and market research focused on trends on which the MSP site can capitalize. As it turns out, one of the most powerful of these trends is the growth in state government. Because Jefferson City is the state capital and because it is a relatively small city, state government exerts an unusually high amount of "market" influence. To this degree, state government is the underlying "basic industry" in the Jefferson City area.

The methodology for the market analysis of the MSP site included the following major steps:

1. Projections of market absorption and timing
2. Analysis of regional, state, and national economic contexts
3. Interviews of public and private officials
4. Correlations of past growth with data indicators
5. Projections of growth based on indicators
6. Conversion of trends to building and land area needs

## Market Analysis

### Comparative Population Trends


The focus of our regional economic context is a four-county area of Mid-Missouri. This includes Cole, Moniteau, Osage, and Callaway Counties. Together, these had a combined 2000 population of just over 140,000.

If Mid-Missouri was a formal metropolitan statistical area, it would rank about 210 out of America’s almost 300 metro areas. Boone County, where Columbia is located, is its own metro area with 135,000 people, which is obviously also part of the regional economy of Jefferson City.

The Mid-Missouri counties, therefore, rank on a par with formally designated metropolitan areas like Lima, Ohio (155,000) and State College, Pennsylvania (136,000), not to mention Columbia, Missouri. By comparison, other Missouri metro areas rank as follows:

- St. Louis is the 18<sup>th</sup> largest metro area with over 2.6 million people.
- Kansas City is the 26<sup>th</sup> largest with 1.8 million.
- Springfield is the nation’s 124<sup>th</sup> largest metro area with 326,000 residents.
- Joplin is 196<sup>th</sup> with 157,000.
- Columbia is 221<sup>st</sup> with 135,000.

Jefferson City is one of only eight state capitals that is not part of a formally designated metro area.



## Market Analysis


### Mid-Missouri County Populations

Cole County is certainly the largest of the four Mid-Missouri Counties with about 71,500 residents as of the 2000 census. Since 1940, it is the only one of the four counties to have grown significantly.

Callaway County is the second largest at 41,000 residents. Its growth rate during the 1990s, however, was about twice as fast as Cole County. Each county added roughly 8,000 residents but, because Callaway was smaller to begin with, its growth rate was just over 24 percent compared to about 12 percent in Cole County.

Independent projections of population for Missouri counties prepared after the 1990 Census by the Missouri Office of Administration suggest that the population of the Mid-Missouri counties would have a combined total of about 160,000 by 2020. This includes an adjustment by Development Strategies to the projections to adjust for actual counts in 2000. Independent projections have not yet been completed to reflect Census 2000.

This 20,000 increase in population between 2000 and 2020 is about a 14 percent growth rate. This would be slightly faster than the Census Bureau’s 11 percent growth rate projection for the entire state of Missouri but slower than the U.S. national projection of about 18 percent (middle series).




## Market Analysis

### Mid-Missouri Components of Growth

Population growth results from two major forces: More births than deaths and more in-migration than out-migration. The four Mid-Missouri counties have done well in both respects.

- The red bars show the net difference between births and deaths—positive for all decades since 1950.
- The yellow bars show net migration, which has been positive in all decades except the 1960s.

Remarkably, the net in-migration to the four counties during the 1990s was about 2.5 times the net natural increase, resulting in almost 14,000 more residents in 2000 than in 1990 because of new residents attracted from elsewhere. These new in-migrants made up 71 percent of all net new population growth.




Overall, the region has had a 49 percent rate of growth in the last 30 years, much higher than the rate of growth for the St. Louis metro area, for example, at 5.7 percent for 30 years. Net in-migration in metro St. Louis, by the way, was negative in the 1990s. Thus, the net gains in Mid-Missouri suggest an ability of the four counties to attract new residents with quality of life characteristics and decent jobs. This ability to attract residents will be important in forging a larger and more diverse economy in the coming years.

## Market Analysis

### Mid-Missouri Jobs and Households

In the last three decades, however, jobs and housing development grew faster than population. To accommodate the 49 percent increase in population in the four Mid-Missouri counties, there are now 82 percent more housing units (actually, growth in households which are occupied housing units). And many of these people wanted or came for jobs. Employment in the four counties increased by 59 percent between 1970 and 2000.

Corresponding growth rates in metro St. Louis, for comparative purposes as the largest metro area in the state, were 5.7 percent for population 23 percent for housing, and 33 percent for jobs. While these growth rates represent larger absolute numbers, it is clear that Mid-Missouri has been growing relatively rapidly, most notably through its ability to attract in-migrants to take a rapidly expanding number of jobs.




## Market Analysis

### Commuting to Jobs Mid-Missouri, 1999

Cole County is the center of jobs in Mid-Missouri, as long as Boone County is ignored. Of the four Mid-Missouri counties, only Cole attracts a *net* number of commuters each day while the others all have net decreases.

This is based on comparing the number of jobs in a county with the number of residents who hold jobs—no matter where those jobs are. Cole County has almost 23,000 more jobs within its borders than residents who have jobs. Thus, there is a whole lot of in-commuting in the morning, and out-commuting at night.

Note, however, that the “negatives” of Callaway, Moniteau, and Osage Counties do not equal the “positive” of Cole County. This indicates that Cole is attracting commuters from a wider range of counties, not just the other three. In fact, the Greater Jefferson City Chamber of Commerce defines its economic region over ten counties, which would probably better reflect the “commuting shed” for Jefferson City.



## Market Analysis


### Mid-Missouri Unemployment Rates

The good news is that the unemployment rate in Mid-Missouri is and has been consistently below the national rate all through the 1990s until today. The bad news is that the unemployment rate has been so far below the national rate.

Analysis of these curves suggests that there is a relatively small labor pool in the Jefferson City labor market area (LMA) that can be immediately called upon to fill new job creations. The LMA consists of the four counties of Mid-Missouri. It also suggests that there may be a relatively high number of jobs not being adequately filled with the right kinds of workers.

This latter factor tends to attract workers from outside the region to take such jobs. Indeed, as was shown with the net migration graph, this area has been attracting population and labor force at a fairly strong rate.

The recent convergence of the unemployment rate lines in this graph suggests that this pressure to attract in-migrants may be softening a little bit, but the trends are far too short to make any such firm conclusion.



## Market Analysis


### Changes in Mid-Missouri Employment by Sector, 1970 - 2000

The “business” of Mid-Missouri is not so much business as it is government. Almost three out of ten jobs in the region are in government. Of course, this isn’t surprising since this is the seat of state government in the 17th most populous state in the nation (almost 5.6 million residents).

The federal government’s computer model that determines multipliers for economic sectors shows that state government in the four counties of Mid-Missouri has a multiplier of 1.68, meaning that, for every dollar spent to support state government in Mid-Missouri, another 68 cents are generated in “gross domestic product” in the four counties. And one state government job in Mid-Missouri creates another 1.1 jobs in the four counties.

These multipliers emphasize how important state government is because it attracts so many dollars from elsewhere in the state to be spent locally. Projecting a potential development program for the MSP site, therefore, should start with analysis of growth in government employment.

Since 1970, however, the proportion of government workers has dropped slightly from 30.7 percent of all jobs to 28.4 percent. While the four counties never constituted a large manufacturing center (12.9 percent of all jobs in 1970), they have experienced much the same rate of decrease in manufacturing employment as the rest of the nation, coupled with a shift to more jobs in the services sector.




## Market Analysis

### State Government Employment Projections in Cole County

Growth in state government employment implies the need for growth in places to work. This graph illustrates two scenarios for projecting state employment in Cole County.

- The blue line is based on the long-term relationship between state government jobs in the state and the population of the state. As the population grows, so does the need for government workers to continue to serve that population.
- The red line assumes there is a relationship between state government jobs and all other jobs. That is, there is long-term ratio of state jobs to the entire economy of the Missouri.



The graph depicts these effects on state government jobs located within Cole County alone. The second scenario would suggest that present state jobs in Cole County are well below the long-term relationship between state government and other jobs. Thus, there would have to be a lot of catching up to do by 2005 to get on the “trend line.” But further growth in state jobs on this line would be slower than the other scenario.

In 2000, there were about 17,350 state government jobs in Cole County. The blue line scenario would increase this to 18,600 by 2005 while the red line scenario would increase it to 20,500 by 2005. These projections would “cross” in about 2015 so that, by 2025, Cole County would need to be home to some 24,300 state employees based on the per capita scenario or 22,400 state employees based on the per all jobs scenario. Thus, between 5,000 and 6,900 additional state jobs would be located in Cole County in 25 years.

## Market Analysis


### State Government Office Space Needs in Cole County

On an assumption that 75 percent of the jobs projected on the previous graph would be located in office space in Cole County (the other 25 percent would not require office space, per se), an additional 755,000 to 1,040,000 square feet of office space would need to be in place in Cole County by 2025 to accommodate this growth.

But this presumes only *net new growth* in office needs. There would also likely have to be other office space construction in the time frame to account for *replacement space* that would become (or already is) obsolete by 2025.

By way of comparison, the Truman State Office Building in downtown Jefferson City has approximately 800,000 square feet of floor area. Thus, the projections suggest that, on a net new basis, the equivalent of another Truman Building would be necessary by 2025.

This is not to suggest that such a single, large building be constructed in Jefferson City in the near future. But it suggests that the scale of future development may be about the same.




## Market Analysis

### State Government Office Space Projections in Cole County

Based on estimates of existing state government office (and related) space in Cole County, the projections shown on the previous graph would yield the red line (lower line) on this graph. In essence, there would be a total need for about 3.3 million square feet of state government office space in the year 2025 in Cole County.

In 1995, a study was completed for the State of Missouri on the office space needs of state government. *(That study was headed by Sverdrup Facilities, Inc. and included Development Strategies and Stifel, Nicolaus as subcontractors.)* To that time, state office space in Cole County had averaged about 2.1% annual growth over a long period of time. Projecting that same rate into the future, however, yields the blue line (top line) of this graph, showing a potential need for over four million square feet.



Both lines are the same from 1994 through 2002, using available information on actual state office space occupancy.


Thus, the employment projections model, used for this study, is more “conservative” than the historic growth rates. That is, the space projections shown earlier would yield less net new office space than if trend line projections were used. In many ways, it is best to be that conservative because the statistical relationship between state government employment and other indicators is not likely to be as “direct” as assumed here. And there are likely to be economies of scale in state government as its importance grows, such that past trends will be dampened by greater attention to costs and greater use of office technology leading to a need for relatively less space per employee.

## Market Analysis

### Private and Other Government Office Space Projections

Applying similar projection techniques to the rest of the Cole County economy, and applying different ratios of office space within each major economic sector, the non-state component of employment growth in the County would require more than 600,000 net additional square feet of office space by 2025.

Thus, Cole County may have to construct between about 1.4 million and 1.7 million *net additional square feet* of office space in the next 25 years. Plus there will be need for replacement space from outdated facilities. Planning for the location of such space is of critical importance to Jefferson City and Cole County authorities. The MSP site may offer an exceptional solution to these market-based pressures.



## Market Analysis

### Public Assembly Facility: Reasons for Potential Success

The other major land use that emerges as a market-based opportunity for the MSP site is for a public assembly facility. Long debated in the Jefferson City area, there has yet been no resolution of the issue as to whether and where it might be built.

There are many reasons why Jefferson City should have a large meeting facility. Tops among them is that it is the state capital and should be a center for meetings that involve state-wide issues. With economic growth come more reasons to meet. As the state economy grows, so do business meetings.

Moreover, the entire nation continues to see growth and change in the number of organizations that are created and hold regular meetings. Americans, in fact, are noted worldwide for their willingness and ability to organize into interest groups. As a free and democratic society, this will not change. We constantly find commonality with one another and we organize to fulfill many missions that, ideally, improve the human condition. With more groups, combined with more leisure time, more income, and longer life spans, will come the need for more and better places to meet. There is little reason why the capital of the 17<sup>th</sup> largest state should not be a major meeting place for Missouri-based organizations.

Increasingly, Jefferson City is easier to reach. Four-lane highways and Amtrak serve it well. While Jefferson City is one of only two state capitals not directly on an Interstate highway, Route 54 and, to a lesser degree, Highway 50 help to circumvent this shortfall. Better road access, however, would improve the ability of the city to market itself for statewide meetings.

Meanwhile, there are two key indicators that local demand is in need of more facilities:

(1) The Greater Jefferson City Convention & Visitors Commission says the city is turning away business because of a lack of facilities;

<p><b>Reasons for Potential Success</b> <b>PUBLIC ASSEMBLY FACILITY</b></p> <ul style="list-style-type: none"><li>• Center of state government</li><li>• Statewide and Mid-America growth in organizations needing to meet:<ul style="list-style-type: none"><li>○ Religious</li><li>○ Social</li><li>○ Hobbies</li><li>○ Professional</li><li>○ Athletic</li><li>○ Political</li></ul></li><li>• Central location, ease of access</li><li>• State economic growth: More reasons to meet.</li><li>• Sufficient and convenient hotel rooms are a necessity.</li></ul>
--

## Market Analysis

(2) The Truman Building is perennially booked and is increasingly more “in-scheduled” for government business with less room for “out-scheduling” to serve other organizations.

But one factor will be critical in meeting the challenges of meetings: overnight accommodations. A successful convention and conference facility must have sufficient numbers of lodging rooms. If Jefferson City is a great place to meet and there will be more meetings, there will need to be more hotel rooms.

### Public Assembly Facility: Anticipated Scale of Development

To date, a few proposals have been put forth for a Jefferson City convention center, none of which has been able to get underway. Moreover, a number of other small cities in a variety of economic contexts have constructed various kinds of convention, conference, and arena facilities. Conclusions from this analysis discount indoor sporting events as a major opportunity for Jefferson City in light of the facilities in Columbia, Springfield, Kansas City, and St. Louis. Also discounted are major concerts from being significant attractions because of the facilities in the aforementioned cities.

But meeting space is necessary. A consensus arises from an evaluation of other facilities and the size of the Jefferson City “market” that a facility could be created that has up to 60,000 square feet, plus parking, as outlined on the adjacent table. The exhibit hall/ballroom should be at least 30,000 square feet in scale, subdividable for smaller groups and/or multiple groups. And there should be break-out meeting spaces, perhaps with a formal lecture hall/small theater. A larger facility is also possible if a performing arts venue is created. But this should be done only after fuller testing of the market potential for attracting theatrical and small concert programs, possibly in conjunction with the Greater Lake of the Ozarks market and the Columbia/Boone County market.

#### Recommended Physical Components PUBLIC ASSEMBLY FACILITY

- Single, open floor space to accommodate up to 2,500 participants (approx. 30,000 square feet)
  - Exhibits
  - Ballroom
  - Large group meetings
- Separate, divisible meeting areas:
  - 10 to 15 rooms
  - Combinable
- Possible performing arts venue
- Full service kitchen
- Large and well-appointed lobby and pre-event area
- Appropriate number of parking spaces.

## Market Analysis

### Market Analysis: Summary Conclusions

1. The Jefferson City area needs more sites for office development.
  - a. State government alone could add over 750,000 square feet by 2025.
  - b. The private market adds perhaps another 600,000 square feet.
  - c. Plus land for campus settings, parking, road system.
2. Public Assembly Facility appears to be a crucial need for accommodating demand and diversifying the local economy.
  - a. There is a pressing need to resolve location issues.
  - b. There is absolutely a need support good quality and walkable hotel rooms.
3. MSP site offers solutions to these opportunities.
  - a. Little else will be ready and available in time.
  - b. Fulfills Governor's order to concentrate state facilities in existing cities (Smart Growth philosophy)



# Architecture


**M S P**

# Architecture

## Introduction

The Project Team has conducted a redevelopment/reuse overview evaluation of the existing project structures which were identified in the Process Definition Plan (the Consensus Plan) for further consideration and inclusion in the Framework Plan. The structures evaluated included:

- Housing Unit 1
- Housing Unit 2
- Housing Unit 3
- Housing Unit 4
- Housing Unit 5
- Shoe Factory
- Furniture Factory
- Metal Working Plant
- Centennial Cells
- Gas Chamber
- Potato House
- Education Building & Maintenance Building
- Stone Walls



# Architecture

## Process

The Project Team reviewed existing drawings and established background floor plans; conducted building and site walk-throughs; conducted visual inspection and findings; developed existing building diagrams, studied volume/space opportunities and identified potential uses.

A generalized program statement for the reuse of the existing buildings was prepared along with functional diagram concepts for the reuse of the existing buildings. These recommendations are illustrated on the following pages and integrated into the site, urban design and community context plan solutions.

## Buildings Re-Use

During the planning process three building re-use concepts emerged as viable solutions within the framework plan. Examples of the re-use scenarios include:

- Preserve & Restore (HU 4)
- Combination Restore and Adaptive Re-Use (HU 1)
- Adaptive Re-Use (HU 2)

## Summary

The build evaluations and recommendations were generally formulated based on the following basic principles: first, preserving the context of the site from a “public” view and a “user” view; preserving the “essence of the prison”; structural considerations of the existing buildings; architectural/historic value; Consensus Plan perspective; and surrounding land use recommendations contained in the Framework Plan.



# Architecture

## Housing Unit #1 – Existing Information

### General Information

Date of Construction: **1905** (Earlier building once existed behind it that dated to pre-1885)

Existing No. of Floors: **5** Existing No. of Full Floors: **1** Existing No. of Offset Floors: **3**


Existing Area per Full Floor Plates: **7,000 gross sq. ft.**

Existing Total Floor Area: **26,300 gross sq. ft.**

Existing Prison Cell Floor to Floor Height: **7’-4”**

### Historic Information

1. WPA construction has covered the exterior of this building on almost every elevation.
2. Rear (east) elevation compromised by the removal of a pre-1885 structure during the WPA remodeling. The earlier building acted as a gated entrance into the prison.
3. Emma Goldman lived here; famous anarchist and communist, she argued for prison reform.
4. “Red Kate” O’Hare lived here; American socialist and federal prisoner, the U.S. had no female prisons at the time.
5. A bust of Governor Alexander Dockery, a clock and a state seal carved out of stone exist on the main (west) elevation above the entrance.



# Architecture

## Housing Unit #1 – Existing Information



### Preservation Zones

- Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority
- Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone
- Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
- Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



West Elevation



View from Northeast

## Architecture

### Housing Unit #1 – Possible Use

#### Redevelopment Issues


1. How should the east elevation be restored once the WPA corridor is removed? The brick infill where H.U. #1 attached to the pre-1885 structure is somewhat unsightly. Rebuilding this structure should be considered in redevelopment plans.
2. Major modifications should be reversed for appearance and historic integrity. These include restoring the roof overhang, rebuilding approximately 5'-0" to the tops of the turrets, 7'-0" of the clock tower and restoring window openings that have been bricked in.

#### Best Potential Uses

1. Prison Museum / Interpretive Education Center, Support Retail, Tourist Information Center & Restrooms
2. Film Site or Studio
3. MSP Commission Offices & CVB Offices



Historic View of West Elevation prior to WPA (1936) additions, the rear pre-1885 structure is barely visible to the right.



Historic View of East Elevation prior to WPA (1936) additions, the rear pre-1885 structure is shown here.

# Architecture


## Housing Unit #1 – Possible Use




1935 plan of 1<sup>st</sup> floor of H.U. #1. Notice the double gate through the center of the building

### Possible Use Zones

- 
**Primary Use**  
 This area identifies the primary use for the building
- 
**Secondary Use**  
 This area identifies additional uses for the building beyond the primary use
- 
**Circulation**  
 This area identifies a zone for potential hallways, new required stairs, lobbies and elevator cores
- 
**Possible Addition**  
 This area identifies a zone for potential development attached to this historic building and suggestion as to how it could be done in a sensitive manner



Proposed First Floor Plan



Proposed 2nd Floor Plan



# Architecture

## Housing Unit #2 – Existing Information

### General Information

Date of Construction: **1938**

Existing No. of Floors: **5** Existing No. of Full Floors: **2** Existing No. of Offset Floors: **3**


Existing Area per Full Floor Plates: **18,000 gross sq. ft.**

Existing Total Floor Area: **49,000 gross sq. ft.**

Existing Prison Cell Floor to Floor Height: **9'-0"**


### Historic Information

1. Prison Cells are a significant feature within the building although examples of similar era cell construction will be preserved in Housing Unit #1 and potentially H.U. #3.
2. New floor levels to replace cells will eliminate full view of multi-level windows from the interior.
3. New construction for addition may require archeological work to comply with Section 106.
4. Constructed during extensive WPA work at this site.



# Architecture

## Housing Unit #2 – Existing Information



**NORTH ELEVATION PRIMARY, FACES HISTORIC QUADRANGLE & SERVES AS BACKDROP TO VIEWS FROM 1868 H.U. #4**

**Preservation Zones over Existing Plan**



### Preservation Zones


- Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority
- Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone
- Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
- Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



Typical View Into Cell Block Area



North elevation



**Existing Section**



# Architecture

## Housing Unit #2 – Possible Use

### General Information


Date of Construction: **1938**

Proposed No. of Floors: **4** Proposed No. of Full Floors: **4** Proposed No. Of Offset Floors: **0**

Proposed Area per Full Floor Plates: **18,000 gross sq. ft.**

Proposed Total Floor Area: **72,000 gross sq. ft.**

Redevelopment plan: **Cells to be removed and new floors installed**



Alternate Section




### Redevelopment Issues

1. The north elevation of this building can serve as the southern backdrop for the historic zone.
2. The steel cells are independent of the building structure, they can be removed without effecting the roof structure.

### Potential Uses

1. Corrections Offices with 48,000 gross sq. ft. addition to the south.



Alternative overlaid onto Existing Plan



## Architecture

### Housing Unit #3 – Existing Information

#### General Information

Date of Construction: **1914**

Existing No. of Floors: **6** Existing No. of Full Floors: **2** Existing No. Of Offset Floors: **4**


Existing Area per Full Floor Plates: **16,000 gross sq. ft.**

Existing Total Floor Area: **75,000 gross sq. ft.**

Existing Prison Cell Floor to Floor Height: **8'-4"**


#### Historic Information

1. Prison Cells are a significant feature within the building although examples of similar era cell construction will be preserved in Housing Unit #1. Cells at one-half of the building's length could be preserved for interpretive purposes.
2. New floor levels to replace cells will eliminate full view of multi-level windows from the interior.
3. Interior stairwell is a significant historic feature; these should be retained although new floor levels will not match the existing landing elevations.
4. 1954 riot started and ended in this building.



**Architecture**

**Housing Unit #3 – Existing Information**



**Existing First Floor Plan**



**Preservation Zones**

- Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority
- Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone
- Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
- Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



View of gun walk



Existing North Elevation

# Architecture

## Housing Unit #3 – Possible Use

### General Information

Date of Construction: **1914**

Proposed No. of Floors: **5 1/2** Proposed No. of Full Floors: **2** Proposed No. Of Offset Floors: **4**

Proposed Area per Full Floor Plates: **16,000 gross sq. ft.**

Proposed Total Floor Area: **75,600 gross sq. ft.**

Redevelopment plan: **Cells at west half of building could be removed for office space & new full floors installed**

### Redevelopment Issues


1. Interior gun walk / stairwell is a historic feature that should be preserved; landing levels are at each cell floor level. Existing cell floor-to-floor heights are not acceptable for modern offices. If the cells of at least one side of the building are removed for new development the stair landings will no longer line up with the new floor levels; a creative solution will be required.
2. WPA Canteen should be removed from the west elevation and the exterior then restored to pre-WPA appearance.

### Potential Uses

1. Offices
2. Prison museum

### Possible Use Zones

- Primary Use**  
This area identifies the primary use for the building
- Secondary Use**  
This area identifies additional uses for the building beyond the primary use
- Circulation**  
This area identifies a zone for potential hallways, new required stairs, lobbies and elevator cores
- Possible Addition**  
This area identifies a zone for potential development attached to this historic building and suggestion as to how it could be done in a sensitive manner



Alternative overlaid onto Existing Plan



## Architecture

### Housing Unit #4 – Existing Information

#### General Information

Date of Construction: **1868**

No. of Floors: **5** No. of Full Floors: **1** No. Of Offset Floors: **3**


Existing Area per Full Floor Plates: **13,500 gross sq. ft.**

Existing Total Floor Area: **43,000 gross sq. ft. not included basement**

Cell Floor to Floor Height: **10'-3"**

#### Historic Information

1. To what period should building be restored?
2. Roof overhang was removed.
3. A vertical mullion stone appears to have been removed at each window opening at the north and south elevations. This divided each opening into what was originally two separate windows.
4. Built for post-Civil War criminals.
5. Designed by Warden Horace Swift.
6. Stone was quarried on site by prisoners.
7. Oldest building existing on the site.




# Architecture

## Housing Unit #4 – Existing Information



View of typical window




Existing First Floor Plan



### Preservation Zones

- Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority
- Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone
- Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
- Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



Interior View




View from Northwest

# Architecture

## Housing Unit #4 – Possible Use

### Redevelopment Issues

1. What period should the building be restored? Many modifications have occurred to the building since it's construction.
2. It appears that the roof overhang and soffits were removed exposing brick backup material above the stone walls, these should be restored.
3. Stone restoration will be necessary. There are crushed stones at various locations and missing stone mullions in the window openings that should be restored.
4. Integrating modern mechanical systems could be completely hidden. The extent to which this is done will be dependant on the interpretive philosophy for this building.




### Potential Uses

1. Prison Museum / Interpretive Center. Each floor level could be restored and furnished to represent distinct time periods of prison life as shown in the Alternate Section above.

#### Possible Use Zones

- Primary Use**  
This area identifies the primary use for the building
- Secondary Use**  
This area identifies additional uses for the building beyond the primary use
- Circulation**  
This area identifies a zone for potential hallways, new required stairs, lobbies and elevator cores
- Possible Addition**  
This area identifies a zone for potential development attached to this historic building and suggestion as to how it could be done in a sensitive manner



## Architecture

### Housing Unit #5 – Existing Information

#### General Information

Date of Construction: **1938**

No. of Floors: **7** No. of Full Floors: **4** No. Of Offset Floors: **3**


Existing Area per Full Floor Plates: **17,000 gross sq. ft.**

Existing Total Floor Area: **97,500 gross sq. ft.**

Cell Floor to Floor Height: **9'-0"**


#### Historic Issues

1. Prison Cells are a significant feature within the building although examples of similar era cell construction will be preserved in Housing Unit #1 and potentially H.U. #3.
2. New floor levels to replace cells will eliminate full view of multi-level windows from the interior.
3. Constructed during extensive WPA work at this site.



**Architecture**

**Housing Unit #5 – Existing Information**



Preservation Zones over Existing Plan

1"=50'-0"

**Preservation Zones**


- Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority
- Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone
- Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
- Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



Typical View Into Cell Block Area



South Elevation



Existing Section

1"=50'-0"

## Architecture

### Housing Unit #5 – Possible Use

#### General Information

Date of Construction: **1938**

No. of Floors: **6** No. of Full Floors: **6** No. Of Offset Floors: **0**

Proposed Area per Full Floor Plates: **17,000 gross sq. ft.**

Proposed Total Floor Area: **102,500 gross sq. ft.**


Cells to be completely removed

#### Redevelopment Issues

1. Locked in between Housing Unit #4 preservation area to the south and proposed vehicular circulation to the north.
2. West elevation is integrated into the WPA corridor since they were built at the same time; if the corridor is removed, the detailing of this at the building will be important.
3. Water infiltration problems are occurring in the sub-basement level due to the extended lower levels under courtyard to the south.
4. Shallow floor plates.
5. The south elevation can serve as the northern backdrop for the historic zone.

#### Potential Uses

1. Hotel – approximately 152 rooms (38 rooms on each floor x 4 floors)
2. Offices




**Architecture**

**Housing Unit #5 – Possible Use**

**Possible Use Zones**

- Primary Use**  
This area identifies the primary use for the building
- Secondary Use**  
This area identifies additional uses for the building beyond the primary use
- Circulation**  
This area identifies a zone for potential hallways, new required stairs, lobbies and elevator cores
- Possible Addition**  
This area identifies a zone for potential development attached to this historic building and suggestion as to how it could be done in a sensitive manner



**Alternative overlaid onto Existing Plan**



## Architecture

### Shoe Factory – Existing Information

#### General Information

Date of Construction: **pre-1881 although burned in 2 major fires**

No. of Floors: **4**


Existing Area per Floor Plates: **12,000 gross sq. ft.**

Existing Total Floor Area: **46,600 gross sq. ft.**

Floor to Floor Height: **12'-0"-16'-0"**

#### Historic Information

1. The 2<sup>nd</sup> oldest building on the prison site
2. Somewhat cut-off from historic courtyard by H.U. 5, which was built during the WPA work.
3. Was one of the largest Saddletree manufacturer's in the world, owned by J.S. Sullivan Saddletree Factory
4. The only building on the site representing both 19<sup>th</sup> and 20<sup>th</sup> century prison inmate labor by lease, contract and state operated methods.




# Architecture

## Shoe Factory – Existing Information

### Preservation Zones

-  **Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority
-  **Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone
-  **Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
-  **Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



Northeast corner of building, H.U. 5 is in the background



View of interior structure

## Architecture

### Shoe Factory – Possible Use

#### General Information

Date of Construction: **pre-1881 although it burned in 2 major fires**

No. of Floors: **4**

Existing Area per Floor Plates: **12,000 gross sq. ft.**

Existing Total Floor Area: **46,600 gross sq. ft.**

Cell Floor to Floor Height: **12'-0"-16'-0"**

#### Redevelopment Issues

1. A significant amount of the original window openings have been bricked in over the years, these should be re-opened and restored.
2. Paint should be removed from the exterior brick surface.
3. The original window design should be replicated and installed.
4. Existing floor-to-floor height is ideal for redevelopment.

#### Potential Uses

1. Hotel / Convention Center

#### Other Successful Examples

1. The Westin Hotel, St. Louis

# Architecture

## Furniture Factory – Existing Information

### General Information


Date of Construction: **between 1925-1936**

No. of Floors: **1** No. of Full Floors: **1**

Existing Area: **35,200 gross sq. ft.**

### Historic Information

1. Represents history of 20<sup>th</sup> century prison labor.
2. Built at the same time as the Metal Working Plant, the two should remain as a pair.




# Architecture

## Furniture Factory – Existing Information

### Preservation Zones

- Level 1 - Preservation Zone**  
 The character & qualities of this zone should be maintained & preserved as the highest priority
- Level 2 - Preservation Zone**  
 Every effort should be made to maintain and preserve the character and qualities of this zone
- Level 3 - Rehabilitation Zone**  
 Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
- Level 4 - Free Zone**  
 Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



Preservation Zones over Existing Plan

# Architecture


## Furniture Factory – Possible Use

### Redevelopment Issues

1. Adjacent to the existing rail line, the prison stone wall should remain around this building as a sound barrier.
2. Early graveyard may be located around and/or under this building.
3. The adjacent Sallyport is an integral part of this building and should remain.
4. The number of columns throughout the space could potentially be reduced with transfer beams.

### Potential Uses

1. Meeting Rooms for Hotel / Convention and Conference Center
2. Exhibit Hall
3. Performing Arts Center
4. Restaurant



### Possible Use Zones

- 
**Primary Use**  
 This area identifies the primary use for the building
- 
**Secondary Use**  
 This area identifies additional uses for the building beyond the primary use
- 
**Circulation**  
 This area identifies a zone for potential hallways, new required stairs, lobbies and elevator cores
- 
**Possible Addition**  
 This area identifies a zone for potential development attached to this historic building and suggestion as to how it could be done in a sensitive manner



Existing view of South elevation, I-Hall is in the foreground to the right

# Architecture

## Metal Working Plant – Existing Information

### General Information


Date of Construction: **between 1925-1936**

No. of Floors: **1**

Proposed Total Floor Area: **40,000 sq. ft.**

### Historic Information

1. Represents history of 20<sup>th</sup> century prison labor.
2. Built at the same time as the Furniture Factory, the two should remain as a pair.



# Architecture


## Metal Working Plant – Existing Information



Existing Interior View

### Preservation Zones

- Level 1 - Preservation Zone**  
 The character & qualities of this zone should be maintained & preserved as the highest priority
- Level 2 - Preservation Zone**  
 Every effort should be made to maintain and preserve the character and qualities of this zone
- Level 3 - Rehabilitation Zone**  
 Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
- Level 4 - Free Zone**  
 Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



Existing First Floor Plan



# Architecture


## Metal Working Plant – Possible Use

### Redevelopment Issues

1. Skylights are a feature that should be incorporated into the re-use. This would require that the interior space remains a fairly open plan.
2. The number of columns throughout the space could potentially be reduced with transfer beams.

### Potential Uses

1. Performing Arts Center
2. Restaurant
3. Meeting Rooms for Hotel / Convention and Conference Center
4. Exhibit Hall



### Possible Use Zones

- 
**Primary Use**  
 This area identifies the primary use for the building
- 
**Secondary Use**  
 This area identifies additional uses for the building beyond the primary use
- 
**Circulation**  
 This area identifies a zone for potential hallways, new required stairs, lobbies and elevator cores
- 
**Possible Addition**  
 This area identifies a zone for potential development attached to this historic building and suggestion as to how it could be done in a sensitive manner



Existing South Elevation, above grade steam pipes are in the foreground

## Architecture

### Centennial Cells – Existing Information

#### General Information

Date of Construction: **pre-1885 (exact date unknown)**

No. of Floors: **Underground Foundation Remains Only**


Existing Area: **7,200 gross sq. ft.**

#### Historic Issues

1. Archeological investigations may have to occur if foundation is disturbed for future development.
2. According to early Sanborn maps, it appears that the north wall of the Centennial Cells was incorporated into an earlier stone prison wall that ran east and west.



View of secure exercise yards above the Centennial Cells



## Architecture

### Centennial Cells – Possible Use

#### Redevelopment Issues

1. Difficult to preserve ruins for viewing without a new structure to serve as protection from weather and erosion.
2. If plans were to include preserving these foundation remains, should other remains be left undisturbed, some may be even older than this structure. Through available Sanborn maps we know exactly where many foundation remains may be. In fact, the “E” Hall foundation, which was built before 1898, is exposed in the yard north of Housing Unit #4.

#### Potential Uses

1. Leave site undisturbed underground, interpret through maps, drawings & other historical information.
2. Excavate and interpret as ruins.



Photograph by Mark Schreiber taken during archeological investigation

## Architecture

### Gas Chamber – Existing Information

#### General Information


Date of Construction: **1937**

No. of Floors: **1** No. of Full Floors: **1**

Existing Area: **750 gross sq. ft.**

#### Historic Information

1. The context of this building is important. An arbor once existed just outside the entrance along the walk to the west. The walk has an inlaid cross.
2. 39 executions and 1 lethal injection occurred here.
3. Last used in 1989.
4. Built by inmate labor; the stone is from the prison-operated quarry.



**Architecture**

**Gas Chamber – Existing Information**



Existing interior view

**Preservation Zones**

- Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority
- Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone
- Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
- Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



Existing view from Southwest

## Architecture


### Gas Chamber – Possible Use

#### Redevelopment Issues

1. Location may hinder new development; extra effort must be made to integrate with new construction around it.
2. The arbor and walk should be restored to retain historic setting.

#### Potential Uses

1. Prison Museum / Interpretive
2. Gas Chamber Museum H-9, an icon for future redevelopment



## Architecture

### Potato House – Existing Information

#### General Information


Date of Construction: **1935**

No. of Floors: **1** No. of Full Floors: **1**

Existing Area: **24,000 gross sq. ft.**

#### Historic Information

1. Separated from the historic area by the roadway and stone walls.
2. The structure is buried under an earth berm. Some large trees have grown on top of the structure; the larger trees should be removed in order to maintain the building.




# Architecture

## Potato House – Existing Information

### Preservation Zones

-  **Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority
-  **Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone
-  **Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible; However, contemporary methods, materials, & designs may be selectively incorporated
-  **Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs



Existing First Floor Plan



Existing view of interior



Existing view of North elevation

## Architecture

### Potato House – Possible Use

#### Redevelopment Issues

1. Waterproofing the roof will be expensive and require careful detailing.
2. There are no windows on the east or west elevations.

#### Potential Uses

1. Interpretive Center for Department of Natural Resources
2. Farmer's Market

## Architecture

### Education Building / Dining Hall & Clothing Factory – Existing Information

#### Education Building / Dining Hall General Information

Date of Construction: **1885**

No. of Floors: **2**

Existing Area per Full Floor Plates: **11,100 gross sq. ft.**

Existing Total Floor Area: **22,200 gross sq. ft.**

Original Uses: 1<sup>st</sup> floor: Lower Dining Hall & Kitchen

2<sup>nd</sup> floor: Larger Dining Hall

3<sup>rd</sup> floor: Chapel, Library

Basement: ice plant, cold storage & vegetable cellar

#### Clothing Factory General Information

Date of Construction: **pre-1885**

No. of Floors: **2**

Existing Area per Full Floor Plates: **9,600 gross sq. ft.**


Existing Total Floor Area: **19,200 gross sq. ft.**

#### Education Building / Dining Hall Historic Information

1. Upper floors were destroyed during the 1954 riot.
2. Originally enclosed courtyard.

#### Clothing Factory Historic Information

1. Upper floors were destroyed during the 1954 riot.
2. Older than the Dining Hall but original construction date unknown.



## Architecture

### Education Building / Dining Hall & Clothing Factory – Possible Use

#### Dining Hall General Information

Date of Construction: **1885**

No. of Floors: **4**

Proposed Area per Full Floor Plates: **11,100 gross sq. ft.**

Proposed Total Floor Area: **44,400 gross sq. ft.**

#### Dining Hall Redevelopment Issues

1. Modern top floor addition should be removed.
2. More photographs or drawings need to be located.

#### Dining Hall Potential Uses

1. Offices

#### Clothing Factory General Information

Date of Construction: **pre-1885**

No. of Floors: **3**

Proposed Area per Full Floor Plates: **9,600 gross sq. ft.**

Proposed Total Floor Area: **28,800 gross sq. ft.**

#### Clothing Factory Redevelopment Issues


1. Since the original upper floors were destroyed during the 1954 riot a new modern roof and/or potentially glass clerestory could be constructed according to needs of the new use.

#### Clothing Factory Potential Uses

1. Meeting Hall for Convention Center



View of the north elevation of the Education Building / Dining Hall



Current photograph looking west with H.U. 4 in the background. The Dining Hall is to the left and the Clothing Factory (currently Maintenance), to the right.



Early photograph / rendering of stone Dining Hall with brick Clothing Factory to the north.

# Architecture

## Stone Walls – Existing Information


### General Information

Date of Construction: **Pre-1885 to 1980's**

**(The earliest date is unknown at this time, although a stone wall was contracted for construction as early as 1834.)**

### Historic Issues

1. The stone walls have been modified over time as the prison was enlarged and security improved. A more extensive evaluation should be done to determine what periods certain sections of the walls were built.
2. Some stones have early markings by prisoners, quarrying and earlier uses.




**REMAINING WALLS**

**\* DATES SHOWN ARE APPROXIMATE DATE OF CONSTRUCTION. FURTHER RESEARCH & ON-SITE INVESTIGATION SHOULD BE DONE IN ORDER TO ENSURE THAT THE EARLIER SECTIONS OF THE WALL ARE IDENTIFIED**



Existing view of typical guard tower.



Existing view of Northern end of pre-1885 wall @ Shoe Factory

# Architecture


## Stone Walls – Possible Use

### Redevelopment Issues

1. New openings will be required through the walls for vehicular and pedestrian access.
2. Some guard towers should be restored to their original appearance through photographic documentation.
3. Corners should be retained in order to preserve the boundaries of the enclosed prison site for interpretative purposes.
4. Care must be taken to retain the walls as a key historic feature to the site.
5. Any new openings should be clearly defined as different from restored openings with careful and consistent detailing.

### Potential Uses

1. Interpretation of the prison site boundaries.
2. Existing sound barrier against rail line to the north.
3. Defines the historic zone.
4. Tourist destination feature as observation points from guard stations. It would be interesting a guard station as a modern example and restore others to an earlier period. Many people would be curious as to what it would be like to have monitored the site for long shifts as they do now. Also, access into the northern guard stations could offer tremendous views up and down the Missouri River.





# Building Systems



**M S P**

## Building Systems

### Introduction

The following are descriptions of heating, ventilating and air conditioning (HVAC), plumbing, fire protection and electrical systems at major buildings within the Jefferson City Correction Center, are based on a brief building and site walk-throughs and discussions with facility operating personnel.

### Central Plant

#### Existing Conditions

The central plant consists of four 1000 BHP and one 300 BHP high-pressure steam boilers. They are headered together to provide a redundant heating system for the prison. Under current operating conditions, the summer boiler (300 BHP) is too small to satisfy the summer load. In the winter, two large boilers can satisfy the load. The plant has been well maintained and appears to be in excellent condition.

Central hot water is also generated and distributed to each building from the central plant through a steam to hot water heat exchanger.

#### Proposed Actions

The plant if maintained at its current level could service the facility for the next 20 to 30 years. The boilers are currently an asset to the State and should be considered in any transfer of the property.

In our opinion, the future of the boiler plant hinges on ownership of the property and individual buildings. If the property, or a significant portion of the property, is held by a single entity, then a central boiler plant could provide operating benefits to the facility of reduced maintenance, optimized operational (energy and personnel) cost savings and reduced building construction costs. The cost of central utilities could



Boiler Plant Auxiliaries



Boiler Plant Exterior

## Building Systems

be incorporated into the individual rate structures. A full cost benefit ratio could be performed to determine if this would be a viable/attractive concept. However, if individual title is transferred for the properties, then we believe that the central utility system should be abandoned and individual systems serving each facility constructed.

It should be noted that the current development plan calls for major new road construction directly at the current boiler plant site. If this is the case this equipment will need to be relocated, or some combination of central and distributed plant established, or the unused portions of the facility mothballed under new individual heating plant are established.

If the plant is to be disposed, of the State should considered dismantling the plant and relocating it to the new prison or other State facility.



Boilers



Overhead Steam, Condensate & DHW  
Piping from Boiler Plant

## Building Systems

### Utility Distribution & Steam Tunnels

#### Existing Conditions

The steam tunnels are a mixture of brick arch structures and new reinforced concrete tunnels. The piping in these tunnels were replaced in the mid-1980's. The steam piping appears to be in good condition, but operating personnel indicate that they have noticed increased maintenance requirements with the piping. No water leakage or standing water was observed during our visit, although some steel angle supports showed signs of advanced deterioration.

Central domestic hot water piping appears to be in good condition. A large portion of this piping appears to be uninsulated.

Domestic cold water piping is also installed in the tunnels. This piping appears to be in very poor condition.

#### Proposed Actions

The steam tunnels, in general, appear to be in satisfactory condition and could be reutilized; however, we have observed structural conditions that need to be addressed. The piping in the tunnel is currently 20 years old and will require escalating maintenance. Again, we believe that the future of the tunnels and piping depend on the future ownership of the campus. See Central Plant.




## Building Systems

### Steam Tunnels – Utility Distribution

- Overhead Distribution
- - - - - Underground (Direct Buried, Tunnels or Through Basements) Distribution

Utility Transformers



## Building Systems

### Gas Chamber

#### Existing Conditions


The gas chamber is a stand-alone structure. It is electrically heated with recessed unit heaters by the doors. Minimal plumbing and electrical systems are provided.

#### Propose Actions

We understand that the building is to be preserved in its current condition, as an historical artifact.



Gas Chamber Door



Wall Mounted Unit Heater

## Building Systems

### Furniture Factory

#### Existing Conditions

The Furniture Factory provides furniture for State facilities. We understand that almost all of the furniture equipment infrastructure will be relocated to the new prison. The building is serviced with steam heat from the central plant from overhead lines. Pressure is reduced inside the building to 15 lbs. The building is heated with large unit heater style equipment. There is no central ventilation system. The building is fully sprinklered.

Electrically the building is served from an 800 amp/440 volt, 3 phase panel. The building has adequate power for machine shop activities.

#### Proposed Actions

The building remains viable for light machining applications. A new ventilation system and spot cooling would likely be required for a commercial setting.



Condensate Pump



## Building Systems

### Metal Working Plant

#### Existing Conditions

The Metal Working Plant provides license plates for motor vehicles throughout the state. We understand that almost all of the equipment and infrastructure will be relocated to the new prison. The building is serviced with steam heat from the central plant from overhead lines. Pressure is reduced inside the building to 15 lbs. A summer steam boiler (1380 lbs./hour) is contained in the building. It is currently not utilized. The boiler should be capable of providing minimal heating to a 30,000 sq. ft. structure.



The building is heated with large unit heater style equipment. There is no central ventilation system. Exhaust is only provided in the finishing area. The building is fully sprinklered.

Electrically the building is served from a two 600 amp/440 volt, 3 phase panel. The building has adequate power for machine shop activities. Lighting is a mixture of incandescent and fluorescent

#### Proposed Actions

The building remains viable for light machining applications. A new ventilation system and spot cooling would likely be required for a commercial setting. In general, the systems could continue to be serviceable in an industrial setting.



Auxiliary Boiler

## Building Systems

### Shoe Factory

#### Existing Conditions

The Shoe Factory has been renovated over the years to be a manufacturing facility of “finer” quality goods which require detailed tasks. In general, lighting has been improved and minimal power distributed for sewing machines and presses. The building is heated with steam unit heaters from distribution piping in the basement. No ventilation is currently provided.

#### Proposed Actions

If the Shoe Factory is to be renovated into a commercial center, then all new mechanical/electrical infrastructure will be required. Existing electrical service is likely not adequate to service commercial requirements.



Basement Storage Room – Steam Pipe



## Building Systems

### Boiler House

#### Existing Conditions

The Boiler House contains the original boiler plant from the 1930's and supplemented in 1979. The equipment is virtually useless with spare parts being stripped for other facilities.

The building currently serves two functions:

- 1) as a transition between the new steam plant distribution system and the original steam distribution system.
- 2) To provide space for new condensate pumps were recently installed to return condensate to the new Boiler House.

#### Proposed Actions

The building is no longer a necessary part of the campus infrastructure except for the two minimal space requirement functions noted above. Gutted, abated and cleaned the building could be functional space adapted to many uses.



Old Boiler Plant and Overhead Piping

Interior View

## Building Systems

### Housing Unit #1


#### Existing Conditions

Housing Unit #1 is provided with minimal mechanical and electrical systems. Steam unit heaters provide space heating; ceiling fans provide circulation. No central ventilation system is provided. The building is fully sprinklered.

The building is equipped with a 225 amp/440 volt service. Lighting and distributed power are minimal but meet current space requirements.

#### Proposed Actions

Any adaptive retrofit would require a wholesale gut rehab of the mechanical/electrical systems in the facility.



## **Building Systems**

### **Housing Unit #2**

#### Existing Conditions

Housing Unit #2 is provided with minimal mechanical and electrical systems. An abandoned heating/ventilating system is provided at the rooftop level. Steam unit heaters provide space heating; ceiling fans provide circulation. No central ventilation system is provided. The building is fully sprinklered.

The building is equipped with a 500 amp/440 volt service. Lighting and distributed power are minimal but meet current space requirements.

#### Proposed Actions

Any adaptive retrofit would require a wholesale gut rehab of the mechanical/electrical systems in the facility.

## Building Systems

### Housing Unit #3

#### Existing Conditions

Housing Unit #3 is provided with minimal mechanical and electrical systems. Heating and ventilating units (100 percent outdoor air) were installed in a basement mechanical room in the 1980's. These units appear to be in good condition. The building is fully sprinklered.

The building is equipped with a 400 amp/440 volt service. Lighting and distributed power are minimal but meet current space requirements.

#### Proposed Actions

Any adaptive retrofit would require a wholesale gut rehab of the mechanical/electrical systems in the facility.



Basement Heating and Ventilating Units



## Building Systems

### Housing Unit #4

#### Existing Conditions

Housing Unit #4 is provided with minimal mechanical and electrical systems. Steam unit heaters provide space heating; ceiling fans provide circulation. No central ventilation system is provided. The building is fully sprinklered.

The building is equipped with a 440 volt service. (Amperage could not be determined.) Lighting and distributed power are minimal but meets current space requirements.

#### Proposed Actions

Any adaptive retrofit would require a wholesale gut rehab of the mechanical/electrical systems in the facility. However, we understand the current master plan may include reutilizing this facility as a history museum. If that is the case it will be important to introduce modern MEPF systems into the building in a manner that consistent with the period nature of the museum. In addition, a fully conditioned space may be difficult to achieve without substantial intrusion due to the construction of the cell units. Only partial environmental control of the cell blocks may be provided (in addition to being historically accurate), while the central core is a more conditioned space.



Typical Cell Converted to Office



Views of Main Corridor  
with Unit Heaters



## Building Systems

### Housing Unit #5


#### Existing Conditions

Housing Unit #5 is provided with minimal mechanical and electrical systems. Rooftop heating and ventilating units were abandoned in the 1980's and are in poor condition. Steam unit heaters provide space heating; ceiling fans provide circulation. No central ventilation system is provided. The building is fully sprinklered.


The building is equipped with a 225-amp/440 volt service from Building 5C. Lighting and distributed power are minimal but meets current space requirements.

#### Proposed Actions

Any adaptive retrofit would require a wholesale gut rehab of the mechanical/electrical systems in the facility.



Interior – Unit Heaters and Ceiling Fans



Interior Stairwell Core



Ice Plant Equipment



# Environmental Summary

**M S P**

## Environmental Summary

### Introduction

A Phase I Environmental Site Assessment (ESA) was performed in November, 2001 for the property known as the Jefferson City Correctional Facility (MSP) located in Jefferson City, Cole County, Missouri. The Phase I ESA was conducted for the purpose of identifying potential recognized environmental conditions (RECs) associated with the property. In addition, a Phase I Environmental Site Assessment (ESA) was performed in June 2001, for the property known as The State Agency for Surplus Property. Together these two documents are referenced one to the other and presented in Appendix A.

### Location

The subject property occupies approximately 150 acres in Cole County, Missouri. The main prison is bounded by; East State Street, Lafayette Street, and East Capitol Avenue to the east; Dulle and Hampton Towers to the north; Union Pacific and Missouri River to the west; and the Missouri Department of Surplus Properties to the south. The subject property consists primarily of grass and tree covered lots, asphalt and concrete lots, and limestone and brick buildings with concrete basements. Concrete sidewalk, streets, alleys, yards, and several underground utilities surround the subject property. The State Agency for Surplus Properties is located on the Jefferson City Correctional Facility property.



Jefferson City Correctional Facility Administration Building Facing North

## Environmental Summary

### Summary of Findings


The Environmental Data Resources (EDR) database search identified 33 facilities within their respective American Society for Testing Materials (ASTM) defined search distances from the subject property.

Twelve UST (Underground Storage Tank) sites were located within the ¼-mile radius search of the subject property. These sites were

- Jefferson City Correctional Center,
- SIPI's 66,
- Former Medical Arts Building,
- Buescher Memorial Home,
- Hocker Oil Company,
- Jefferson City Station,
- Phillip's 66/Pump Handle Snack Shop,
- Turner's Conoco,
- Central Maintenance Garage,
- Al's Tire Service,
- State of Missouri Surplus Property, and
- Cole County Courthouse.

Ten LUST (leaking underground storage tank) sites were located within ½-mile of the subject property. These sites were

- Former Medical Arts Building,



## Environmental Summary

- Hocker Oil Company,
- Jefferson City Station,
- Central Maintenance Garage,
- Al's Tire Service,
- State of Missouri Surplus Property,
- Sprint,
- Jefferson State Office Building,
- Central Education Facility,
- Fill and Wash and Clark and Elm.

Seven Resource Conservation and Recovery Act Small Quantity Generator (RCRA SQG) sites were located within ¼-mile of the subject property. These sites were

- Jefferson City Correctional Center,
- Jefferson City Central Maintenance Center (820 East Miller Street),
- Jefferson City Central Maintenance Center (210 Monroe Street),
- Al's Tire Service,
- Missouri Bar Print,
- City of Jefferson City, and
- Firestone Tire and Rubber Company.

One FINDS (Facility Index System) site was located as part of the search. This site was Jefferson City Correctional Center, the target property.

One FTTS [FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) /TSCA (Toxic Substance Control Act) Tracking System] site was located. This site was also the Jefferson City Correctional Center.

Three orphan sites were indicated by the EDR report. An orphan site is defined as a site unmappable with the information available. One site was Delong's, located on East Capitol Avenue in Jefferson City, Missouri 65101. This site was classified as a UST. A second site was

## Environmental Summary

SS 5634, located at 507 McCarty Street in Jefferson City, Missouri 65101. This site was also classified as a UST. A third site was the MO Highway and Transportation Dept., located on East McCarty Street in Jefferson City, Missouri 65101. This site was classified as an LUST. Information on the address location and activities on these sites was not provided.

The following RECs have been identified for the subject property as a result of the Phase I ESA:

- Potential asbestos-containing building materials (ACBM);
- Potential lead-based paint (LBP);
- Potential soil and groundwater impact from UST and LUST tank removal sites at topographically equal or lower elevations to the property located at the old boiler house, Surplus Properties, the garage facility, behind the Soap factory, and the new boiler house;
- Potential soil and groundwater impact from current and historical industrial sites located in two places within the prison. The current site is located in the west section in a topographically low area of the prison. The historical industrial site is located in the east section in a topographically high area of the prison where the current upper playing fields are located. Former chemical storage vaults located on the southeast side of the prison between the new boiler house and Surplus Properties would also be a target;
- Potential soil impact from unknown sources of backfill materials located in five locations in and around the prison. The first location is the current Administration Building and Garage Facility. The second location is outside the southeast prison wall along East Capital Drive. The third location is the terrace slope where the new boiler house is located. The fourth location is along the bluffs next to the former Lard house and Potato House. The fifth location is a soil hill trending northwest/southeast between the upper and lower playing fields.
- Recognized environmental conditions relate to possible environmental impacts associated with historic land use and practices, and potential sources of environmental impacts associated with the existing building and/or current site practices.

Asbestos and lead-based paint inspections of existing structures must be performed by Missouri licensed inspectors. These inspections are required by federal, state and local regulations prior to disturbance of these structures. Environmental soil borings may be necessary for the subject property in the areas topographically lower or equal to former UST and AST sites; current and former industrial site locations within the prison; the former chemical storage vaults outside the prison; and the five backfill locations in and around the prison to determine if any environmental impact exists.

## Environmental Summary

### Purpose

The purpose of the environmental site assessment is to address potential environmental concerns of the subject property by reviewing past usages of the subject property and adjacent properties, identifying recognized environmental conditions (RECs), and assessing the environmental impact of the RECs on the subject property. RECs are defined in ASTM E 1527-00 as “the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property.” An additional purpose of this ESA is to address the relevance of the identified RECs to the subject property’s future development.

The environmental site assessment was conducted in accordance with the ASTM Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM E 1527-00. The Phase I ESA activities consist of:

- Records Review
- Site Reconnaissance
- Interviews
- Documentation

The conclusions included in the report were prepared with the understanding that the sites may be redeveloped in the near future. See Appendices A for the full details of the Phase I Environmental Site Assessment (ESA) for JCCC (MSP) and Surplus Property.



# Framework Plan

The MSP Redevelopment Project

*Appendices A, B, C, & D*

M S P




Bob Holden, Governor



*“Make no little plans; they have no magic to stir men’s blood and probably themselves will not be realized. Make big plans; aim high in hope and work, remembering that a noble, logical diagram once recorded will never die, but long after we are gone will be a living thing, asserting itself with ever growing insistency. Remember that our sons and grandsons are going to do things that would stagger us. Let your watchword be order and your beacon beauty.”*

*Daniel Burnham - 1907*



# Framework Plan

The MSP Redevelopment Project

Appendices A, B, C, & D

M S P



October 2003

## Table of Contents

### **Framework Plan** (Under Separate Cover)

#### **Appendix A**

Phase I Environmental Assessment – Jefferson City Correctional Facility (MSP) June 3, 2002

Phase I Environmental Assessment – State Agency for Surplus Property June 29, 2001

#### **Appendix B**

Observations of the Enclosure Walls

#### **Appendix C**

PowerPoint Handout - Public Presentation - February 11, 2003


#### **Appendix D**

Existing Buildings To Remain – Drawing

The Master Plan – Drawing

Master Plan Sketch Looking East

Master Plan Sketch Looking West



# Appendix A

**M S P**



## PHASE I ENVIRONMENTAL ASSESSMENT

JEFFERSON CITY CORRECTIONAL FACILITY  
631 EAST STATE STREET  
JEFFERSON CITY, MISSOURI 65101

*Prepared for:*  
*Parson HBA*  
*400 Woods Mill Road South, Suite 300*  
*St. Louis, Missouri 63017*



59<sup>th</sup> and Arsenal  
Building C  
Two Campbell Plaza  
St. Louis, Missouri 63139

June 3, 2002



Section.....	Page.....
Executive Summary	
1.0 Introduction.....	7
1.1 Purpose.....	7
1.2 Methodology.....	7
2.0 Site Description.....	8
2.1 Location and Legal Description.....	8
2.2 Site and Vicinity .....	8
2.3 Site Improvements .....	8
2.4 Current Uses of Property .....	8
2.5 Past Uses of the Property .....	8
2.6 Current and Past Uses of Adjoining Property.....	9
2.7 Site Physical Setting .....	9
3.0 Records Review .....	10
3.1 Environmental Record Sources.....	10
3.2 Aerial Photographs.....	17
3.3 Local Directories.....	18
3.4 Local Zoning/Land-Use Records.....	18
3.5 Sanborn Maps .....	18
3.6 Historical Topography Maps .....	20
3.7 Audit Check Facility Report .....	20



4.0 Site Reconnaissance.....21

4.1 Site Survey Process.....21

4.2 Hazardous Materials and Petroleum Products .....21

4.3 Storage Tanks.....21

4.4 Drums.....21

4.5 Hazardous Waste .....22

4.6 Solid Waste .....22

4.7 Wastewater.....22

4.8 Drains and Sumps .....22

4.9 Stains and Pools of Liquid (Interior) .....22

4.10 Pits, Ponds, Lagoons .....22

4.11 Stained Soil or Pavement and Stressed Vegetation .....23

4.12 Potential PCB-Containing Electrical or Hydraulic Equipment .....23

5.0 Interviews and Questionnaire .....24

5.1 Owner/Tenant Questionnaire .....24

5.2 Local Fire Department .....24

5.3 Local Utility Company .....24

6.0 Findings, Conclusions and Recommendations .....25

7.0 Signatures of Environmental Professionals .....26

8.0 Qualifications of Environmental Professionals .....27

9.0 Limitations of Report.....29



Figures

- 1 Topographic and Site Plan

Appendices

- A State Agency for Surplus Property – Phase I Environmental Assessment (June 29, 2001), by reference only.
- B Site Reconnaissance Photographs
- C Site Survey Summary Form
- D Material Safety Data Sheet Summary
- E Ameren UE Correspondence



## Executive Summary

---

TSi Engineering, Inc. (TSi) performed a Phase I Environmental Site Assessment (ESA) in November, 2001 for the property known as the Jefferson City Correctional Facility located in Jefferson City, Cole County, Missouri. This Phase I ESA was conducted for Parson HBA, Inc. for the purpose of identifying potential recognized environmental conditions (RECs) associated with the property.

The subject property occupies approximately 150 acres in Cole County, Missouri. The main prison is bounded by; East State Street, Lafayette Street, and East Capitol Avenue to the east; Dulle and Hampton Towers to the north; Union Pacific and Missouri River to the west; and the Missouri Department of Surplus Properties to the south. The subject property consists primarily of grass and tree covered lots, asphalt and concrete lots, and limestone and brick buildings with concrete basements. Concrete sidewalk, streets, alleys, yards, and several underground utilities surround the subject property. The Missouri Department of Surplus Properties is located on the Jefferson City Correctional Facility property. TSi performed a Phase I ESA of this property and the adjoining undeveloped forested area to the southeast, to the extent accessible, in June of 2001. That Phase I ESA is presented in this report as appendix A.

The Environmental Data Resources (EDR) database search identified 33 facilities within their respective American Society for Testing Materials (ASTM) defined search distances from the subject property. Twelve UST (Underground Storage Tank) sites were located within the ¼-mile radius search of the subject property. These sites were Jefferson City Correctional Center, SIPI's 66, Former Medical Arts Building, Buescher Memorial Hone, Hocker Oil Company, Jefferson City Station, Phillip's 66/Pump Handle Snack Shop, Turner's Conoco, Central Maintenance Garage, Al's Tire Service, State of Missouri Surplus Property, and Cole County Courthouse. Ten LUST (leaking underground storage tank) sites were located within ½-mile of the subject property. These sites were Former Medical Arts Building, Hocker Oil Company, Jefferson City Station, Central Maintenance Garage, Al's Tire Service, State of Missouri Surplus Property, Sprint, Jefferson State Office Building, Central Education Facility, Fill and Wash and Clark and Elm. Seven Resource Conservation and Recovery Act Small Quantity Generator (RCRA SQG) sites were located within ¼-mile of the subject property. These sites were Jefferson City Correctional Center, Jefferson City Central Maintenance Center (820 East Miller Street), Jefferson City Central Maintenance Center (210 Monroe Street), Al's Tire Service, Missouri Bar Print, City of Jefferson City, and Firestone Tire and Rubber Company. One FINDS (Facility Index System) site was located as part of the search. This site was Jefferson City Correctional Center, the target property. One FTTS [FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) /TSCA (Toxic Substance Control Act) Tracking System] site was located. This site was also the Jefferson City Correctional Center. Three orphan sites were indicated by the EDR report. An orphan site is defined as a site unmappable with the information available. One site was Delong's, located on East Capitol Avenue in Jefferson City, Missouri 65101. This site was classified as a UST. A second site was SS 5634, located at 507 McCarty Street in Jefferson City, Missouri



65101. This site was also classified as a UST. A third site was the MO Highway and Transportation Dept., located on East McCarty Street in Jefferson City, Missouri 65101. This site was classified as an LUST. Information on the address location and activities on these sites was not provided.

In our opinion, the following RECs have been identified for the subject property as a result of this Phase I ESA:

- Potential asbestos-containing building materials (ACBM);
- Potential lead-based paint (LBP);
- Potential soil and groundwater impact from UST and LUST tank removal sites at topographically equal or lower elevations to the property located at the old boiler house, Surplus Properties, the garage facility, behind the Soap factory, and the new boiler house;
- Potential soil and groundwater impact from current and historical industrial sites located in two places within the prison. The current site is located in the west section in a topographically low area of the prison. The historical industrial site is located in the east section in a topographically high area of the prison where the current upper playing fields are located. Former chemical storage vaults located on the southeast side of the prison between the new boiler house and Surplus Properties would also be a target;
- Potential soil impact from unknown sources of backfill materials located in five locations in and around the prison. The first location is the current Administration Building and Garage Facility. The second location is outside the southeast prison wall along East Capital Drive. The third location is the terrace slope where the new boiler house is located. The fourth location is along the bluffs next to the former Lard house and Potato House. The fifth location is a soil hill trending northwest/southeast between the upper and lower playing fields.

Recognized environmental conditions relate to possible environmental impacts associated with historic land use and practices, and potential sources of environmental impacts associated with the existing building and/or current site practices.

Asbestos and lead-based paint inspections of existing structures must be performed by Missouri licensed inspectors. These inspections are required by federal, state and local regulations prior to disturbance of these structures. Environmental soil borings may be necessary for the subject property in the areas topographically lower or equal to former UST and AST sites; current and former industrial site locations within the prison; the former chemical storage vaults outside the prison; and the five backfill locations in and around the prison to determine if any environmental impact exists.



## 1.0 Introduction

---

### 1.1 Purpose

The purpose of this environmental site assessment is to address potential environmental concerns of the subject property by reviewing past usages of the subject property and adjacent properties, identifying recognized environmental conditions (RECs), and assessing the environmental impact of the RECs on the subject property. RECs are defined in ASTM E 1527-00 as “the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property.” An additional purpose of this ESA is to address the relevance of the identified RECs to the subject property’s future development.

### 1.2 Methodology

This environmental site assessment was conducted in accordance with the ASTM Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM E 1527-00. The Phase I ESA activities consist of:

- Records Review
- Site Reconnaissance
- Interviews
- Documentation

The conclusions included in this report were prepared with the understanding that the sites may be redeveloped in the near future.



## 2.0 Site Description

---

### 2.1 Location and Legal Description

The subject properties occupy approximately 150+ acres in Cole County, Missouri. The main prison is bounded by; East State Street, Lafayette Street, and East Capitol Avenue to the east; Dulle and Hampton Towers to the north; Union Pacific and Missouri River to the west; and the Missouri Department of Surplus Properties to the south. The Missouri Department of Surplus Properties is located on the Jefferson City Correctional Facility property and a Phase I Environmental Site Assessment (ESA) was performed by TSi Engineering June of 2001. The Missouri Department of Surplus Properties Phase I ESA report is presented in this report as Appendix A. The subject property consist primarily of grass and tree covered lots, asphalt and concrete lots, and limestone and brick buildings with concrete basements. Concrete sidewalk, streets, alleys, yards, and several underground utilities surround the subject property. The location of the subject property is shown in Figure 1, Topographic and Site Plan.

### 2.2 Site and Vicinity

The subject property is a prison facility with associated housing units, factories, and administrative buildings surrounded by several residential neighborhoods and light commercial businesses. The site is located on a bluff, over looking the Missouri River. The bluff slopes towards the river to the northeast with inter-tonguing ravines between summits.

### 2.3 Site Improvements

Due to the age of the facility, many changes in buildings and area of the prison have occurred. There have been several expansions to the prison site most notably expansions to the north and to the south. These expansions include demolition or pre-existing structures and construction of new buildings. Currently, the site consists of asphalt and concrete sidewalks and parking lots, paved streets, multistory brick and concrete buildings and underground utilities.

### 2.4 Current Uses of Property

The subject property is primarily a prison and prison support facilities.

### 2.5 Past Uses of the Property

The subject property has been used as a prison since the 1830's.



## 2.6 Current and Past Uses of Adjoining Property

### 2.6.1 Current Uses of Adjoining Property

The current uses of adjoining property consist of a mix of residential and commercial. There are also designated wetland areas along the Missouri River northeast of the prison between the riverbank and the Union Pacific Railroad.

### 2.6.2 Past Uses of Adjoining Property

According to the historical research, there has been little change in the uses of the adjoining property. The area has remained primarily residential and commercial. The International Shoe Factory was previously in operation south of the prison.

## 2.7 Site Physical Setting

### 2.7.1 Topography

The subject property is located on bluffs overlooking the Missouri River approximately 540 to 660 feet above sea level. A site topographic map is presented in Figure 1, Topographic and Site Plan.

### 2.7.2 Soil and Geology

Soil characteristics of the area are variable. The predominant soil type at the subject property is a silty clay to clay soil. The subject property is located on dolomite of the Paleozoic Era, Ordovician System, Canadian Series. These formations gently dip toward the north-northeast.

### 2.7.3 Groundwater and Surface water

Surface runoff is controlled primarily by the storm sewer system. Groundwater levels and flow vary due to influences of surface water flow and soil/rock type. The subject property is located on the high bluff area between two intermittent creeks flowing south to north on the northeast side of the property and on the southwest side of the property respectively. The Missouri River flows west to east on the northeast side of the prison. There are water supply wells located on prison property southeast of the prison.



### 3.0 Records Review

---

#### 3.1 Environmental Record Sources

Environmental Data Resources, Inc. (EDR) was subcontracted to search available environmental record databases. The results of the environmental record database search are presented in a report titled The EDR – Radius Map with GeoCheck®, Jefferson City Correctional Facility, 631 East State Street, Jefferson City, MO 65101, Inquiry No: 708648.5s, prepared for TSi Engineering, Inc. and dated November 29, 2001. The distances used for searching the environmental record databases are in accordance with American Society for Testing and Materials (ASTM) Standard Practice for Environmental Site Assessments, ASTM E 1527-00.

##### 3.1.1 EDR Environmental Database Search

The following federal and state agency databases were searched and reviewed for evidence of any potential environmental contamination issues, such as incidents or facilities that may have affected the environmental integrity of the subject property:

- National Priority List (NPL) – 1 mile search radius
- State Hazardous Waste Sites – 1 mile search radius
- Resource Conservation and Recovery Act (RCRA) Corrective Action Activity (CORRACTS) – 1 mile search radius
- Superfund (CERCLA) Consent Decrees (CONSENT) – 1 mile search radius
- Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) – ½ mile search radius
- State Landfill – ½ mile search radius
- Resource Conservation and Recovery Act Transportation, Storage and Disposal (RCRA-TSD) – ½ mile search radius
- Leaking Underground Storage Tank (LUST) – ½ mile search radius
- Underground Storage Tank (UST) – ¼ mile search radius
- RCRIS Small Quantity Generator (RCRIS-SQG) – ¼ mile search radius
- RCRIS Large Quantity Generator (RCRIS-LQG) – ¼ mile search radius
- Delisted NPL Sites – Target Property
- CERCLA No Further Remedial Action Planned (CERC-NFRAP) – Target Property
- Above-ground Petroleum Storage Tanks (AST) – Target Property



- RCRA Administrative Action Tracking System (RAATS) – Target Property
- Hazardous Materials Information Reporting System (HMRIS) – Target Property
- PCB Activity Database System (PADS) – Target Property
- Emergency Response Notification System (ERNS) – Target Property
- Facility Index System (FINDS) – Target Property
- Toxic Chemical Release Inventory System (TRIS) – Target Property
- NPL Liens (NPL Lien) – Target Property
- Toxic Substance Control Act (TSCA) – Target Property
- FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) /TSCA (Toxic Substance Control Act) Tracking System (FTTS) – Target Property
- Material Licensing Tracking System (MLTS) – Target Property
- Certified Hazardous Waste Resources Recovery Facilities (MO RRC) – Target Property

3.1.2 Summary of EDR Environmental Database Search Results

The subject property was identified in the EDR Environmental Database search. Several surrounding property were identified within the ASTM specified search distances from the subject property. A listing of database search findings is presented below.

Database Searched	Search Distance (Miles)	Facilities Located
UST	¼	12
LUST	½	10
RCRIS-SQG	¼	7
FINDS	Target Property	1
FTTS	Target Property	1
Orphan Site	¼	3



Discrepancies between the information provided by government agencies and EDR may exist due to incomplete or non-updated databases of either resource. In addition, facilities may be listed in more than one category on the environmental screening report. A summary of the EDR sites identified within the above listed search distances follows.

UST (12 sites)

- Jefferson City Correctional Center, 631 State Street, Jefferson City, Missouri 65101. This site is the subject property. Three tanks have been removed. The subject property is not listed as a LUST property.
- SIPI's 66, 801 East High Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile south-southwest of the subject property. Two tanks are currently in use.
- Former Medical Arts Building, 515 East High Street, Jefferson City, Missouri 65101. This property is located 0 to ¼ mile west of the subject property. One tank has been removed.
- Buescher Memorial Hone, 429 East Capitol Avenue, Jefferson City, Missouri 65101. This property is located 0 to ¼ mile west-northwest of the subject property. One tank has been removed.
- Hocker Oil Company, 501 East McCarty Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile west-southwest of the subject property. Three tanks are currently in use and four tanks have been permanently closed in place.
- Jefferson City Station, 301 State Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile northwest of the subject property. Two tanks have been removed.
- Phillip's 66/Pump Handle Snack Shop, 510 Cherry Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile south-southwest of the subject property. Two tanks have been removed.



- Turner’s Conoco, 401 East McCarty Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile west of the subject property. Three tanks have been removed.
- Central Maintenance Garage, 830 East Miller Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile south-southwest of the subject property. Four tanks are currently in use and one tank has been removed.
- Al’s Tire Service, 1015 East McCarty Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile south of the subject property. Four tanks are reported removed.
- Cole County Courthouse, 301 East High Street, Jefferson City, Missouri 63101. This site is located 0 to ¼ mile west-northwest of the subject property. One tank is currently in use.
- State of Missouri Surplus Property, 117 Riverside Drive, Jefferson City, Missouri 63102. This site is located 0 to ¼ mile east-southeast of the subject property. Two tanks have been removed.

**LUST (10 sites)**

- Former Medical Arts Building, 515 East High Street, Jefferson City, Missouri 65101. This property is located 0 to ½ mile west of the subject property. There was a release reported at this facility on 8/25/92. Remedial technique was reported as excavation. Spill cleanup began on 8/25/92 and ended on 10/12/95.
- Hocker Oil Company, 501 East McCarty Street, Jefferson City, Missouri 65101. This site is located 0 to ½ mile west-southwest of the subject property. There was a release reported on 4/8/92. The remedial technique was reported as excavation. Soil was listed as the contaminated media. Spill cleanup started on 4/8/92 and ended on 5/27/99.
- Jefferson City Station, 301 State Street, Jefferson City, Missouri 65101. This property is located 0 to ½ mile northwest of the subject property. There was a release reported on 10/23/96. Excavation, tank closure, and monitoring were the remedial techniques listed. Soil and groundwater were listed as the contaminated media. Spill cleanup began on 10/23/96 and ended on 11/03/96.
- Central Maintenance Garage, 830 East Miller Street, Jefferson City, Missouri 65101. This site is located 0 to ½ mile south-southwest of the subject property. There was a release reported on 12/13/94. Excavation was the remedial technique listed. Soil was listed as the contaminated media. Spill cleanup began on 12/13/94 and ended on 5/22/95.
- Al's Tire Service, 1015 East McCarty Street, Jefferson City, Missouri 65101. This site is located 0 to ½ mile south of the subject property. There was a release reported on 1/01/88. Excavation, tank closure, and landfill were the remedial techniques listed. Soil was listed as the contaminated media. Spill cleanup and completion dates were not provided.
- State of Missouri Surplus Property, 117 Riverside Drive, Jefferson City, Missouri 63102. This site is located 0 to ½ mile east-southeast of the subject property. There was a release reported on 7/2/93. Excavation was listed as the remedial technique. Spill cleanup began on 7/2/93 and ended on 12/15/93.
- Sprint, 319 Madison Street, Jefferson City, Missouri 65101. This site is located 0 to ½ mile west-northwest of the subject property. There was a release reported on 6/13/94. Excavation was listed as the remedial technique. Spill cleanup began on 7/27/94 and ended on 11/3/94.



- Jefferson State Office Building, 205 Jefferson, Jefferson City, Missouri 65102. This site is located 0 to ½ mile west-northwest of the subject property. There was a release reported on 8/24/98. Excavation and tank closure were the remedial techniques listed. Soil and groundwater were listed as the contaminated media. Spill cleanup began on 10/1/98 and no completion date was provided.
- Central Education Facility, 214 East Miller Street, Jefferson City, Missouri 65102. This site is located 0 to ½ mile west of the subject property. There was a release reported on 2/1/94. Excavation was the remedial technique listed. Spill cleanup began on 2/15/94 and ended on 5/6/94.
- Fill and Wash, Clark and Elm, Jefferson City, Missouri 65101. This site is located 0 to ½ mile south of the subject property. There was a release reported on 5/18/94. Site characterization was listed as the remedial technique. Groundwater was listed as the contaminated media. Spill cleanup began on 4/30/97 and ended 4/5/2000.

RCRIS-SQG (7 sites)

- Jefferson City Correctional Center, 631 State Street, Jefferson City, Missouri 65101. This site is the subject property. Two violations were reported on 2/9/90.
- Jefferson City Central Maintenance Center, 820 East Miller Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile south-southwest of the subject property. No violations were reported.
- News Tribune Company, 210 Monroe Street, Jefferson City, Missouri 65102. This site is located 0 to ¼ mile west-northwest of the subject property. No violations were reported.
- Al's Tire Service, 1015 East McCarty Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ south of the subject property. No violations were reported.
- Missouri Bar Print, 326 Monroe, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile west-northwest of the subject property. No violations were reported.



- City of Jefferson City, 320 East McCarty Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile west of the subject property. One violation was reported on 6/24/88.
- Firestone Tire and Rubber Company, 406 Monroe Street, Jefferson City, Missouri 65101. This site is located 0 to ¼ mile west of the subject property. No violations were reported.

**FINDS (1 site)**

- Jefferson City Correctional Center, 631 State Street, Jefferson City, Missouri 65101. This site is the subject property. This report identified pertinent environmental activity at the site with Facility Registry System, National Compliance Database, Resource Conservation and Recovery Act Information System, and Section Seven Tracking System. Details of any information found on the site were not provided.

**FTTS (1 site)**

- Jefferson City Correctional Center, 631 State Street, Jefferson City, Missouri 65101. This site is the subject property. This report indicated proposed penalties and a close out date of 6/3/91. Violations were listed as PCB storage and disposal.

**Orphan site (3 sites)**

- Delong's, East Capitol Avenue, Jefferson City, Missouri 65101. This site was classified as a UST. Information on the address location and activities on the site was not provided.
- SS 5634, 507 McCarty Street, Jefferson City, Missouri 65101. This site was classified as a UST. Information on activities on the site was not provided.
- Mo Highway and Transportation Dept., East McCarty Street, Jefferson City, Missouri 65101. This site was classified as a LUST. Information on the address location and activities on the site was not provided



Based on the findings of the database review, REC's were noted for the subject property in the form of lists previously located on site and violations associated with PCB's storage and disposal. Additionally, the prior LUST listing for the adjoining and up gradient State of Missouri Surplus Property is a REC. None of the other database listings appear to be a REC based on distance, groundwater gradient, and/or closure status.

### 3.1.3 Environmental Assessment Reports

The property owner indicated that no previous Phase I ESA was performed on the subject property. There were two sites which received five violations from the Missouri Department of Natural Resources (MDNR) in February of 1990 for EPA regulations. One site was located near to the northwest area of the Gas Chamber. Violations in this area were associated with waste disposal of Potassium Cyanide and Sulfuric Acid after executions. Analytical results of soil borings in the area revealed little to no impact from the storage of these chemicals. The other site was located at the old dumpsite on the bluffs near to the Potato House. Violations were associated with hazardous chemical drums, which were found. Analytical results of soil borings in the area indicated little to no impact from the chemicals.

## 3.2 Aerial Photographs

Aerial photographs were obtained and reviewed for the subject property and surrounding areas for the years 1961, 1965, 1970, 1980, 1989, and 1995.

### 3.2.1 1961 Aerial Photograph Review

The subject property appeared to be consistent with present day structures inside the prison with the exception of the Chapel and the Maximum Security Building. The interior wall (former exterior prison wall) of the prison is present. The property adjoining to the northwest is tree and grass covered with part of the area used for parking. Three residential structures are present to the northwest. The area to the southeast near the water tower is tree and grass covered and may have been used for farming. Southwest of the prison wall is primarily residential homes. There are three AST tanks located northeast of the Diesel Plant and four silo structures south of the Old Boiler Plant.

### 3.2.2 1965 Aerial Photograph Review

The area near to the water tower appears to be developed with buildings and parking lots. There appears to be debris in and around the Slaughter House and the Incinerator.



### 3.2.3 1970 Aerial Photograph Review

The interior wall of the prison is gone. An additional structure has been added to the north of the garage facility. Additional buildings have been added to the development to the southeast near the water tower. There appears to be debris along the bluff northeast of the Potato House.

### 3.2.4 1980 Aerial Photograph Review

The Chapel appears for the first time in the prison. Additional buildings have been added to the development to the southeast near the water tower. The Dulle & Hampton Towers appear on the property to the northwest.

### 3.2.5 1989 Aerial Photograph Review

The Maximum Security Building appears for the first time. The New Boiler Plant is present outside the southeast wall with two AST tanks associated with the building. The three residential houses near the prison property are no longer present and the area is now a parking lot

### 3.2.6 1995 Aerial Photograph Review

There were no significant changes observed in this photograph.

## 3.3 Local Directories

Polk and Haines directories are in the process of being reviewed. A summary of the review will be presented in Table 1 as this information is made available.

## 3.4 Local Zoning/Land-Use Records

The city zoning office was contacted for current zoning/land use of the subject property. The subject property is zoned RS-1 which represents residential single.

## 3.5 Sanborn Maps

Sanborn maps were obtained and reviewed for the subject property and surrounding areas for the years 1885, 1892, 1898, 1908, 1916, 1923, 1939, 1943, 1968, and 1984.

The Sanborn map of 1885 shows the prison with approximately 20 structures. Lafayette Street goes to the river and East State Street is named East Water Street. The map shows a deep ravine approximately 50 feet north of East Water Street and approximately 100 feet west



of Lafayette Street. A quarry outline is shown inside the prison on the southeast side. Warehouses and stables are present near Lafayette Street. The surrounding area appears to have small residential structures.

The Sanborn map of 1892 shows several structures (the print shop, machine shop, clothing department, and laundry) removed from the center section of the prison. There appears to be expansion of the prison to East Main Street (now East Capitol Avenue) towards the southwest with two additional boot and shoe factory structures.

The Sanborn map of 1898 shows two additional structures in the northeast section of the prison and the addition of a cell house in the middle of the prison. The Slaughter House is shown outside the east prison wall near Chestnut Street along the river. The surrounding area is being developed as residential.

The Sanborn map of 1908 shows a boiler plant outside the prison wall on the northeast side. The female department structures have been reconstructed and an additional factory was built in the southeast section. The shoe factory south of the prison appears for the first time.

The Sanborn map of 1916 shows little change from 1908. The residential properties surrounding the prison are developing. Capitol City Water Company appears along the river north of the prison.

The Sanborn map of 1923 shows the construction of an auditorium outside the southeast prison wall. The Centennial Building and one of the factories are no longer present and three smaller buildings are shown. A T.B. Hospital is indicated near the area where the quarry was previously located. Two tanks located on the north side of the boiler plant are labeled for crude oil. The shoe factory south of the prison has expanded to the rear.

The 1939 Sanborn map shows major changes in the prison site. The prison has been expanded to the northwest and southwest with approximately 14 structures including the prison wall. The structures in the northwest expansion include the Hospital, T.B. Ward, Kitchen and Dining Hall, Administration Building, dormitory outside the wall and the Garage Facility. This expansion went over the existing Lafayette Street and over a pre-existing deep ravine. The expansion to the southeast includes the Twine Factory, "I" Housing Unit, Shoe Factory, General Storage Building, Print and Tin Shop, Dry Cleaning, and 'Death House'. The Slaughter House remains outside the east prison wall. The Female Dormitory located southeast of the prison is shown and is near to the water tower.

The Sanborn Map of 1943 shows little change from the 1939 map.

The Sanborn Map of 1968 shows major changes in prison buildings. The Auditorium, all but one building in the south upper industrial area, and the south side of the boiler plant are no longer present. Two new recreational buildings are located in the south upper industrial area. The new Chapel is located in the courtyard area between housing units 3 and 4. Four oil tanks are located on the south side of the



boiler plant. The General Storage Building is now the Soap Factory with caustic pits located on the northwest side of the building. The Twine Factory is now the License Plate Factory. The Slaughter House on Chestnut Street has been removed. A new building (potentially the isolation cell house) located on the north side of the prison is indicated but no name is provided. The residential area to the southeast has undergone further development. The Female Dormitory on the hill near the water tower is now the Officer Training Center. The northeast portion of the building has been demolished along with several support buildings nearby. The property just south of the Officer Training Center is developed for the State Agency for Surplus Property. The map shows a new oil fueled power plant located outside the southeast prison wall. Southeast of the Power Plant are three buildings identified as the Paint and Chem Vault.

The Sanborn Map for 1984 shows little change from 1968.

The Sanborn map review indicates REC's in the form of historical industrial usage, bulk fuel storage, and chemical storage on the subject property.

### 3.6 Historical Topography Maps

Historical topography maps were obtained and reviewed for the subject property and surrounding areas for the years 1942, 1967, and 1974.

The historical topography map of 1942 shows a quarry located southeast of the prison wall along the hillside near the Potato House.

The historical topography map of 1967 shows the quarry located southeast of the prison wall near the Potato House has been removed and possibly backfilled. The interior prison wall has a berm of soil where the wall was removed.

The historical topography map of 1974 shows little change.

### 3.7 Audit Check Facility Report

An EDR AuditCheck facility report was obtained and reviewed for the subject property. This report indicated that the Jefferson City Correctional Facility is listed as a hazardous waste generator (RCRIS) and has had violations reported. It also indicated the facility manages registered Underground Storage Tanks (UST). The facility is a producer of pesticides and has notified the EPA under section 7 of FIFRA (SSTS). Disinfectants produced in the Soap Factory fall under this regulation. The report indicated that the facility is listed in the EPA's index system (FINDS). It also indicates the facility has inspections under FIFRA, TSCA, or EPCRA.

Based on a review of the Audit Check facility report, the prior manufacture and usage of FIFRA regulated disinfectants is a REC.



---

## 4.0 Site Reconnaissance

### 4.1 Site Survey Process

A site reconnaissance of the subject property was conducted by TSi Engineering, Inc. on November 14, 2001. Photographs of the subject property are presented in Appendix B. The site survey summary is presented in Appendix C.

### 4.2 Hazardous Materials and Petroleum Products

Due to the age of the buildings identified, suspect asbestos containing building materials and lead-based paint may be present. The Partition Factory uses paint, adhesives, and solvents for the partitions manufactured. The Metal Working Factory uses hydraulic fluids for machinery and cutting of metal. They also use paints and coatings. The Furniture Factory uses varnish and paint for furniture manufacturing. The Soap Factory uses dry cleaning fluid and caustics in their facility. The basement of the Shoe Factory is used for bulk storage of chemicals. The graphics arts department located on the second floor uses inks, solvents, and dyes. The Garage Facility uses a variety of products for the maintenance of vehicles. The New Boiler Plant uses a variety of products to maintain the boilers. Warehouse facilities store products manufactured at the prison as well as products used in manufacturing. A summary of Material Safety and Data Sheets is presented in Appendix D. The storage and usage of the above listed chemicals and petroleum products are REC's.

### 4.3 Storage Tanks

The Soap Factory has underground storage tanks used for storing potassium hydroxide and sodium hydroxide. These tanks are currently not in use. The Garage facility has two ASTs used for fuel. The New Boiler Plant has several ASTs used to store chemicals for the boiler plant. The Warehouse Facility located on Chestnut Street has one AST for diesel fuel. The chemical and fuel tanks listed on the subject property are REC's.

### 4.4 Drums

The Partition Factory stores paints and associated chemicals throughout the plant in 55 gallon drums. The Metal Working Factory stores oils and hydraulic fluids in designated areas throughout the plant in 55 gallon drums. The drums were undamaged and not leaking. The Furniture Factory stores paints and varnishes in 5 to 10 gallon containers primarily in the paint booth. Several flammable liquid cabinets are located throughout the plant. The containers were undamaged and not leaking. The Soap Factory stores dry cleaning fluid and caustics in 55-gallon drums throughout the plant. None of the containers or drums were damaged or leaking. The Shoe Factory has bulk storage in



plastic, metal and paper drums. These were in good condition. The Garage had drums and containers of lubricants and antifreeze, none of which were leaking. The New Boiler Plant had a storage room of lubricants, solvents, and cleaners used in maintenance of the plant. These were in good condition. Warehouse facilities stored soap products made in the prison. Pallets of goods were stored in undamaged condition.

#### 4.5 Hazardous Waste

The Partition Factory, the Metal Working Factory, the Furniture Factory, the Soap Factory, the Shoe Factory, the Garage, the New Boiler Plant, and the Warehouse facilities all use and have chemicals stored in each of the facilities. Material Safety and Data Sheets summary are presented in Appendix D. The storage and usage of the above listed chemicals and petroleum products are REC's.

#### 4.6 Solid Waste

The Jefferson City Correctional facilities all use, have chemicals stored, and generate solid waste in each of the facilities. The prison maintains and secures all solid waste activities at the site. Material Safety and Data Sheets summary are presented in Appendix D. The storage and usage of the above listed chemicals and petroleum products are REC's.

#### 4.7 Wastewater

The Jefferson City Correctional facilities all use and have chemicals stored in each of the facilities. Records indicate that a discharge permit was issued to the prison and a pre-treatment facility is on the site. It is not clear whether the permit is still active and or to what extent the pre-treatment facility is being utilized. Material Safety and Data Sheets summary are presented in Appendix D. The storage and usage of the above listed chemicals and petroleum products are REC's.

#### 4.8 Drains and Sumps

The Partition Factory, the Metal Working Factory, the Furniture Factory, the Soap Factory, the Shoe Factory, the Garage, the New Boiler Plant, and Warehouse facilities had floor drains that did not have stains other than normal water stains.

#### 4.9 Stains and Pools of Liquid (Interior)

The Partition Factory, the Metal Working Factory, the Furniture Factory, the Soap Factory, the Shoe Factory, the Garage, the New Boiler Plant, and Warehouse facilities were kept clean. Any spills that occurred were attended to immediately.

#### 4.10 Pits, Ponds, Lagoons



Evidence of pits, ponds or lagoons was not observed during the site visit.

#### 4.11 Stained Soil or Pavement and Stressed Vegetation

Evidence of stained soils and stressed vegetation was not observed during the site visit.

#### 4.12 Potential PCB-Containing Electrical or Hydraulic Equipment

The Metal Working Factory has oils and hydraulic fluids. Waste oils were drummed and labeled. The Garage uses lubricants and hydraulic equipment in the maintenance of Correctional Facility vehicles. Electrical transformers were located throughout the prison and are maintained by the prison. PCB information for electrical transformers maintained by Ameren UE at or near the subject property is presented in Appendix E.



## 5.0 Interviews and Questionnaire

---

### 5.1 Owner/Tenant Questionnaire

The purpose of the questionnaire is to obtain historical background information for the site. TSi Engineering, Inc. has forwarded this questionnaire to the appropriate persons and shall submit the response as part of the final report or an addendum to the report.

### 5.2 Local Fire Department

The Jefferson City Fire Department was contacted on December 3, 2001 to assess whether the local fire department had responded to any environmental emergencies at the property. According the Administrative Secretary, the Jefferson City Fire Department has not responded to any environmental emergencies at the subject property.

### 5.3 Local Utility Company

Ameren UE was contacted by TSi Engineering, Inc. regarding the polychlorinated biphenyls (PCB) status of electrical transformers at the site and surrounding areas. The Ameren UE search indicated 32 transformers in the vicinity of the Jefferson City Correctional Facility that are filled with mineral oil and are considered PCB contaminated until tested. A copy of the letter received from Ameren UE is presented in Appendix E.



## 6.0 Findings and Conclusions

---

Based on the information readily available to TSi Engineering, Inc., the following conclusions are pertinent to the subject property.

The buildings on the subject property are over 50 years old. Due to the age of the buildings and observed building materials, asbestos-containing building (ACBM) materials and lead-based paint may be present.

In our professional opinion, the following RECs have been identified for the subject property during this assessment:

- Potential asbestos-containing building materials (ACBM);
- Potential lead-based paint (LBP);
- Potential soil and groundwater impact from UST and LUST tank removal sites at topographically equal or lower elevations to the property located at the old boiler house, Surplus Properties, the garage facility, behind the Soap factory, and the new boiler house;
- Potential soil and groundwater impact from current and historical industrial sites located in two places within the prison. The current site is located in the west section in a topographically low area of the prison. The historical industrial site is located in the east section in a topographically high area of the prison where the current upper playing fields are located. Former chemical storage vaults located on the southeast side of the prison between the new boiler house and Surplus Properties would also be a target;
- Potential soil impact from unknown sources of backfill materials located in five places in and around the prison. The first location is the current Administration Building and Garage Facility. The second location is outside the southeast prison wall along East Capital Drive. The third location is the terrace slope where the new boiler house is located. The fourth location is along the bluffs next to the former Lard house and Potato House. The fifth location is a soil hill trending northwest/southeast between the upper and lower playing fields.

Recognized environmental conditions relate to possible environmental impacts associated with historic land use and practices, and potential sources of environmental impacts associated with the existing building and/or current site practices.

- Asbestos and lead-based paint inspections of existing structures must be performed by Missouri licensed inspectors. These inspections are required by federal, state and local regulations prior to disturbance of these structures. Environmental soil borings may be necessary for the subject property in the areas topographically lower or equal to former UST's and AST's; current and former industrial site locations within the prison; the former chemical storage vaults outside the prison; and the five backfill locations in and around the prison to determine if any environmental impact exists.



7.0 Signatures of Environmental Professionals

---

This Phase I Environmental Site Assessment was conducted by the following environmental professionals in accordance with ASTM E 1527-00.

\_\_\_\_\_  
Rick Whitney  
Staff Geologist

\_\_\_\_\_  
Date

\_\_\_\_\_  
Sylvester Douglas  
Manager, Environmental Services

\_\_\_\_\_  
Date



## 8.0 Qualifications of Environmental Professionals

---

Rick Whitney  
Staff Geologist

### Professional Summary:

As a geologist, Mr. Whitney has over 15 years of experience within the geological and environmental field. His project experience includes: Phase I/II environmental assessments; preparation of work plans; asbestos investigations; feasibility studies; soil sampling; UST/AST storage tank management; and groundwater, air quality, and well placement monitoring. These services have been performed for commercial, industrial, and residential property.

### Areas of Expertise:

Subsurface Investigations  
Soil Classifications  
Groundwater Monitoring  
Asbestos and Lead Sampling  
Phase I, II and III ESA

### Education:

B.S. in Geology, University of Missouri – Columbia, 1982

Sylvester Douglas  
Environmental Group Manager

### Professional Summary:

Mr. Douglas has over 14 years of experience in every facet of asbestos management including conducting AHERA inspections, identifying asbestos-containing materials, collecting bulk samples, preparing technical specifications and architectural drawings for asbestos abatement plans, performing air monitoring, determining and enacting engineering control methods to reduce potential hazards to abatement workers and the public, and preparing final reports. His background also includes management of a phase contrast microscopy (PCM) laboratory, including development of quality control programs, design of all reporting and recordkeeping systems, and management of air monitoring technicians and field personnel.

### Areas of Expertise:

Phase I, II and III ESA  
Asbestos and Lead Surveys  
Regulatory Reviews  
Environmental Audits  
Process Safety Management Studies  
EPA Risk Assessments



Rick Whitney

Staff Geologist (continued)

Registrations/Certifications:

ACI Certified Technician, American Concrete Institute  
Certified Lead Inspector  
Certified Asbestos Inspector  
Certified Air Monitoring Technician  
OSHA 40-Hour Health and Safety Training Certification

Professional Affiliations:

Geological Society of America

Sylvester Douglas

Environmental Group Manager (continued)

Education:

B.S. in Engineering and Public Policy, Washington University, 1988

Registrations/Certifications:

MoDNR Certified Air Sampling Professional  
AHERA Inspector, MO  
AHERA Management Planner, MO  
AHERA Abatement Worker, MO  
AHERA Project Designer  
NIOSH 582 Sampling and Evaluating Airborne Asbestos Dust  
(Method 7400)  
Lead Inspector, KUVII43000-4



## 9.0 Limitations of Report

---

This report has been prepared on behalf of and for the exclusive use of the addressee, solely for use in an environmental assessment of the site. This report and the findings contained herein were prepared for Parsons HBA, Inc. expressly for their intended use of the property.

This site assessment was performed in accordance with generally accepted practices of other consultants undertaking similar studies at the same time and in the same geographical area and TSi Engineering, Inc. observed that degree of care and skill generally exercised by other consultants under similar circumstances and conditions. The findings and conclusions stated herein must be considered not as scientific certainties, but rather as professional opinions concerning the significance of the limited data gathered during the course of the environmental site assessment. No other warranty, express or implied, is made. Specifically, TSi Engineering, Inc. does not and cannot represent that the site contains no hazardous waste or material, oil (including petroleum products), or other latent condition beyond that observed by TSi Engineering, Inc. during their site assessments.

The observations described in this Report were made under the conditions stated herein. The conclusions presented in the Report were based solely upon the services described therein and not on scientific tasks or procedures beyond the scope of described services or the time and budgetary constraints imposed by the Client. Furthermore, such conclusions are based solely on site conditions and rules and regulations that were in effect, at the time of the study. The work described in this Report was carried out in accordance with the terms of contract language associated with TSi Engineering, Inc.'s contract agreement with Parsons HBA, Inc.

In preparing this report, TSi Engineering, Inc. has relied on certain information provided by state and local officials and other parties referenced herein and on information contained in the files of state and/or local agencies available to TSi Engineering, Inc. at the time of the site assessment. Although there may have been some degree of overlap in the information provided by these various sources, and attempt to independently verify the accuracy or completeness of all information reviewed or received during the course of this site assessment was not made.

Observations were made of the site and of structures on the site as indicated within the Report. Where access to portions of the site or to structures on the site was unavailable or limited, TSi Engineering, Inc. renders no opinion as to the presence of hazardous waste or material, oil or other petroleum products, or to the presence of indirect evidence relating to hazardous waste or material, oil or other petroleum products in that portion of the site or structure. In addition, TSi Engineering, Inc. renders no opinion as to the presence of hazardous waste or material, oil or other petroleum products or to the presence of indirect evidence relating to hazardous material, oil or



other petroleum products where direct observation of the interior walls, floor, roof or ceiling of a structure in a site was obstructed by objects or coverings on or over these surfaces. Unless otherwise specified in the Report, TSi Engineering, Inc. did not perform testing or analyses to determine the presence or concentrations of asbestos, radon, formaldehyde, lead-based paint, lead-in-drinking water, electromagnetic fields (EMFs), methane gas or polychlorinated biphenyls (PCBs) at the site or in the environment at the site.



The purpose of this Report was to present the results of a Phase I Environmental Site Assessment performed in substantial conformance with ASTM E1527-00 and included assessing the physical characteristics of the subject site with respect to the presence in the environment of hazardous waste or material, oil, or petroleum products, as defined in 40 CFR Parts 261, 280-281, 302, 355 and 49 CFR Part 172. No specific attempt was made to check on the compliance of present or past owners or operators of the site with federal, state, or local laws and regulations, environmental or otherwise.

It is recommended that TSi Engineering, Inc. be retained to provide further engineering services during construction and/or implementation of any remedial measures recommended in this Report. This is to allow the TSi Engineering, Inc. to observe compliance with the concepts and recommendations contained herein and to allow the development of design changes in the event that subsurface conditions differ from those anticipated.



Figures

- 1 Topographic and Site Plan



DRAINAGE  
 - STORM DRAINS

200 0 200



SCALE: 1"=200'



TOPOGRAPHIC AND SITE PLAN JEFFERSON CITY CORRECTIONAL FACILITY 631 EAST STATE STREET JEFFERSON CITY, MISSOURI			
Drawn By: EBS	Checked By: RHW		
Project No. 2000077.03	Date: 12/11/2001	Figure 1	



(BLANK)



Appendix A

State Agency for Surplus Property – Phase I Environmental Assessment (June 29, 2001), by reference only.



Appendix B

Site Reconnaissance Photographs



Truck gate northeast wall facing northwest



Area below incinerator and slaughterhouse facing south



Wastewater treatment plant facing south



Northeast wall and Union Pacific Railroad facing northwest



Abandoned incinerator facing north



Lard house facing northeast



Storage shed facing north



Abandoned slaughterhouse facing southwest



Abandoned slaughterhouse facing west



Abandoned slaughterhouse facing east



Rear of diesel plant facing southwest



Jefferson City Correctional Facility Administration Building Facing North



Fill soil bank between Upper and Lower Recreation yard Facing West



Lower Recreational yard Facing South



Lower Recreational yard Facing SouthEast



Drainage culvert along Lower recreation yard



Soil bank between partition factory and school facing North



Drainage South side of partition factory



Soil bank between lower recreation yard and partition factory facing East



Walkway to gas chamber facing East



Inside gas chamber



Gas chamber vent system



Front of gas chamber facing East



Steam lines between partition factory and metal plant facing North



Empty drum storage behind partition factory facing West



Steam lines between partition factory and metal plant facing West



Partition Factory construction plaque facing South



Area between metal Factory and East wall facing North



Pipe insulation Metal Factory



Pipe insulation Metal Factory



Duct Wrap on vents Metal Factory



Drum storage Metal Factory



Drum storage Metal Factory



Drum storage Metal Factory



Metal Factory floor and plate storage



Metal Factory floor and Box and pallet storage



Metal Factory water discharge between Metal Factory and I-Hall facing SouthWest



I-Hall (abandoned) facing North



Industry Warehouse facing North



Steam lines between M&M and warehouse facing West



Steam lines going into old boiler house facing NorthWest



Empty drum storage behind warehouse facing East



Steam lines over top of furniture factory facing North



Furniture Factory



Furniture Factory piping



Furniture Factory transformer on South side of building



Furniture Factory water discharge on South side of building



Furniture Factory



Furniture Factory Paint Booth



Furniture Factory Paint Storage



Furniture Factory Paint Booth



Furniture Factory Equipment



Furniture Factory Storage



Furniture Factory Pump



Loading bin and utility lines West side of Furniture Factory



Soap Factory equipment



Soap Factory piping and insulation



Soap Factory drum storage-dry cleaning area



Soap Factory dry clean area



Soap Factory 2<sup>nd</sup> floor



Soap Factory equipment



Soap Factory mixing vat



Soap Factory mixing vat



Soap Factory drum storage



Soap Factory drum storage



Soap Factory lab



Soap Factory lab



Soap Factory lab



Soap Factory lab



Soap Factory lab



Area between Soap Factory and boiler house facing west



Soil along North side old boiler house facing South west



Inside old boiler house



Inside old boiler house



Inside old boiler house



Inside old boiler house



Inside old boiler house



Covers over water main valve



Area behind Soap Factory facing North



Underground storage for NaOH and POH behind Soap Factory not in use



Area between Shoe Factory and North wall



Water main piping in tunnel



Inside Shoe Factory-Garment Manufacturing



Inside Shoe Factory-Garment Manufacturing



Basement storage Shoe Factory



Basement storage Shoe Factory



Basement storage Shoe Factory



Basement storage Shoe Factory



Basement storage Shoe Factory



Basement piping Shoe Factory



3<sup>rd</sup> floor Shoe Factory graphic arts storage



3<sup>rd</sup> floor Shoe Factory graphic arts storage



Area between Shoe Factory and H.U.5C facing North



Chapel and H.U.4 facing East



Area between H.U.4 and H.U.5C facing East



Tunnel next to H.U.3 piping



Tunnel next to H.U.3 piping insulation



Tunnel next to M&M piping insulation



Tunnel next to M&M piping insulation



Tunnel next to H.U.1 piping insulation



Tunnel next to H.U.1 piping insulation



Upper recreation yard facing South



Upper recreation yard facing South



Upper recreation yard facing East



AST at Garage facing West



AST at Garage lower area facing North



Front of Salley Port facing North



Rear of Garage facing West



Inside Garage




Inside Garage



Inside Garage



Inside new Boiler Plant



Inside new Boiler Plant



Inside new Boiler Plant Storage Area



Inside new Boiler Plant Lab



Inside new Boiler Plant



Inside new Boiler Plant



Inside new Boiler Plant Machine Shop



Rear new Boiler Plant facing North



AST Tanks next to New Boiler Plant facing North



Manhole water discharge (unknown source) East of New Boiler Plant



AST next to Industries warehouse facing East



Inside Industries warehouse



Inside Industries warehouse



Inside Industries warehouse



Steam lines, fill soil, and manhole behind new Boiler Plant facing East



Dulle and Hamilton Tower facing North



505 East State Street-Hamilton Nutritional Center facing North



520 East State Street-Shryack-Hirst Grocery Co. facing SouthWest



520 East State Street-Shryack-Hirst Grocery Co. facing SouthWest



Prison parking lot facing East



Drainage area behind Prison parking lot facing North



Side of 100 Lafayette and 620-622 East State Street facing West



100 Lafayette Street facing West



102-110 Lafayette Street facing North



636 East Capitol Avenue (vacant) facing north



621 and 619 East Capital – State Tax Division and Division of Administration Support respectively, facing northwest



624 East Capitol facing southwest



700 East Capitol facing south-Capitol Center Law Office



700 East Capitol facing southwest-Capitol Center Law Office



712-722 East Capitol facing west



West Prison wall on Lafayette facing North



South Prison wall on East Capital facing East



728 East Capitol Street facing SouthWest



201 Cherry Street at corner of Cherry and East Capitol facing South



South Prison wall on East Capitol Street facing East



802, 810, 812 East Capitol Street facing West



Low area behind 200 Chestnut Street facing West



East Prison wall facing North



901 East Capitol Street facing East



201 Chestnut Street facing SouthEast



200 Chestnut Street facing SouthWest



Rear lots of 901-913 East Capitol Street facing SouthEast



Drainage area East side Chestnut behind 901-913 East Capitol facing East



911 and 913 East Capitol facing North



Vacant lot 200 Ash Street facing West



201 Ash Street Apartments facing South



1002 East Capitol Street Apartments facing SouthWest (same building as 201)



Parking lot behind Apartment building facing South



Drainage area West of former International Shoe Factory facing NorthEast



1003 and 1005 East Capitol Street facing NorthEast



Drainage area behind 1003 and 1005 East Capitol facing East



Drainage area behind 1003 and 1005 East Capitol facing NorthEast



Drainage area behind 1003 and 1005 East Capitol facing North



1101 East Capital former International Shoe Factory facing NorthEast



MDNR Compost behind new Boiler House facing SouthEast



Appendix C

Site Survey Summary Form

## Site Survey Summary

Address: 631 East State Street  
Jefferson City Correctional Facility

Description of Site: State Prison site since ~1835. Manufacturing  
of Soap, Furniture, Metal license plates, Partitions, Graphic  
arts Printing, and Garments. Houses maximum security  
State prisoners.

1. Is the Property or any adjoining property used for an industrial, commercial or manufacturing use?

	<u>Land Use</u>	<u>Photograph?</u>
Property:	Prison	✓
Adjoining Properties North:	Union Pacific RR	
Adjoining Properties South:	Residential + light Commercial	✓
Adjoining Properties East:	Surplus Properties + Residential	✓
Adjoining Properties West:	Residential + light Commercial	✓

1

2. Has the Property or any adjoining property been used for an industrial, commercial or manufacturing use in the past?

	<u>Owner</u>	<u>Use</u>	<u>Dates</u>
Previous Use of Property	Prison	Manufacturing	Upper Rec area before 1954
Previous Use of Properties to North			
Previous Use of Properties to South			
Previous Use of Properties to East			
Previous Use of Properties to West			

3. Is there evidence that there are currently, or have been previously, any pesticides, automotive or industrial batteries, paints, or other chemicals stored on or used at the Property or at the facility other than undamaged containers of consumer products of under five gallons in total volume?

Finding: 55 gallon Drums of paint, Lubricants, Hydraulic fluid, Cleaning Supplies (Dry Cleaning fluid)

Source: Site Visit

4. Is there evidence that there are currently, or have been previously, any industrial drums (typically 55-gallon) or sacks of chemicals located on the Property or at the facility?

Finding: 55 gallon Drums + Sacks of supply chemicals are stored in and around Manufacturing area

Source: Site Visit

5. Is there evidence that fill dirt has been brought onto the site which originated from a contaminated site or of an unknown origin?

Finding: Fill Dirt along removed Prison wall, Fill Dirt around New Boiler house area, Fill Dirt along East Capitol Street out Side of wall  
Source:

6. Is there evidence that there are currently, or have been previously, any pits, ponds or lagoons located on the Property in connection with waste treatment or waste disposal?

Finding: Pondered storm water in area South of New Boiler house was being Pumped  
Source:

7. Is there evidence that there is currently, or has been previously, any stained soil or stressed vegetation on the Property?

Finding: No evidence  
Source:

8. Is there evidence that there are currently, or have been previously, any registered or unregistered storage tanks (above or underground) located on the Property?

Finding: There are 2 AST's by garage facility, 4 AST's around New Boiler house. UST's removed from garage area. UST's removed from New Boiler house  
Source:

9. Is there evidence that there are currently, or have been previously, any vent pipes, fill pipes or access ways indicating a fill pipe protruding from the ground on the Property or adjacent to any structure located on the Property?

Finding: No evidence  
Source:

10. Is there evidence that there are currently, or have been previously, any flooring, drains, or walls located within the facility that are stained by substances other than water or are emitting foul odors?

Finding: *Paint Booth in Furniture Shop*

Source:

11. Is there evidence that the Property is served by a private well or non-public water system, and if so, has the well or system been designated as contaminated by any governmental environmental/health agency?

Finding: *Water Tower has previously served as private water for prison.*

Source:

12. Does the owner of the Property or operator of the facility have any knowledge of environmental liens or governmental notification relating to past or current violations of environmental laws with respect to the Property or any facility located on the Property?

Finding: *N/A*

Source:

13. Has the owner of the Property or operator of any facility at the Property been informed of any past or current existence of hazardous substances or environmental violations with respect to the Property or any facility located on the Property?

Finding: *None to the knowledge of the staff*

Source:

14. Does the Property owner or facility operator have any knowledge of any environmental assessment of the Property or facility that indicated the presence of hazardous substances on the site or recommended further assessment of the Property?

Finding: *No Knowledge from Staff*

Source:

15. Does the owner of the Property or any operator of a facility at the Property know of any past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any hazardous substance involving the Property by any owner or tenant of the Property?

Finding: *N/A*

Source:

16. Is there evidence that the Property discharges wastewater, other than storm water, directly to a ditch, stream, septic system, or sump on or adjacent to the Property?

Finding: *No evidence*

Source:

17. Is there evidence that any construction debris, substances identified as hazardous, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials, trash, debris or refuse been dumped above grade, buried and/or burned on the site?

Finding: *Old Boiler house has asbestos + Lead Paint. No evidence of debris, trash or open burning*

Source:

18. Is there evidence of any electrical or hydraulic equipment (such as compressors, transformers and large capacitors), now on the site or that have been on the site in the past, known to contain PCBs? If so, describe the equipment, identify its location, approximate dates of use of the equipment, and whether it has been registered as PCB containing material, and actual knowledge of leaks.

Finding: Possible Building Debris from The 1954 Prison riot may be in Fill areas and may contain electrical/hydraulic equipment  
No surface evidence of material

Source:

19. Is there evidence that equipment containing PCBs has been removed? If so, obtain the approximate dates of removal, location removed from, and name of the removal contractor.

Finding: No evidence

Source:

20. Is there evidence that there have been any fires on the Property involving PCBs? If so, describe and provide the dates(s) of the occurrence and remediation methods.

Finding: No Knowledge of fires involving PCB's or Electrical/hydraulic equipment

Source:

This Site Survey Summary Was Completed By:

Name: Rick Whitney Title: Staff Geologist  
Firm: TSI Date: 11/14/01  
Address: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Preparer represents that to the best of the Preparer's knowledge the above statements and facts are true and correct and that to the best of the Preparer's knowledge no material facts have been suppressed or misstated.

Signed:  Date: 11/14/01



Appendix D

Material Safety Data Sheet Summary

JCCC Raw Materials MSDS

FD & C yellow #5	Kathon CG/ICP preservative
Eastman DE-HG Solvent	Rhodamine 6GDN Extra
TBEP (Tributoxyethyl phosphate)	Isopropanol
Ammonia Hydroxide	Bio-Soft S-100
Blankophor (Stilbene optical brightner)	Bio-terge 804
Meto pentabead 20	Stepanol ABHS-15C
Acusol 445ND polymer	Bio-Soft LD-95
Sodium Perborate	Sodium Orthosilicate
Methyl Salicylate	Ethylene Glycol
10% Antifoam emulsion	Sulfochem B-209
Pylaklor acid blue LX-9738	ACL 56
Pylaklor sea green S-432	Valfor ® zeolite
Pylaklor brilliant blue S-566	Monosodium Phosphate
TEXANOL ester alcohol	Sodium Bicarbonate
FC-120 Fluorad brand fluorchemical surfactant	Metso beads 2048 sodium Metasilicate
Zonyl FSJ fluorosurfactant	Sipernat 22S
RHOPLEX B-60A emulsion	Sodium Tripolyphosphate
RHOPLEX B-85 emulsion	Tetrapotassium pyrophosphate
Duraplex 2 emulsion	Ninol 40-CO
Glycol ester DESG	Mercol
Concentrated Deodorant fragrance	Diethanolamine
Rosin ester solution	Soda ash
Dowper solvent (perchloroethylene)	Morpholine
Primfix resin	Triethanolamine
BTC 1010	Lemon fragrance
Stepan SXS	Sodium Sulfate
Tergitol NP-9 Surfactant	Urea
BTC 2125M P40	FB Sodium Percarbonate
Arosurf TA-100	Sun ripened raspberry fragrance
SO/SAN 30M	Nacconol 40G
Shellflex ® 1210	T DET N 14
Carboxymethyl Cellulose	Butyl cellosolve solvent
Sokalan ® PA 30	Pantene type fragrance
Cedephos FA-800	Tide w/ bleach
Sodium Silicofluoride	Pine oil disinfectant
Sodium Silicate	
Ban Soap	
Caustic Potash – liquid	
Versene 100 chelating agent	
Caustic Soda	
Poly emulsion 43 N 40	
Ploy emulsion 371N35	
Michem emulsion 80540	
Antapox BL-225 surfactant	
IGEPAL DM 970 Flakes	
Makon NF-5	

## JCCC Finished Goods MSDS

All purpose cleaner  
Neutral floor cleaner  
Window and mirror cleaner  
High speed burnishable floor finish  
Floor finish  
Floor sealer  
Heavy duty floor cleaner  
Polymer floor stripper  
Dust mop treatment  
Pine oil disinfectant  
Special deodorant  
Disinfectant and sanitizer 205M 7.5%  
Machine dishwashing compound  
Hand dishwashing compound  
Rinse aid  
Pot and Pan degreaser  
Machine dishwashing detergent  
Laundry soap compound  
Non-phosphate laundry detergent  
Automatic laundry detergent  
Break laundry detergent  
Bleach, X-tra bright chloral  
Laundry detergent with bleach  
Non-phosphate chloral bleach  
Automatic laundry detergent heavy duty  
Built soap compound tallow base  
Laundry sour  
Blue laundry sour  
Oxygen safe dry bleach  
Household fabric softener and sanitizer  
Powered fabric softener and sanitizer  
Toilet bar soap  
Liquid hand soap  
Liquid shampoo  
Liquid dishwashing soap  
Antibacterial hand soap

## JCCC Furniture Factory MSDS

Con-bond 330  
Titebond wood glue  
Dark oak stain  
Pre-cat Laquer topcoat  
Pre-cat 35 sheen  
#2 dark oak stain  
Resistovar Topcoat  
#1048 Catalyst  
Oak stain  
Sanding sealer  
Regalite (sandpaper)  
Catalyst  
Lacquer reducers (thinner)  
Ball heavy hitter cleaner  
Bates Boothcoating/Glue release  
330 green neoprene contact cement  
#1 dark oak stain  
Wood-tex face grade synthetic wood/all

JCCC License Plate Factory MSDS

Scotchlite dip tank thinners  
Kester Solder  
Bingham roller and blanket wash  
Scotchlite roll coating clear 260  
Scotchlite transparent printing ink 200  
Scotchlite roll coating thinner 270  
Toluene  
Scotchlite roll coat thinner 4905  
Scotchlite roll coat color 4806V blue  
Acetylene  
Oxygen  
Oak cool (coolant)  
Scotchlite roll coat color 4805V black  
Carbon Dioxide  
Byk-catalyst (p-toluene sulfonic acid)  
Kleer kote #6004  
Premium contact cleaner  
GVYL (Gloss vinyl)  
Scotchlite roll coat color 4815V purple  
Scotchlite clear coat thinner 746  
Reflecto-lite brand 754 clear  
Xylene

JCCC Maintenance Engineering MSDS

Polybac #1183  
5018 dual purpose sulfite indicator powder  
5015,5016 potassium iodide-iodate  
5007 phenolphthalein indicator  
5000, 5001 hardness titrating solution  
5004,5005 sulfuric acid  
5002 hardness buffer solution  
5003 hardness indicator solution  
6057 neutralizing solution  
5031 5032 bromcresol green-methyl red  
4770 cooling water treatment  
453 steamline treatment  
Caustic soda liquid  
595 oxygen scavenger  
1659 boiler compound  
1147 alkaline boil out  
Weather seal siloxane WB  
Propane  
Acetylene  
Carbon dioxide  
Helium  
DPD free chlorine reagent  
Fluorescent marking paint  
Paintstik  
Foaminator  
Dem-Kote metallic finish  
HP cleaner  
Leak detector low temp  
Blowout  
Brite Alum  
Foaming cooling coil  
No Sweat  
Argon  
Nitrogen  
Plus  
Scale remover  
TT-P-1511 Semi-gloss paint  
Spray adhesive  
Stargold C-25 shielding gas  
Argon Carbon Dioxide Helium mixture  
Oxygen  
Upper limits  
Buckeye floor sealer  
Rough tough scrubs in a bucket  
Gojo natural orange hand cleaner  
Hydrochloric acid

Qwik traffic stripe aerosol (white, yellow, blue)  
Lime-a-way  
Carbon steel electrode  
Flo-glaze cleaner  
DAP kwik foam  
Rayovac batteries  
Kester solder  
Valve action paint marker  
Coated abrasive product (sandpaper)  
"44" rosin flux solder  
CRC Contact cleaner  
Mercury (quicksilver)  
Halstead contact adhesive  
W/R Epoxy pastel base  
Silicon Carbide abrasive (sandpaper)  
Aluminum Oxide grinding wheel  
Aluminum Grease  
LPS heavy duty Silicone lubricant  
Makon NF-5  
LPS themaplex hi-temp grease  
LPS 2 industrial strength lubricant  
Silicone aerosol  
Beat the nails (adhesive)  
Plumber pipe dope  
Poly temp VSP (TFE Valve Stem Pack)



38. DYE SOLVENT	HOBBIE CRAFT
39. DYE, OIL	HOBBIE CRAFT
40. DYE, SPIRIT	HOBBIE CRAFT
41. DYE, SPRAY	HOBBIE CRAFT
42. DYE, THINNER	HOBBIE CRAFT
43. FILLER, WOOD	HOBBIE CRAFT
44. FINISH, LIQUID	HOBBIE CRAFT
45. FINISH, SPRAY	HOBBIE CRAFT
46. GLUE, LIQUID	HOBBIE CRAFT
47. GLUE, SPRAY	HOBBIE CRAFT
48. LACQUER THINNER	HOBBIE CRAFT
49. LACQUER, LIQUID	HOBBIE CRAFT
50. LACQUER, SPRAY	HOBBIE CRAFT
51. MINERAL SPIRITS	HOBBIE CRAFT
52. PAINT, LIQUID	HOBBIE CRAFT
53. PAINT, SPRAY	HOBBIE CRAFT
54. POLISH, WOOD, SPRAY	HOBBIE CRAFT
55. PRIMER	HOBBIE CRAFT
56. RETARDER, PAINT	HOBBIE CRAFT
57. SEALER, WATER	HOBBIE CRAFT
58. SEALER, SANDING WOOD	HOBBIE CRAFT
59. SEALER, SANDING, SPRAY	HOBBIE CRAFT
60. SILICONE SPRAY	HOBBIE CRAFT
61. STAIN, WOOD	HOBBIE CRAFT
62. THINNER, PAINT	HOBBIE CRAFT
63. TULONAL	HOBBIE CRAFT
64. URETHANE, LIQUID	HOBBIE CRAFT
65. URETHANE, SPRAY	HOBBIE CRAFT
66. VARNISH, LIQUID	HOBBIE CRAFT
67. VARNISH, SPRAY	HOBBIE CRAFT
68. WAX, LEATHER	HOBBIE CRAFT
69. WAX, WOOD	HOBBIE CRAFT
70. WD-40	HOBBIE CRAFT
71. CARBITOL SOLVENT	CHEMICAL PRODUCTS
72. TRIBUTOXYETHYL PHOSPHATE	CHEMICAL PRODUCTS
73. AMONIUM HYDROXIDE	CHEMICAL PRODUCTS
74. FLOURESCENT BRIGHTNER	CHEMICAL PRODUCTS
75. HEXYLENE GLYCOL	CHEMICAL PRODUCTS
76. METHYL SALICYLATE	CHEMICAL PRODUCTS

77. ANTI FG-10 EMULSION	CHEMICAL PRODUCTS
78. TEXANOL	CHEMICAL PRODUCTS
79. FC-120 FLUORAD	CHEMICAL PRODUCTS
80. RHOPLEX B-60A EMULSION	CHEMICAL PRODUCTS
81. RHOPLEX B-85 EMULSION	CHEMICAL PRODUCTS
82. DURAPLUS 2 EMULSION	CHEMICAL PRODUCTS
83. DOWANOL	CHEMICAL PRODUCTS
84. FRESH LEMON #1356-MB, OS	CHEMICAL PRODUCTS
85. TIDE/W BLEACH	CHEMICAL PRODUCTS
86. PYLAKLOR BRILLAIANT BLUE	CHEMICAL PRODUCTS
87. FD&C YELLOW #5	CHEMICAL PRODUCTS
88. RHODAMINE 6GDN EXTRA	CHEMICAL PRODUCTS
89. PYLAKLOR ACID BLUE LX-9738	CHEMICAL PRODUCTS
90. PYLAKLOR ACID BLUE LX 7257B	CHEMICAL PRODUCTS
91. PYLAKLOR ACID SEA GREEN S-432	CHEMICAL PRODUCTS
92. DOWPER* SOLVENT	CHEMICAL PRODUCTS
93. PINE OIL DISINFECTANT CONCENTRATE PF	CHEMICAL PRODUCTS
94. BTC 1010	CHEMICAL PRODUCTS
95. STEPANATE SXS	CHEMICAL PRODUCTS
96. TERGITOL NP-9 SURFACTANT	CHEMICAL PRODUCTS
97. GLYCOL ETHER	CHEMICAL PRODUCTS
98. AROSURF TA-100	CHEMICAL PRODUCTS
99. MINERAL SEAL OIL	CHEMICAL PRODUCTS
100. CARBOXYMETHYL CELLULOSE, SODIUM (CMC)	CHEMICAL PRODUCTS
101. RHODAFAC RA-600	CHEMICAL PRODUCTS
102. SODIUM SILICOFLUORIDE (SSF)	CHEMICAL PRODUCTS
103. HIGH TITER SOAP	CHEMICAL PRODUCTS
104. CAUSTIC POTASH, LIQUID	CHEMICAL PRODUCTS
105. VERSENE* 100 CHELATING AGENT	CHEMICAL PRODUCTS
106. CAUSTIC SODA BEADS	CHEMICAL PRODUCTS
107. POLY EMULSION 43 N 40	CHEMICAL PRODUCTS
108. MICHEM EMULSION 80540	CHEMICAL PRODUCTS
109. ANTAROX BL-225	CHEMICAL PRODUCTS
110. IGEPAL DM 970 FLAKE	CHEMICAL PRODUCTS
111. KATHON CG/ICP	CHEMICAL PRODUCTS
112. ISOPROPANOL 99%	CHEMICAL PRODUCTS
113. D.D.B.S.A.	CHEMICAL PRODUCT
114. BIOTERGE 804	CHEM/SHOE FACTORY
115. STEPHANOL ABHS-15C	CHEM/SHOE FACTORY

116.BIOSOFT LD-95	CHEM/SHOE FACTORY
117.SODIUM ORTHOSILICATE	OUTSIDE WAREHOUSE
8.LIQUID CAUSTIC SODA	CHEMICAL PRODUCTS
119.ETHYLENE GLYCOL	CHEM/SHOE FACTORY
120.SODIUM DICHLORISOCYANURATE	CHEM/SHOE FACTORY
121.VALFOR 100	CHEM/SHOE FACTORY
122.MONOSODIUM PROSPHATE	CHEM/SHOE FACTORY
123.SODIUM BICARBONATE	CHEM/SHOE FACTORY
124.SODIUM METASILICATE	CHEM/SHOE FACTORY
125.SIPERNAT 22 S	CHEM/SHOE FACTORY
126.SODIUM TRIPOLYPHOSPHATE	CHEM/SHOE FACTORY
127.TETRAPOTASSIUM PYROPHOSPHATE	CHEM/SHOE FACTORY
128.NINOL 40-CO	CHEM/SHOE FACTORY
129.MERCOL 30	CHEM/SHOE FACTORY
130.DIETHANOLAMINE	CHEM/SHOE FACTORY
131.MONETHANOLAMINE	CHEMICAL PRODUCTS
132.SODIUM CARBONATE	CHEM/SHOE FACTORY
133.MORPHOLINE	CHEM/SHOE FACTORY
134.TRITHANOLAMINE 99%	CHEM/SHOE FACTORY
135.LEMON PERFUME	CHEMICAL PRODUCTS
136.SODIUM SULFATE	CHEM/SHOE FACTORY
137.UREA INDUSTRIAL GRADE	CHEM/SHOE FACTORY
138.SODIUM PERCARBONATE	CHEM/SHOE FACTORY
139.T-DET-N-14	CHEM/SHOE FACTORY
140.BUTYL CELLOSOLVE	CHEM/SHOE FACTORY
141.TIDE W/ BLEACH FRAGRANCE	CHEMICAL PRODUCTS
142.SUPREME SALT FINES	CHEMICAL PRODUCTS
143.PINE OIL	CHEM/SHOE FACTORY
144.GILDCO PF PINE OIL DISINFECTANE CONCENTRATE	CHEM/SHOE FACTORY
145.BTC-1010	CHEM/SHOE FACTORY
146.SODIUM XYLENE SULFONATE	CHEM/SHOE FACTORY
147.NONIONIC SURFACANT	CHEM/SHOE FACTORY
148.STEPAN BTC 2125M P-40	CHEM/SHOE FACTORY
149.AEROSURF TA-100	CHEM/SHOE FACTORY
150.STEPAN SO/SAN 30M	CHEM/SHOE FACTORY
151.SHELLFLEX 2210	CHEM/SHOE FACTORY
152.SODIUM CARBOXYMETHYL	CHEM/SHOE FACTORY
153.SOKALAN PA-30 CL 45% SOLUTION	CHEM/SHOE FACTORY
154.CEDEPHOS FA 600	CHEM/SHOE FACTORY

155.SODIUM SILICOFLUORIDE	CHEM/SHOE FACTORY
156.H.T. SOAP POWDER	CHEM/SHOE FACTORY
157.LT. DRYER FLAKES	CHEM/SHOE FACTORY
158.POTASSIUM HYDROXIDE	CHEM/SHOE FACTORY
159.E.D.T.A.	CHEM/SHOE FACTORY
160.SODIUM HYDROXIDE BEADS	CHEM/SHOE FACTORY
161.EPOLENE E-43N 40%	CHEM/SHOE FACTORY
162.POLYEMULSION 371N35	CHEM/SHOE FACTORY
163.AC 325N 35%	CHEM/SHOE FACTORY
164.ANTOROX BL-225	CHEM/SHOE FACTORY
165.IGEPAL DM-790	CHEM/SHOE FACTORY
166.MAKON NF-5	CHEM/SHOE FACTORY
167.KATHON CG ICP	CHEMICAL PRODUCTS
168.ISOPROPANOL	OUTSIDE WAREHOUSE
169.CARBITOL SOLVENT	CHEM/SHOE FACTORY
170.KP-140 PLASTICIZER T-BEP	CHEM/SHOE FACTORY
171.AQUA AMMONIA	CHEM/SHOE FACTORY
172.BLAKOPHOR DML OPTICAL BRIGHTNER	CHEM/SHOE FACTORY
173.HEXELENE GLYCOL	CHEM/SHOE FACTORY
174.METHYL SALICYLATE	CHEMICAL PRODUCTS
175.ANTIFOAM	CHEMICAL PRODUCTS
176.TEXANOL	CHEM/SHOE FACTORY
177.FC-120	CHEMICAL PRODUCTS
178.RHOPLEX B-60A	CHEM/SHOE FACTORY
179.RHOPLEX B-85	CHEM/SHOE FACTORY
180.DURAPLUS 2	CHEM/SHOE FACTORY
181.DIPROPYLENE GLYCOL METHYL ETHER	CHEM/SHOE FACTORY
182.SPECIAL DEODORANT CONCENTRATE	CHEMICAL PRODUCTS
183.RESINALL 802 25%	CHEM/SHOE FACTORY
184.PERCHLOROETHYLENE	CHEM/SHOE FACTORY



Appendix E

Ameren UE Correspondence

AmerenUE  
Capital District Office

1310 Industrial Drive  
PO Box 1558  
Jefferson City, MO 65102-1558  
800.552.7583

February 8, 2002

Mr. Rick Whitney  
TSI Engineering, Inc.  
59<sup>th</sup> & Arsenal  
Building C, 2 Campbell Plaza  
St. Louis, MO 63139



**Re: Transformer Information – Jefferson City Correctional Facility, 631 East State St, Jefferson City, MO**

Dear Mr. Whitney:



This is in response to your request for information regarding the status of transformers located at or near 631 E. State St. in Jefferson City, Missouri.

Our records indicate AmerenUE owns 32 transformers in the vicinity of the adjoining addresses listed in your letter dated November 30, 2001.


These transformers are of the type filled with mineral based insulating oil. They are not filled with PCB fluid and are not defined as a PCB transformer under EPA rules. Under these rules, mineral oil transformers that have not been tested are classified as "PCB contaminated transformers." This means that since it is possible that they may have been accidentally contaminated with low levels of PCB's, they are assumed to contain 50 to 499 PPM unless tested. The term 50 PPM means 50 parts per million or 1/200 of 1%, an extremely small amount of contamination.

Although the majority of our transformers are free of PCB's, it is not uncommon to find slight levels of contamination in some, typically 50 PPM or less. We have no plans for routine testing of these transformers because of the cost and service outages that are involved. EPA does not require any special precautions with transformers of this type, and we feel that they do not present any exposure problem from a health or environmental standpoint.

We have no records of any problems with these or any other transformers at or near this site.

If you have questions concerning this matter, please advise.

Sincerely,

  
David L. Hagan, P.E.  
Supervising Engineer



## PHASE I ENVIRONMENTAL ASSESSMENT

STATE AGENCY FOR SURPLUS PROPERTY  
117 NORTH RIVERSIDE DRIVE  
JEFFERSON CITY, MISSOURI

*Prepared for:*  
*Berkebile Nelson Immenschuh McDowell Architects*  
*106 West 14<sup>th</sup> Street Suite 200*  
*Kansas City, Missouri 64105*



59<sup>th</sup> and Arsenal  
Building C  
Two Campbell Plaza  
St. Louis, Missouri 63139

June 29, 2001



Section.....	Page
Executive Summary	
1.0 Introduction.....	7
1.1 Purpose.....	7
1.2 Methodology.....	7
2.0 Site Description.....	8
2.1 Location and Description.....	8
2.2 Site and Vicinity.....	8
2.3 Site Improvements.....	8
2.4 Current Uses of Property.....	8
2.5 Past Uses of the Property.....	9
2.6 Current and Past Uses of Adjoining Property.....	9
2.7 Site Physical Setting.....	9
3.0 Records Review.....	10
3.1 Environmental Record Sources.....	10
3.2 Aerial Photographs.....	13
3.3 Local Directories.....	14
3.4 Local Zoning/Land-Use Records.....	14
3.5 Sanborn Maps.....	14
3.6 Historical Topography Maps.....	15
4.0 Site Reconnaissance.....	16



4.1 Site Survey Process.....16

4.2 Hazardous Materials and Petroleum Products .....16

4.3 Storage Tanks.....16

4.4 Drums.....16

4.5 Hazardous Waste .....16

4.6 Solid Waste .....17

4.7 Wastewater.....17

4.8 Drains and Sumps .....17

4.9 Stains and Pools of Liquid (Interior) .....17

4.10 Pits, Ponds, Lagoons .....17

4.11 Stained Soil or Pavement and Stressed Vegetation .....17

4.12 Potential PCB-Containing Electrical or Hydraulic Equipment .....17

5.0 Interviews and Questionnaire .....18

5.1 Owner/Tenant Questionnaire .....18

5.2 Local Fire Department .....18

5.3 Local Utility Company .....18

6.0 Findings and Conclusions.....19

7.0 Signatures of Environmental Professionals .....20

8.0 Qualifications of Environmental Professionals .....21

9.0 Limitations of Report.....23



Figures

- 1 Site Location and Topography (USGS)
- 2 Site Location and Topography (Detail)

Appendices

- A Site Reconnaissance Photographs
- B Site Survey Summary Form
- C MSDS Sheets
- D Ameren UE Correspondence



## Executive Summary

---

TSi Engineering, Inc. performed a Phase I Environmental Site Assessment (ESA) in June 2001 for the property known as the State Agency for Surplus Property located at 117 North Riverside Drive, City of Jefferson, Missouri (subject property). This Phase I ESA was conducted for State Agency for Surplus Property for the purpose of identifying potential recognized environmental conditions (RECs) associated with the property.

The subject property occupies approximately 8 acres in the City of Jefferson, Missouri and is bounded: to the north by the Missouri Pacific Railroad and Missouri River; to the east by additional Missouri Correctional Facility properties and Riverside Park; to the west by the Missouri State Penitentiary; and to the south by Renn Residential Neighborhood and International Shoe Factory. The subject property consists primarily of 9 major structures built of sheet metal with steel framing and supports. The Administration Building located on the property is constructed of cinder block walls and steel framing. The lots between the buildings are composed primarily of concrete. Additional gravel lots surround the facility. Tree covered hillsides and grassy areas surround the fenced area of property.

The Environmental Data Resources (EDR) database search identified seven facilities within their respective American Society for Testing Materials (ASTM) defined search distances from the subject property. One UST (Underground Storage Tank) site was located within the ¼ mile radius search of the subject property. This site was the State of Missouri Surplus Property (subject property). Two LUST (leaking underground storage tank) sites were located within ½ mile of the subject property. These two sites were State of Missouri Surplus Property (subject property) and Al's Tire Service. Two orphan sites were listed that could be within ASTM defined search distances, however, insufficient information exists on these site as to their exact location and remediation status. An orphan site by definition is a site which complete records are not available regarding location or remediation status. The two orphan sites listed were Missouri Highway and Transportation Department and Delong's, Inc.

In our opinion, the following RECs have been identified for the subject property as a result of this Phase I ESA:

- Potential asbestos-containing materials (ACM);
- Potential lead-based paint (LBP).
- Potential soil and groundwater impact from LUST tank removal on site.
- Potential soil and groundwater impact from open dumping of chemicals.
- Potential soil and groundwater impact from former firing range.
- Potential soil and groundwater impact from former landfill.



Potential ACM and LBP present at existing structures at the subject property should be inspected by U. S. Environmental Protection Agency (EPA) and State of Missouri certified and licensed inspectors. Asbestos inspections are required by federal, state and local regulations prior to any disturbance of these materials. Environmental subsurface investigations may be necessary for the subject property at locations which are at topographically lower elevations than the former LUST sites. Environmental subsurface investigations may also be necessary to properly characterize subsurface conditions for the former dumping site, the former firing range site and the former landfill site.

Recognized environmental conditions relate to possible environmental impacts associated with historic land use and practices, and potential sources of environmental impacts associated with the existing buildings and/or current site practices.



## 1.0 Introduction

---

### 1.1 Purpose

The purpose of this environmental site assessment is to address potential environmental concerns of the subject property by reviewing past usages of the subject property and adjacent property, identifying recognized environmental conditions (RECs), and assessing the environmental impact of the RECs on the subject property. RECs are defined in ASTM E 1527-00 as “the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property.” An additional purpose of this ESA is to address the relevance of the identified RECs to the subject property’s future development.

### 1.2 Methodology

This environmental site assessment was conducted in accordance with the ASTM Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM E 1527-00. The Phase I ESA activities consist of:

- Records Review
- Site Reconnaissance
- Interviews
- Documentation

The conclusions included in this report were prepared with the understanding that the sites may be redeveloped in the near future.



## 2.0 Site Description

---

### 2.1 Location and Description

The subject property occupies approximately 8 acres in the City of Jefferson, Missouri and is bounded: to the north by the Missouri Pacific Railroad and Missouri River; to the east by additional Missouri Correctional Facility properties and Riverside Park; to the west by the Missouri State Penitentiary; and to the south by Renn Residential Neighborhood and International Shoe Factory. The subject property consists primarily of 9 major structures built of sheet metal with steel framing and supports. The Administration Building located on the property is constructed of cinder block walls and steel framing. The lots between the buildings are primarily paved with concrete. Additional gravel lots surround the facility. Tree covered hillsides and grassy areas surround the fenced area of property.

### 2.2 Site and Vicinity

The subject property is located on a bluff overlooking the Missouri River. The bluff is relatively level on the top portion and slopes steeply to the west, north, and east. The site consists of the State Agency for Surplus Property (Surplus Property) and the Old Training Academy. The Surplus Property facility is comprised primarily of sheet metal buildings with steel out buildings used for warehouse storage. The Administration Building of Surplus Property is built of cinder block and steel framing. The Old Training Academy is a two-story brick building with concrete block basement walls. The structure was built in 1937 as the Women's Correctional Facility. Storm drains are located throughout the area and service the subject property.

### 2.3 Site Improvements

The subject property consists primarily of concrete, asphalt, and gravel covered lots. Some areas to the north are grass and tree covered. Minimal change has occurred on the property since the Surplus Property structures were built in the 1960's.

### 2.4 Current Uses of Property

The subject property is primarily used by Surplus Property as a storage facility for federal and state surplus goods. The Old Training Academy is used as living quarters for the guards at the state penitentiary. There are also offices for guard supervisors. The basement houses dogs used for identifying drugs.



## 2.5 Past Uses of the Property

The subject property was previously used by the Women’s Correctional Facility until approximately 1965. The Surplus Property site was used as a farm and gardens for the women inmates.

## 2.6 Current and Past Uses of Adjoining Property

### 2.6.1 Current Uses of Adjoining Property

The adjoining property to the west is the state penitentiary. The adjoining properties to the south are the International Shoe Factory and the Renn Residential Neighborhood. The adjoining property to the east is undeveloped and is owned by the state corrections office. Missouri Pacific railroad tracks and the Missouri River are located to the north of the subject property.

### 2.6.2 Past Uses of Adjoining Property

According to the historical research, past uses of the adjoining properties are consistent with the current uses.

## 2.7 Site Physical Setting

### 2.7.1 Topography

The sites are located on steeply rolling bluffs approximately 640 to 660 feet above sea level. The Missouri River borders to the north and all drainage from the site flows to the river. A site topographic map is presented in Figure 1, Site Location and Topography (USGS).

### 2.7.2 Soil and Geology

Soil characteristics of the area are predominantly silty clay to clay soil. The subject property is located on dolomite formation of the Paleozoic Era, Lower Ordovician System, Canadian Series. These formations gently dip toward the northeast.

### 2.7.3 Groundwater and Surface water

Surface runoff is controlled primarily by the storm sewer system located on the site. Groundwater levels and flow vary due to influences of surface water flow and soil/rock type. The subject property is located on the high bluff overlooking the Missouri River and surface water flows away from the property.



### 3.0 Records Review

---

#### 3.1 Environmental Record Sources

Environmental Data Resources, Inc. (EDR) was subcontracted to search available environmental record databases. The results of the environmental record database search are presented in a report titled The EDR – Radius Map with GeoCheck®, Surplus Property, 117 North Riverside Drive, Jefferson City, Missouri 65101, Inquiry No: 639486.3s, prepared for TSi Engineering, Inc. and dated June 1, 2001. The distances used for searching the environmental record databases are in accordance with American Society for Testing and Materials (ASTM) Standard Practice for Environmental Site Assessments, ASTM E 1527-00.

##### 3.1.1 EDR Environmental Database Search

The following federal and state agency databases were searched and reviewed for evidence of any potential environmental contamination issues, such as incidents or facilities that may have affected the environmental integrity of the subject property:

- National Priority List (NPL) – 1 mile search radius
- State Hazardous Waste Sites – 1 mile search radius
- Resource Conservation and Recovery Act (RCRA) Corrective Action Activity (CORRACTS) – 1 mile search radius
- Superfund (CERCLA) Consent Decrees (CONSENT) – 1 mile search radius
- Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) – ½ mile search radius
- State Landfill – ½ mile search radius
- Resource Conservation and Recovery Act Transportation, Storage and Disposal (RCRA-TSD) – ½ mile search radius
- Leaking Underground Storage Tank (LUST) – ½ mile search radius
- Underground Storage Tank (UST) – ¼ mile search radius
- RCRIS Small Quantity Generator – ¼ mile search radius
- RCRIS Large Quantity Generator – ¼ mile search radius
- Delisted NPL Sites – Target Property
- CERCLA No Further Remedial Action Planned (CERC-NFRAP) – Target Property
- Above-ground Petroleum Storage Tanks (AST) – Target Property
- RCRA Administrative Action Tracking System (RAATS) – Target Property



- Hazardous Materials Information Reporting System (HMRIS) – Target Property
- PCB Activity Database System (PADS) – Target Property
- Emergency Response Notification System (ERNS) – Target Property
- Facility Index System (FINDS) – Target Property
- Toxic Chemical Release Inventory System (TRIS) – Target Property
- NPL Liens (NPL Lien) – Target Property
- Toxic Substance Control Act (TSCA) – Target Property
- Material Licensing Tracking System (MLTS) – Target Property
- Certified Hazardous Waste Resources Recovery Facilities (MO RRC) – Target Property

### 3.1.2 Summary of EDR Environmental Database Search Results

The subject property was identified in the EDR Environmental Database search as UST and LUST sites. Additional surrounding properties were also identified within the ASTM specified search distances from the subject property. A listing of database search findings is presented below.

Database Searched	Search Distance (Miles)	Facilities Located
UST	¼	1
LUST	½	2

Discrepancies between the information provided by government agencies and EDR may exist due to incomplete or non-updated databases of either resource. In addition, facilities may be listed in more than one category on the environmental screening report. A summary of the EDR sites identified within the above listed search distances follows.

UST (1 site)

- State of Missouri Surplus Property (subject property), 117 North Riverside Drive, Jefferson City, Missouri 65102. Records indicate that 2 tanks were removed.



#### LUST (2 sites)

- State of Missouri Surplus Property (subject property), 117 North Riverside Drive, Jefferson City, Missouri 65102. There was a release reported at this facility on 7/2/93. Excavation was listed as the remediation technique. Spill cleanup started on 7/2/93 and ended 12/15/93.
- Al's Tire Service, 1015 East McCarty, Jefferson City, Missouri 65101. This site is located 1/4 to 1/2 mile west southwest of the subject property. There was a release reported on 4/13/93. Excavation, tank closure and landfill are listed as the remedial techniques. Soil was listed as the contaminated media. Spill cleanup dates were not given.

#### Orphan sites (2 sites)

- Missouri Highway and Transportation Department, East McCarty Street, Jefferson City, Missouri. This site is listed as a LUST. There is insufficient information on this site as to its exact location and remediation status.
- Delong's, Inc., East Capitol Street, Jefferson City, Missouri. This site is listed as a UST. There is insufficient information on this site as to its exact location and remediation status.

#### 3.1.3 Environmental Assessment Reports

The property owner indicated that previous Phase I, II and III environmental assessment work was performed at the subject property beginning in January of 1990 by Sverdrup, Inc. A summary of these reports follows:

In a report titled Site Investigation Phase I Environmental Investigation at the State Agency for Surplus Property dated December 1990, Sverdrup Environmental Inc. began an investigation as a result of an anonymous complaint to the U. S. Environmental Protection Agency (EPA) in January 1990 and a site inspection by Missouri Department of Natural Resources (MDNR) on January 26, 1990. The result of the inspection indicated open dumping of chemicals on the site. Interviews with individuals associated with the Surplus Property conducted in February 1990 indicated that open dumping of chemicals on the site took place anywhere from 1 to 14 years ago. From February to August 1990, soil and groundwater samples were taken by Maecorp and Sverdrup at locations of presumed contamination to delineate the extent of environmental impact on and off site. The result of the investigation concluded elevated levels of organic and



inorganic compounds primarily from the surface discharge of hazardous chemicals. Further investigation was recommended.

In October 1993, Sverdrup proposed a work plan for additional sampling to the MDNR. In a report titled Phase II Environmental Investigation Results, State Agency for Surplus Property dated July 1994; Sverdrup continued the soil and groundwater investigation of the site from January to June 1994. The results of the investigation concluded, in general, that migration of the chemical impact off site was minimal while locations on the site would require remedial soil removal.

From July 22, 1996 to August 8, 1996 Sverdrup contracted P.W. Stevens to perform remedial excavations at the subject property under the supervision of Sverdrup. In a report titled Site Remediation Report at the State Agency for Surplus Property, four locations on the site were excavated 1 to 2 feet deep. Confirmation samples were taken to document the cleanup.

From July 1996 to January 1998, groundwater monitoring was performed on a semi-annual basis. The last report dated September 30, 1998 indicated groundwater impact from the site was low. The report also indicated that site closure could be pursued if groundwater results remained low after a 2 year interval. Many of the groundwater wells were recommended for abandonment. This report was the last report filed with the MDNR.

### 3.2 Aerial Photographs

Aerial photographs were obtained and reviewed for the subject property and surrounding areas for the years 1961, 1965, 1981, and 1990.

#### 3.2.1 1961 Aerial Photograph Review

The subject property appeared to be used for farming. No Surplus Property buildings are present. The Old Training Academy and storage building are present. A water tower and the shoe factory to the south are present.

#### 3.2.2 1965 Aerial Photograph Review

Buildings #1 and #8 are present on the Surplus Property lot. The Old Training Academy and storage building are also present. The water tower and shoe factory to the south remain.

#### 3.2.3 1981 Aerial Photograph Review

All current buildings for the Surplus Property are identifiable. Significant drainage erosion is observed on the hillside east of Lay Down Yard (see Figure 2. Site Location and Topography Detail). The Old Training Academy and storage building are present along with the water tower and the shoe factory to the south.



### 3.2.4 1991 Aerial Photograph Review

There were no significant changes observed in this photograph.

### 3.3 Local Directories

Mullin-Kille, Johnson, and Polk directories were reviewed for the years 1938 through the present. A summary is presented below.

Tenants	Date
Division of Purchasing Surplus Property	2000
Mo. State Surplus Property	1990
Mo. State Surplus Property	1986
State Department of Education Agency for Surplus Property	1971
No Listing	1967
No Listing	1961
No Listing	1955
No Listing	1948
No Listing	1943
No Listing	1938

### 3.4 Local Zoning/Land-Use Records

The city zoning office was contacted for current zoning/land use of the subject property. The subject property is zoned RS-1 which represents residential single family.

### 3.5 Sanborn Maps

Sanborn Maps of the subject property were obtained for the years 1939, 1943, and 1968. The subject property is vacant in 1939 and in 1943. The surrounding area to the south appears under development for residential use. The International Shoe Factory is present to the



south. In 1968, the property is developed with seven structures shown. There were no Sanborn Maps available for the Old Training Academy to the north.

### 3.6 Historical Topography Maps

Historical topography maps of the subject property were obtained for the years 1942, 1967, and 1974. The 1942 topography map shows the Old Training Academy/ Women Correctional Facility and the water tower. The International Shoe Factory is present to the south. No other structures are shown. The 1967 topography map shows a change in topography in the northwest portion of the subject property. The change in topography is in the form of a fill area that once was a drainage gully. The Administration Building and Building #8 are present. The 1974 topography map shows no change in topography. Buildings #3, #5, and #6 are shown.



## 4.0 Site Reconnaissance

---

### 4.1 Site Survey Process

A site reconnaissance of the subject property was conducted by TSi Engineering, Inc. on June 4, 2001. Photographs of the subject property are presented in Appendix A. The site survey summary is presented in Appendix B.

### 4.2 Hazardous Materials and Petroleum Products

Due to the age of the buildings identified, suspect asbestos containing materials and lead-based paint may be present. Suspect asbestos fireproofing was observed on some of the structural steel members of a garage. Suspect asbestos was also noticed on thermal system insulation. Additional materials which may contain asbestos include floor tiles, ceiling tiles, surfacing materials and roofing materials. Potential lead-based paint was found on horizontal and vertical surfaces and mechanical equipment. Lead dust and contaminated soil may also be present at an assumed former firing range. Tires, furniture, and containers of antifreeze, oil and cleaning products were observed in and around the subject property. These items were found in various quantities. Copies of material safety data sheets (MSDS) are presented in Appendix C.

### 4.3 Storage Tanks

Evidence of former underground storage tanks was observed at the subject property. These tanks were located under the current above ground storage tanks and have been removed according to reviewed records.

### 4.4 Drums

Evidence of 55-gallon drums was observed at the subject property. These drums were located in the garage area and in the rear of the property. The drums in the garage area were used for lubricants in the maintenance of equipment. These drums were in good condition. The drums located in the rear of the lot were empty.

### 4.5 Hazardous Waste

Evidence of hazardous waste activities was observed at the subject property. Used car and equipment batteries were stored in a properly contained area of the garage.



#### 4.6 Solid Waste

During interviews of site personal, a possible landfill was discussed located in the northwest corner of the subject property between the Old Training Academy and the Potato House (see Figure 2. Site Location and Topography). The landfill activities occurred prior to the employment of the current staff.

#### 4.7 Wastewater

Storm drains located throughout the area were observed.

#### 4.8 Drains and Sumps

Evidence of stained drains or sumps in the area was not observed.

#### 4.9 Stains and Pools of Liquid (Interior)

Evidence of stains and pools of liquid inside the buildings was not observed.

#### 4.10 Pits, Ponds, Lagoons

Evidence of pits, ponds and lagoons was not observed at the subject property.

#### 4.11 Stained Soil or Pavement and Stressed Vegetation

Evidence of minor stains under some of the vehicles and equipment was observed. Stressed vegetation was not observed.

#### 4.12 Potential PCB-Containing Electrical or Hydraulic Equipment

Evidence of potential PCB-containing electrical or hydraulic equipment was observed. Hydraulic floor lifts and forklifts were located in the Lay Down Yard with no evidence of leakage observed.



## 5.0 Interviews and Questionnaire

---

### 5.1 Owner/Tenant Questionnaire

The purpose of the questionnaire is to obtain historical background information for the site. TSi Engineering, Inc. submitted a questionnaire to Mr. Mark Schreiber of the State of Missouri Corrections. As of the date of this report, Mr. Schreiber has not returned the questionnaire. As soon as this information becomes available, TSi Engineering will submit the responses as an addendum to this report. In an interview on June 4, 2001 with Mr. Schreiber, he was able to impart historical information about the site. The area along the bluffs between the Old Training Academy and the Potato House may have been a landfill utilized by the state correctional facility. He did not see the landfill in use during his tenure which started in the 1960's. Cyanide was stored in the basement of the Old Training Academy during the 1960's but it was never used on the site. The area to the east and down the hill from the Old Academy was used as a firing range. He had no knowledge of any of the activities taking place on the State Agency for Surplus Property facility. Ms. Marilyn Stephen of the State Agency for Surplus Property indicated the locations of the former LUST's and provided MSDS sheets on items currently being used on site. Her knowledge of the activities at the site prior to 1990 was limited.

### 5.2 Local Fire Department

The Jefferson City Fire Department was contacted on June 5, 2001 to assess whether the local fire department had responded to any environmental emergencies at the subject property. According to Fire Chief Robert Rennick, the City Fire Department has responded to a major fire in the Administration Building #1 on October 31, 1981. The fire started in the typewriter repair section of building, destroying most of it. The cause of the fire remains unknown.

### 5.3 Local Utility Company

Ameren UE was contacted by TSi Engineering, Inc. regarding the polychlorinated biphenyls (PCB) status of electrical transformers at the site and surrounding areas. The response from Ameren UE indicated that there are three-pole mounted transformers, the oldest of which is 1986. These transformers are certified by the manufacturer as non-PCB containing. A copy of the Ameren UE correspondence is presented in Appendix D.



## 6.0 Findings and Conclusions

---

Based on the information readily available to TSi Engineering, Inc., the following conclusions are pertinent to the subject property.

The buildings on the subject property are over 30 years old. Due to the age of the buildings and observed building materials, asbestos-containing materials (ACM) and lead-based paint may be present at the site. A former LUST was identified along with a former firing range, potential chemical dumping and a former landfill. Past reports support previous subsurface contamination at the subject property.

In our professional opinion, the following RECs have been identified for the subject property during this assessment:

- Potential asbestos-containing building materials (ACBM).
- Potential lead-based paint (LBP).
- Potential soil and groundwater impact from LUST tank removal on site.
- Potential soil and groundwater impact from open dumping of chemicals.
- Potential soil and groundwater impact from former firing range.
- Potential soil and groundwater impact from former landfill.

Potential ACM and LBP present at existing structures at the subject property should be inspected by U. S. Environmental Protection Agency (EPA) and State of Missouri certified and licensed inspectors. Asbestos inspections are required by federal, state and local regulations prior to any disturbance of these materials. Environmental subsurface investigations may be necessary for the subject property at locations which are at topographically lower elevations than the former LUST sites. Environmental subsurface investigations may also be necessary to properly characterize subsurface conditions for the former dumping site, the former firing range site and the former landfill site.



7.0 Signatures of Environmental Professionals

---

This Phase I Environmental Site Assessment was conducted by the following environmental professionals in accordance with ASTM E 1527-00.

\_\_\_\_\_  
Rick Whitney  
Staff Geologist

\_\_\_\_\_  
Date

\_\_\_\_\_  
Sylvester Douglas  
Manager, Environmental Services

\_\_\_\_\_  
Date



## 8.0 Qualifications of Environmental Professionals

---

### Rick Whitney Staff Geologist

#### Professional Summary:

As a geologist, Mr. Whitney has over 15 years of experience within the geological and environmental field. His project experience includes: Phase I/II environmental assessments; preparation of work plans; asbestos investigations; feasibility studies; soil sampling; UST/AST storage tank management; and groundwater, air quality, and well placement monitoring. These services have been performed for commercial, industrial, and residential property.

#### Areas of Expertise:

- Subsurface Investigations
- Soil Classifications
- Groundwater Monitoring
- Asbestos Sampling
- Phase I, II and III ESA

#### Education:

B.S. in Geology, University of Missouri – Columbia, 1982

### Sylvester Douglas Environmental Group Manager

#### Professional Summary:

Mr. Douglas has over 11 years of experience in every facet of asbestos management including conducting AHERA inspections, identifying asbestos-containing materials, collecting bulk samples, preparing technical specifications and architectural drawings for asbestos abatement plans, performing air monitoring, determining and enacting engineering control methods to reduce potential hazards to abatement workers and the public, and preparing final reports. His background also includes management of a phase contrast microscopy (PCM) laboratory, including development of quality control programs, design of all reporting and recordkeeping systems, and management of air monitoring technicians and field personnel.

#### Areas of Expertise:

- Phase I, II and III ESA
- Asbestos and Lead Surveys
- Regulatory Reviews
- Environmental Audits
- Process Safety Management Studies
- EPA Risk Assessments



Rick Whitney  
Staff Geologist

Registrations/Certifications:

- ACI Certified Technician, American Concrete Institute
- Certified Asbestos Inspector
- Certified Air Monitoring Technician
- OSHA 40-Hour Health and Safety Training Certification

Professional Affiliations:

- Geological Society of America

Sylvester Douglas  
Environmental Group Manager

Education:

B.S. in Engineering and Public Policy, Washington University, 1988

Registrations/Certifications:

- MoDNR Certified Air Sampling Professional
- AHERA Inspector, MO
- AHERA Management Planner, MO
- AHERA Abatement Worker, MO
- AHERA Project Designer
- NIOSH 582 Sampling and Evaluating Airborne Asbestos Dust (Method 7400)
- Lead Inspector, KUVII43000-4



## 9.0 Limitations of Report

---

This report has been prepared on behalf of and for the exclusive use of the addressee, solely for use in an environmental assessment of the site. This report and the findings contained herein were prepared for Berkebile, Nelson, Immenschuh and McDowell Architects (BNIM) expressly for their intended use of the property.

This site assessment was performed in accordance with generally accepted practices of other consultants undertaking similar studies at the same time and in the same geographical area and TSi Engineering, Inc. observed that degree of care and skill generally exercised by other consultants under similar circumstances and conditions. The findings and conclusions stated herein must be considered not as scientific certainties, but rather as professional opinions concerning the significance of the limited data gathered during the course of the environmental site assessment. No other warranty, express or implied, is made. Specifically, TSi Engineering, Inc. does not and cannot represent that the site contains no hazardous waste or material, oil (including petroleum products), or other latent condition beyond that observed by TSi Engineering, Inc. during their site assessments.

The observations described in this Report were made under the conditions stated herein. The conclusions presented in the Report were based solely upon the services described therein and not on scientific tasks or procedures beyond the scope of described services or the time and budgetary constraints imposed by the Client. Furthermore, such conclusions are based solely on site conditions and rules and regulations that were in effect, at the time of the study. The work described in this Report was carried out in accordance with the terms of contract language associated with TSi Engineering, Inc.'s contract agreement with BNIM.

In preparing this report, TSi Engineering, Inc. has relied on certain information provided by state and local officials and other parties referenced herein and on information contained in the files of state and/or local agencies available to TSi Engineering, Inc. at the time of the site assessment. Although there may have been some degree of overlap in the information provided by these various sources, and attempt to independently verify the accuracy or completeness of all information reviewed or received during the course of this site assessment was not made.

Observations were made of the site and of structures on the site as indicated within the Report. Where access to portions of the site or to structures on the site was unavailable or limited, TSi Engineering, Inc. renders no opinion as to the presence of hazardous waste or material, oil or other petroleum products, or to the presence of indirect evidence relating to hazardous waste or material, oil or other petroleum products in that portion of the site or structure. In addition, TSi Engineering, Inc. renders no opinion as to the presence of



hazardous waste or material, oil or other petroleum products or to the presence of indirect evidence relating to hazardous material, oil or other petroleum products where direct observation of the interior walls, floor, roof or ceiling of a structure in a site was obstructed by objects or coverings on or over these surfaces.

Unless otherwise specified in the Report, TSi Engineering, Inc. did not perform testing or analyses to determine the presence or concentrations of asbestos, radon, formaldehyde, lead-based paint, lead-in-drinking water, electromagnetic fields (EMFs), methane gas or polychlorinated biphenyls (PCBs) at the site or in the environment at the site.

The purpose of this Report was to present the results of a Phase I Environmental Site Assessment performed in substantial conformance with ASTM E1527-00 and included assessing the physical characteristics of the subject site with respect to the presence in the environment of hazardous waste or material, oil, or petroleum products, as defined in 40 CFR Parts 261, 280-281, 302, 355 and 49 CFR Part 172. No specific attempt was made to check on the compliance of present or past owners or operators of the site with federal, state, or local laws and regulations, environmental or otherwise.


It is recommended that TSi Engineering, Inc. be retained to provide further engineering services during construction and/or implementation of any remedial measures recommended in this Report. This is to allow the TSi Engineering, Inc. to observe compliance with the concepts and recommendations contained herein and to allow the development of design changes in the event that subsurface conditions differ from those anticipated.



Figures

- 1 Site Location and Topography (USGS)
- 2 Site Location and Topography (Detail)

SITE LOCATION  
SURPLUS PROPERTIES



NOT TO SCALE



engineers, inc.

59TH AND ARSENAL, BUILDING C  
2 CAMPBELL PLAZA  
ST. LOUIS, MISSOURI 63139

SITE LOCATION AND TOPOGRAPHY

SURPLUS PROPERTIES  
JEFFERSON CITY, MISSOURI



Drawn By: EBS

Checked By: RW

Project No. 2001026.00

Date: 06/07/01

Figure 1



N.T.S.

 <small>engineers, inc.</small> <small>5074 AND ARDENAL, BUILDING C          2 CAMPBELL PLAZA          ST. LOUIS, MISSOURI 63139</small>	SITE LOCATION AND TOPOGRAPHY		
	SURPLUS PROPERTIES JEFFERSON CITY, MISSOURI		
Drawn By: EBS	Checked By: RW		
Project No. 2001026.00	Date: 06/07/01	Figure 2	



## Appendix A

### Site Reconnaissance Photographs



P1010001 – Boiler room – Old Training Academy



P1010002 – Basement floor and drains – Old Training Academy



P1010003 – Basement floor – filled floor drains



P1010004 – Inside Potato House



P1010005 – Exterior Potato House



P1010006 – Inside Potato House



P1010007 – Exterior Southside Potato House



P1010008 – Water Tower



P1010009 – East side Old Training Academy



P1010010 – Storage Building



P1010011 – West side Old Training Academy



P1010012 – Southside Old Training Academy



P1010013 – Parking lot East side of Surplus Property



P1010014 – Water Well House



P1010015 – Front Administration Building #1



P1010016 – Front Surplus Property facing North



P1010017 – Overflow parking lot east of Surplus Property



P1010018 – Building #4 storage north shed



P1010019 – Building #4 storage north shed



P1010020 – Building #5 storage south side



P1010021 – Building #5 storage south side



P1010022 – Building #4 south shed



P1010023 – Building #6 and #5 south side



P1010024 – Building #3 storage



P1010025 – AST fuel storage



P1010026 – Drain in front of garage next to building #3



P1010027 – Building #6 storage south side



P1010028 – Rear loading dock Administration Building #1



P1010029 – West side Building #6



P1010030 – Forklift in Lay Down Yard



P1010031 – Hydraulic lifts in Lay Down Yard



P1010032 – Storage in Lay Down Yard



P1010033 – Storage in Lay Down Yard



P1010034 – West end of Lay Down Yard



P1010035 – Empty drums storage west end of Lay Down Yard



P1010036 – Generator Storage Lay Down Yard



P1010037 – Fluorescent light fixtures Lay Down Yard



P1010038 – Empty bins west end Lay Down Yard



P1010039 – Storage west end Lay Down Yard



P1010040 – Pumps in Lay Down Yard



P1010041 – Outboard motors Lay Down Yard



P1010042 – Empty tanks in Lay Down Yard



P1010043 – Empty cylinders in Lay Down Yard



P1010044 – Empty tanks in Lay Down Yard



P1010045 – Generators in Lay Down Yard



P1010046 – Storage on P-Lot



P1010047 – Storage on P-Lot

P1010048 – (skipped)



P1010049 – Cars on Lay Down Lot



P1010050 – Storm drain west of building #6



P1010051 – Area between building #9 and #8



P1010052 – Storage building #9



P1010053 – Surplus refrigerators between building #6 and #8



P1010054 – Storage around building #8



P1010055 – Surplus cars in front of building #7



P1010056 – Area east of building #8 and garage



P1010057 – Empty cylinders east of garage



P1010058 – Large Equipment lot north of garage



P1010059 – Interior of garage



P1010060 – Battery storage



P1010061 – Interior of garage



P1010062 – Interior of garage



P1010063 – Interior of storage area behind garage



P1010064 - Interior of storage area behind garage



P1010065 - Interior of storage area behind garage



P1010066 – West side Building #5

P1010067 – (skipped)



P1010068 – North side building #9 storage



P1010069 - North side building #9 storage



P1010070 – North side building #8 storage



P1010071 – Building #9 (also called C-Barn)



P1010072 – Manhole to Oil/water separator east of building #8



P1010073 – Storage north side building #7



P1010074 – Storage in building #7



P1010075 – Storage in building #7



P1010076 – Storage in building #6



P1010077 – Storage in building #5



P1010078 – Storage area behind Administration Office building #1



P1010079 – South side of Administration Building #1



P1010080 – Computer Storage Building #2



P1010081 – Chair shed south side building #1

P1010082 - ?



P1010083 – Storage area behind Administration building #1



P1010084 – Storage area next to water tower



P1010085 – Storage area next to water tower



P1010086 – Storage area next to water tower



P1010087 – Storage area next to water tower



P1010088 – Storage area next to water tower



P1010089 – Area west of Old Training Academy facing north



P1010090 – Area west of Old Training Academy facing north looking down hill



P1010091 - Area west of Old Training Academy facing north looking down hill



P1010092 – Road along East side of Surplus Properties



P1010093 – Missouri State Agency for Surplus Property



P1010094 – Correction Property East of Surplus Property

P1010095 – (skipped)



P1010096 – Corrections Property east of Surplus Property facing north



P1010097 – Residential dwellings south of surplus property facing south



P1010098 - Residential dwellings south of surplus property facing south



P1010099 - Residential dwellings south of surplus property facing south



P1010100 - State Penitentiary to the west



P1010101 – State Penitentiary to the west



P1010102 – International Shoe Factory to the south



P1010103 - International Shoe Factory to the south



Appendix B

Site Survey Summary Form

- Surplus Property
- Old Training Academy + Storage, Potato House

## Site Survey Summary

Address: Surplus Property

Description of Site: Site has 9 major buildings numbered as such. Admin. #1 is cinder block steel structure on concrete #2 - Sheet Metal Barrack Type w/ steel structure on concrete #3 as #2 #4 as #2 #5 #6 - Sheet Metal warehouse w/ steel structure, #7 as #2 #8 - as #5 #9 - as #2 (more shed) in structure. The area is mostly paved in concrete + asphalt. Gravel lots are located on the far north area. Grass, trees, and woods surround the fenced site

1. Is the Property or any adjoining property used for an industrial, commercial or manufacturing use?

	<u>Land Use</u>	<u>Photograph?</u>
Property:	Surplus Storage (State + Federal)	✓
Adjoining Properties North:	Old Training Academy	✓
Adjoining Properties South:	Remn Residential / <del>Antenna Tower</del> / Antenna Tower / Shoe	✓
Adjoining Properties East:	State Correctional	✓
Adjoining Properties West:	Riverside Park	

2. Has the Property or any adjoining property been used for an industrial, commercial or manufacturing use in the past?

	<u>Owner</u>	<u>Use</u>	<u>Dates</u>
Previous Use of Property	Womans Correctional	Farm	
Previous Use of Properties to North	Missouri River	Watershed	
Previous Use of Properties to South	Reim / International Shoe	Residential / Factory	
Previous Use of Properties to East	STATE Corrections		
Previous Use of Properties to West	Park		

3. Is there evidence that there are currently, or have been previously, any pesticides, automotive or industrial batteries, paints, or other chemicals stored on or used at the Property or at the facility other than undamaged containers of consumer products of under five gallons in total volume?

**Finding:** Batteries, lubricants, solvents found in garage maintenance areas, MSDS sheets available. These are in small single can quantities to large 55 gallon drums. Antifreeze

**Source:**

4. Is there evidence that there are currently, or have been previously, any industrial drums (typically 55-gallon) or sacks of chemicals located on the Property or at the facility?

**Finding:** Area 12+13 of laydown yard has empty 55 gallon drums. Various Containers and Storage Tanks, from 5 gallons to 2000 gallons in size are located in the lay down yard area - ALL ARE EMPTY.

**Source:**



10. Is there evidence that there are currently, or have been previously, any flooring, drains, or walls located within the facility that are stained by substances other than water or are emitting foul odors?

Finding: *No evidence*

Source:

11. Is there evidence that the Property is served by a private well or non-public water system, and if so, has the well or system been designated as contaminated by any governmental environmental/health agency?

Finding: *Water Tower is ground water - Non Potable*

Source:

12. Does the owner of the Property or operator of the facility have any knowledge of environmental liens or governmental notification relating to past or current violations of environmental laws with respect to the Property or any facility located on the Property?

Finding: *State Property*

Source:

13. Has the owner of the Property or operator of any facility at the Property been informed of any past or current existence of hazardous substances or environmental violations with respect to the Property or any facility located on the Property?

Finding: *Environmental violations reported in early 1990 revealed numerous illegal hazardous substances dumping on Property*

Source:

14. Does the Property owner or facility operator have any knowledge of any environmental assessment of the Property or facility that indicated the presence of hazardous substances on the site or recommended further assessment of the Property?

Finding: Phase I, II, + III were performed from 1990 - 1996 with respect to the illegal activities

Source:

15. Does the owner of the Property or any operator of a facility at the Property know of any past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any hazardous substance involving the Property by any owner or tenant of the Property?

Finding:

Source:

16. Is there evidence that the Property discharges wastewater, other than storm water, directly to a ditch, stream, septic system, or sump on or adjacent to the Property?

Finding: No Evidence -

Source:

17. Is there evidence that any construction debris, substances identified as hazardous, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials, trash, debris or refuse been dumped above grade, buried and/or burned on the site?

Finding: As part of the illegal activities, burning pits located west of lay down yard were found and cleaned up

Source:

18. Is there evidence of any electrical or hydraulic equipment (such as compressors, transformers and large capacitors), now on the site or that have been on the site in the past, known to contain PCBs? If so, describe the equipment, identify its location, approximate dates of use of the equipment, and whether it has been registered as PCB containing material, and actual knowledge of leaks.

Finding: Multiple compressor-type equipment - NOT known to contain PCBs

Source:

19. Is there evidence that equipment containing PCBs has been removed? If so, obtain the approximate dates of removal, location removed from, and name of the removal contractor.

Finding: No Evidence -

Source:

20. Is there evidence that there have been any fires on the Property involving PCBs? If so, describe and provide the date(s) of the occurrence and remediation methods.


Finding: No Evidence - Remediation by removal of soil in drainage and burn pits was conducted in 1996 NOT exclusively for PCBs

Source:

This Site Survey Summary Was Completed By:

Name: Rick W. Iney Title: Staff Geologist  
Firm: ISI Engineering Date: 6/4/01  
Address: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Preparer represents that to the best of the Preparer's knowledge the above statements and facts are true and correct and that to the best of the Preparer's knowledge no material facts have been suppressed or misstated.

Signed:  Date: 6/4/01

## Site Survey Summary

Address: Old Training Academy + Storage, Pata House

Description of Site: 2 Story Brick Bldg w/ Basement; 4 Story Brick Storage shed w/ Basement; 1 limestone construction Pata's House located on the Northern half of the Area

1. Is the Property or any adjoining property used for an industrial, commercial or manufacturing use?

	<u>Land Use</u>	<u>Photograph?</u>
Property:	CorrelTena	✓
Adjoining Properties North:	Missouri River	
Adjoining Properties South:	Kern's Residential	✓
Adjoining Properties East:	State CorrelTena	✓
Adjoining Properties West:	State CorrelTena   Riverside Park	✓

2. Has the Property or any adjoining property been used for an industrial, commercial or manufacturing use in the past?

	<u>Owner</u>	<u>Use</u>	<u>Dates</u>
Previous Use of Property	Womens Correctional	≈ 1960's	
Previous Use of Properties to North	River	Water	
Previous Use of Properties to South	Residential/Farm	Agri.	
Previous Use of Properties to East	STATE Prison	1822	
Previous Use of Properties to West	STATE Correctional	Vacant	

3. Is there evidence that there are currently, or have been previously, any pesticides, automotive or industrial batteries, paints, or other chemicals stored on or used at the Property or at the facility other than undamaged containers of consumer products of under five gallons in total volume?

Finding: In The 1960's, CN was stored in Basement.

3/4 gallon Disinfectant Produced @ Prison used for Cleaning Products - Small Quantities

Source: Interview

4. Is there evidence that there are currently, or have been previously, any industrial drums (typically 55-gallon) or sacks of chemicals located on the Property or at the facility?

Finding: No evidence

Source:

5. Is there evidence that fill dirt has been brought onto the site which originated from a contaminated site or of an unknown origin?

Finding: *No evidence - Rumored Landfill To East of Building*

Source: *Interview*

6. Is there evidence that there are currently, or have been previously, any pits, ponds or lagoons located on the Property in connection with waste treatment or waste disposal?

Finding: *No Evidence*

Source:

7. Is there evidence that there is currently, or has been previously, any stained soil or stressed vegetation on the Property?

Finding: *No Evidence*

Source:

8. Is there evidence that there are currently, or have been previously, any registered or unregistered storage tanks (above or underground) located on the Property?

Finding: *None*

Source:

9. Is there evidence that there are currently, or have been previously, any vent pipes, fill pipes or access ways indicating a fill pipe protruding from the ground on the Property or adjacent to any structure located on the Property?

Finding: *None*

Source:

10. Is there evidence that there are currently, or have been previously, any flooring, drains, or walls located within the facility that are stained by substances other than water or are emitting foul odors?

Finding: *No Stains around drains - water from rain leak  
into Basement NE corner*

Source:

11. Is there evidence that the Property is served by a private well or non-public water system, and if so, has the well or system been designated as contaminated by any governmental environmental/health agency?

Finding: *Water Tower - Groundwater - non Potable  
IT has been designated " "*

Source:

12. Does the owner of the Property or operator of the facility have any knowledge of environmental liens or governmental notification relating to past or current violations of environmental laws with respect to the Property or any facility located on the Property?

Finding: *None*

Source:

13. Has the owner of the Property or operator of any facility at the Property been informed of any past or current existence of hazardous substances or environmental violations with respect to the Property or any facility located on the Property?

Finding: *None*

Source:

14. Does the Property owner or facility operator have any knowledge of any environmental assessment of the Property or facility that indicated the presence of hazardous substances on the site or recommended further assessment of the Property?

Finding: *None*

Source:

15. Does the owner of the Property or any operator of a facility at the Property know of any past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any hazardous substance involving the Property by any owner or tenant of the Property?

Finding: *None*

Source:

16. Is there evidence that the Property discharges wastewater, other than storm water, directly to a ditch, stream, septic system, or sump on or adjacent to the Property?

Finding: *No evidence Observed*

Source:

17. Is there evidence that any construction debris, substances identified as hazardous, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials, trash, debris or refuse been dumped above grade, buried and/or burned on the site?

Finding: *Removal Landfill East of Building / None above grade*

Source:

18. Is there evidence of any electrical or hydraulic equipment (such as compressors, transformers and large capacitors), now on the site or that have been on the site in the past, known to contain PCBs? If so, describe the equipment, identify its location, approximate dates of use of the equipment, and whether it has been registered as PCB containing material, and actual knowledge of leaks.

Finding: *None*

Source:

19. Is there evidence that equipment containing PCBs has been removed? If so, obtain the approximate dates of removal, location removed from, and name of the removal contractor.

Finding: *None*

Source:

20. Is there evidence that there have been any fires on the Property involving PCBs? If so, describe and provide the dates(s) of the occurrence and remediation methods.

Finding: *None*

Source:

This Site Survey Summary Was Completed By:

Name: Rick Whitney Title: Staff Geologist  
Firm: TSI Engineering Date: 6/4/01  
Address: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Preparer represents that to the best of the Preparer's knowledge the above statements and facts are true and correct and that to the best of the Preparer's knowledge no material facts have been suppressed or misstated.

Signed:  Date: 6/4/01



Appendix C  
MSDS Sheets





# MATERIAL SAFETY DATA SHEET

1252  
AND SAFE HANDLING AND DISPOSAL INFORMATION



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

MISSOURI SURPLUS (317)  
PROPERTY-JANITORIAL  
1172 RIVERSIDE  
JEFFERSON CITY, MO 65101

06/18/96  
ISSUE DATE: 10/26/95  
SUPERSEDES: 01/11/91  
ZEP VELVET  
PRODUCT NO.: 0958

Hand Cleaner - Lotonized

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (770) 439-4200  
(770) 432-2873 NON-OFFICE HOURS, WEEKENDS  
(770) 424-4789 AND HOLIDAYS, PLEASE CALL YOUR  
(770) 392-1480 LOCAL POISON CONTROL  
(770) 455-8160  
(770) 552-6836  
TRANSPORTATION EMERGENCY: (770) 922-0923  
CHEMTREC: 1-800-424-9300 TOLL-FREE - ALL CALLS RECORDED  
DISTRICT OF COLUMBIA: (202) 483-7616 ALL CALLS RECORDED

### SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	TLV ( <sup>P</sup> PEM)	EFFECTS (SEE REVERSE)	% IN PROD.
* SODIUM LAURYL SULFATE * (sulfuric acid monododecyl ester, sodium salt); sodium monododecyl sulfate, CAS # 151-21-3; RTECS # WT1050000; OSHA PEL/MD	N/D	EIR	30-40

### SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

#### Acute Effects of Overexposure:

This product can be an eye irritant. Inflammation of eye tissue is characterized by redness, watering, and/or itching.

#### Chronic Effects of Overexposure:

Prolonged skin contact (4-8 hrs.), without rinsing, may result in irritation characterized by itching or reddening of the skin. No medical conditions are known to be aggravated by exposure to ingredients in this product. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

Est'd PEL/TLV: Not established

Primary Routes of Entry: N/A

HMS Codes: HEALTH:0;FLAM: 0;REACT: 0;PERS: PROTECT: N/A;CHRONIC HAZ: NO

#### RST AID PROCEDURES:

**Skin:** This product is formulated for use on the skin, but it should be rinsed off with water.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** This route of exposure is not likely due to product nature.  
**Ingest:** If this product is swallowed, do not induce vomiting. If victim is conscious give plenty of water to drink. Get medical attention at once.

### SECTION IV - SPECIAL PROTECTION INFORMATION

**Protective Clothing:** No special measures are required.  
**Eye Protection:** No special measures are required.  
**Respiratory Protection:** No special measures are required.  
**Ventilation:** No special measures are required.

### SECTION V - PHYSICAL DATA

Boiling Point (°F):	220	Specific Gravity:	1.10	Vapor Pressure (mmHg):	N/D
Percent Volatile by Volume (%):	84	Vapor Density (air = 1):	N/D	Evaporation Rate (WATER = 1):	1
Solubility in Water:	COMPLETE	pH (concentrate):	7.7	pH (use dilution of APPROX. 5%):	7.2
Appearance and Odor:	WHITE, PEARLIZED LIQUID WITH PLEASANT FRAGRANCE				

### SECTION VI - FIRE AND EXPLOSION DATA

**Flash Point (°F) (method used):** None (N/A)  
**Flammable Limits:** LEL N/A UEL N/A  
**Extinguishing Media:** Carbon dioxide, dry chemical, water.  
**Special Fire Fighting:** None  
**Unusual Fire Hazards:** None



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

2894

12/16/97  
ISSUE DATE: 05/12/97  
SUPERSEDES: 07/26/89  
ZEP GREASE MONKEY  
PRODUCT NO. 0060

Aerosol Lubricating Grease

## SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680  
BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (770) 439-4200  
NON-OFFICE HOURS, WEEKENDS  
AND HOLIDAYS, PLEASE CALL YOUR  
LOCAL POISON CONTROL  
(770) 432-2873  
(770) 424-4789  
(770) 392-1480  
(770) 455-8160  
(770) 552-8836  
TRANSPORTATION EMERGENCY: (770) 922-0923  
CHEMTREC: 1-800-424-9300  
TOLL-FREE - ALL CALLS RECORDED  
DISTRICT OF COLUMBIA: ALL CALLS RECORDED  
(202) 483-7616

MISSOURI SURPLUS (317)  
PROPERTY-JANITORIAL  
117 N RIVERSIDE DR  
JEFFERSON CITY, MO 65101

## SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS  
@ METHYLENE CHLORIDE ~ dichloromethane/methylene dichloride: CAS # 75-09-2; RTECS # PA8050000; OSHA PEL - 500  
25 ppm; OSHA STEL (15 MIN. TWA) - 125 ppm  
\* PROPRIETARY LUBRICANT BLEND ~ CAS # 8052-41-3; RTECS # WJ89225000

TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PROD.
50	CNS IRR CAR	50-60
500	IRR	20-30

@ Identifies chemicals listed under SARA-Section 313 for release reporting

## SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

### Acute Effects of Overexposure:

Inhalation of vapor can produce central nervous system depression, characterized by dizziness, headache, nausea, cardiac and/or respiratory depression, and stu-por. In some cases, unconsciousness or death could result in poorly ventilated or confined spaces. Exposure to high concentrations of vapor can be irritating to mucous membranes, such as eyes and upper respiratory tract. Severe eye exposure to liquid can cause reversible eye damage. Skin contact may cause a burning sensation and dermatitis. The relevance of these studies to humans has not been established.

### Chronic Effects of Overexposure:

Repeated or prolonged contact by inhalation or skin absorption may produce liver or kidney damage or damage to the central nervous system, characterized by tingling or numbness in the extremities, blurred vision or confusion. Skin, which is debilitated by repeated exposure to solvents, is more susceptible to irritation, infection, and dermatitis. Ingredients in this product may aggravate existing skin, eye, or respiratory disorders. One of the ingredients in this product may cause tumors in laboratory animals. The relevance of these studies to humans has not been established.

Primary Routes of Entry: Inh., Skin.

HMS Codes: HEALTH 2;FLAM. 3;REACT. 1;PERS. PROTECT. B ;CHRONIC HAZ. YES

### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention immediately.  
**Inhale:** Move exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Get medical attention immediately.  
**Ingest:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

## SECTION IV - SPECIAL PROTECTION INFORMATION

Wear viton gloves or use gloves with demonstrated resistance to the ingredients in this product.

**Eye Protection:** Use light-fitting safety glasses. Contact lenses should not be worn when working with this material.

**Respiratory Protection:** If ventilation is inadequate, wear a properly fitting MSHA or OSHA-approved respirator.

**Ventilation:** Ventilation should be equivalent to outdoors. Use exhaust fans and open windows in enclosed spaces.

## SECTION V - PHYSICAL DATA

Boiling Point (°F): 104  
Specific Gravity: 0.820  
Vapor Pressure (mmHg): APPROX. 340  
Solubility in Water: 85  
Vapor Density (air = 1): N/D  
Evaporation Rate (ECL4 = 1): 2.5  
pH (concentrate): N/A  
pH (use dilution of ): N/A

Appearance and Odor: CLEAR, RED SLIGHTLY VISCOUS FLUID WITH A HYDROCARBON ODOR  
SECTION VI - FIRE AND EXPLOSION DATA

Flash Point (°F) (method used): Extremely Flammable (CSMA)

Flammable Limits: LEL 13.0 UEL 22.0

Extinguishing Media: Carbon dioxide, dry chemical and foam.

Special Fire Fighting: Wear self-contained positive pres. breathing apparatus.

Unusual Fire Hazards: Concentrated vapor may ignite if exposed to spark.



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P. O. BOX 2015  
ATLANTA, GEORGIA 30301

MISSOURI SURPLUS  
PROPERTY - JANITORIAL  
117 NO RIVERSIDE DR.  
JEFFERSON CITY, MO 65101

# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

08/26/92  
ISSUE DATE: 08/07/91  
SUPERSEDES: 03/26/90  
ZEP M.L. LUBRICANT  
PRODUCT NO.: 0047

Aerosol Lubricant

## SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (404) 435-2973 NON-OFFICE HOURS, WEEKENDS  
(404) 351-2952 AND HOLIDAYS, PLEASE CALL YOUR  
(404) 432-2873 LOCAL POISON CONTROL  
TRANSPORTATION EMERGENCY: (404) 922-0923  
CHEMTREC: 1-800-424-9300 TOLL-FREE - ALL CALLS RECORDED  
DISTRICT OF COLUMBIA: (202) 483-7616 ALL CALLS RECORDED

## SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PROD.
ASPHALT™ CAS # 8062-42-4; RTECS # C19900000; OSHA PEL -0.2 mg/m <sup>3</sup> ; ACGIH TLV - 5 mg/m <sup>3</sup>	N/D	IRR	40-50
BLEND OF HYDROTREATED AND DEWAXED RESIDUAL OILS ~ CAS # 64742-56-0/64742-62-7; RTECS # NONE;	N/D	IRR	5-15
OSHA PEL-N/D			
1,1,1-TRICHLOROETHANE ~ methyl chloroform chloroethene; CAS # 71-55-6; RTECS # KJ2975000; OSHA PEL-350	350	IRR CNS	10-20
PPM; ACGIH/OSHA STEL-450 PPM			
PARAFFIN OIL ~ blend of heavy and light naphthenic petroleum distillate; CAS # 64742-52-5; and CAS # 64742-53-6;	N/D	IRR	10-20
RTECS # NONE; OSHA PEL-N/D; ACGIH OIL MIST LIMIT = 5mg/m <sup>3</sup>			
BLEND OF ISOBUTANE; CAS # 75-28-5; RTECS # TZ4300001 & [PROPANE; CAS # 74-98-6; RTECS # TX2775000]	800	COR FBL	10-20
& [n-BUTANE; CAS # 106-97-8; RTECS # E44200000] OSHA PEL-1000 ppm			

@ Identifies chemicals listed under SARA-Section 313 for release reporting

## SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

### Acute Effects of Overexposure:

Inhalation of vapor can produce central nervous system depression, characterized by dizziness, headache, nausea, cardiac and/or respiratory depression, stupor, unconsciousness and death in extreme cases. Exposure to high concentrations of vapor by direct contact or inhalation can be irritating to mucous membranes, such as eyes and upper respiratory tract. Severe eye exposure to liquid can cause reversible eye damage. Skin contact may cause a burning sensation and reddening of the skin. Introduction of solvent to the lungs, as in aspiration of vomitus fluids, may cause chemical pneumonia. Exposure to this product may aggravate existing respiratory and cardiac conditions. Inhalation of aerosol mist may produce chemical pneumonia.

### Chronic Effects of Overexposure:

Repeated or prolonged contact by inhalation or skin absorption may produce liver or kidney damage or damage to the central nervous system, characterized by tingling or numbness in the extremities, blurred vision or confusion. Skin, which is dehydrated by repeated exposure to solvents, is more susceptible to irritation, infection, and dermatitis. Exposure to some ingredients in this product can aggravate existing liver disease or heart rhythm disorders. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

Primary Routes of Entry: Inh., Skin.

Est'd PEL/TLV: APPROX. 200 PPM

HMS Codes: HEALTH 2:FLAM 1; REACT. 1; PERS. PROTECT. X; CHRONIC HAZ YES

### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** Move exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Get medical attention immediately.  
**Ingest:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

## SECTION IV - SPECIAL PROTECTION INFORMATION

### Protective Clothing:

Wear nylon gloves or use gloves with demonstrated resistance to the ingredients in this product.

### Eye Protection:

Use tight-fitting safety glasses. Contact lenses should not be worn when working with this material.

### Respiratory Protection:

If ventilation is inadequate, wear a properly fitting MSHA or OSHA-approved respirator.

### Ventilation:

Ventilation should be equal to outdoors. Use exhaust fans and/or exhaust hood in enclosed spaces.

## SECTION V - PHYSICAL DATA

Boiling Point (°F):	105-285F	Specific Gravity:	1.014	Vapor Pressure (mmHg):	APPROX. 315
Percent Volatile by Volume (%):	~33	Vapor Density (air=1):	N/D	Evaporation Rate (CCL4 =1):	2.5
Solubility in Water:	NEGLIGIBLE	pH (concentrate):	N/A	pH (use dilution of N/A):	N/A
Appearance and Odor:	A VISCOUS, BLACK OIL WITH A STRONG, SWEET CHLORINATED ODOR				

## SECTION VI - FIRE AND EXPLOSION DATA

**Flash Point (°F) (method used):** FLAMMABLE (CSMA)  
**Flammable Limits:** LEL/N/D UEL/N/D  
**Extinguishing Media:** Carbon dioxide, dry chemical, water fog, foam.  
**Special Fire Fighting:** Wear self-contained positive pres. Breathing apparatus.  
**Unusual Fire Hazards:** Direct water onto intact containers to prevent bursting.

KA-POW  
DN 4530

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

MANUFACTURED FOR:  
Drummond American Corporation  
600 Corporate Woods Pkwy.  
Vernon Hills, IL 60061

IN CASE OF EMERGENCY CALL:  
ROCKY MOUNTAIN POISON & DRUG CENTER  
COLLECT AT: (303) 623-5716

DATE OF PREPARATION:  
02/01/98

INFORMATION TELEPHONE NUMBER  
(847) 913-9313

SECTION I - IDENTITY

PRODUCT NUMBER DN 4530  
PRODUCT NAME KA-POW  
PRODUCT CLASS CLEANERS

SECTION II - INGREDIENTS

INGREDIENT	CAS NUMBER	%	ACGIH TLV PPM	MG/ M <sup>3</sup>	PEL PPM	STEL PPM
D-LIMONENE	5989-27-5		ND	ND	ND	ND
EDTA	64-02-8		ND	ND	ND	ND
TETRAPOTASSIUM PYROPHOSPHATE	7320-34-5		ND	ND	ND	ND
SODIUM METASILICATE	6834-92-0		ND	ND	ND	ND

S.A.R.A. TITLE III, SECTION 313:  
THIS PRODUCT CONTAINS NO LISTED  
CHEMICALS SUBJECT TO REPORTING.

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT (degrees F): N/A  
VAPOR DENSITY: N/A  
EVAPORATION RATE: N/A  
PERCENT VOLATILE (By Weight): N/A WEIGHT PER GALLON (LBS): N/A

OPTIONAL INFORMATION:

Appearance/Odor: Orange free-flowing granular powder / Citrus scent  
Solubility in water: Complete  
Specific Gravity: 60 lbs/cu ft

KA-POW  
DN 4530

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION: U.N. CLASSIFICATION:  
OSHA CLASS N/A PER DOT N/A  
DOT CLASS N/A PER IMCO N/A

FLASH POINT: N/A

LEL: N/A

UEL: N/A

METHOD: N/A

EXTINGUISHING MEDIA: N/A

UNUSUAL FIRE AND EXPLOSION HAZARDS:  
None known. Addition of water generates heat.

SPECIAL FIREFIGHTING PROCEDURE:  
Do not use water on material itself. Use media suitable for surrounding fire. If large quantities of combustibles are involved, use water in flooding quantity as spray or fog. Use adequate personnel protection. Avoid breathing dust and fumes from burning material.

SECTION V - REACTIVITY DATA

STABILITY: STABLE

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

HAZARD DECOMPOSITION PRODUCTS:  
Carbon dioxide upon acid contact.

CONDITIONS TO AVOID:  
Contact with acids, acidic solutions, and soft metals.

INCOMPATIBILITY (MATERIALS TO AVOID):  
Acids, soft metals.

D.O.T. EMERGENCY RESPONSE INFORMATION:  
\*\*\* NOT APPLICABLE \*\*\*

CORE  
DA 6631

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

MANUFACTURED FOR:  
Drummond American Corporation  
600 Corporate Woods Pkwy.  
Vernon Hills, IL 60061

IN CASE OF EMERGENCY CALL:  
ROCKY MOUNTAIN POISON & DRUG CENTER  
COLLECT AT: (303) 623-5716

DATE OF PREPARATION:  
02/01/98

INFORMATION TELEPHONE NUMBER  
(847) 913-9313

SECTION I - IDENTITY

PRODUCT NUMBER DA 6631  
PRODUCT NAME CORE  
PRODUCT CLASS LUBRICANTS

SECTION II - INGREDIENTS

INGREDIENT	CAS NUMBER	%	ACGIH			
			TLV PPM	MG/ M <sup>3</sup>	PEL PPM	STEL PPM
HEXANE *	110-54-3	1-10	50	N/D	50	N/D
PROPANE/ISOBUTANE/N-BUTANE	74-98-6	10-20	1000	N/D	1000	N/D
NAPHTHENIC OIL	64742-52-5	40-50	5	N/D	N/D	N/D
RESIDUAL OIL	64742-62-7	40-50	5	N/D	N/D	N/D

\*THIS CHEMICAL IS SUBJECT TO  
S.A.R.A. TITLE III, SECTION 313  
REPORTING.

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT (degrees F): 159  
VAPOR DENSITY: HEAVIER THAN AIR  
EVAPORATION RATE: SLOWER THAN ETHER  
PERCENT VOLATILE (By Weight): N/A WEIGHT PER GALLON (LBS): N/A

OPTIONAL INFORMATION:  
Appearance and Odor: Black oil, solvent odor.  
Specific Gravity: 0.8  
Solubility in Water: Nil  
Evaporation Rate (Butyl Acetate=1): >1

CORE  
DA 6631

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION: OSHA CLASS N/A  
DOT CLASS N/A U.N. CLASSIFICATION:  
PER DOT N/A  
PER IMCO N/A

FLASH POINT: < 0°F

LEL: 1.8

UEL: 9.5

METHOD: TAG OPEN CUP

AEROSOL PRODUCT: TREAT AS CYLINDER OF COMPRESSED GAS

EXTINGUISHING MEDIA: CO2 DRY CHEMICAL WATER FOG

UNUSUAL FIRE AND EXPLOSION HAZARDS:  
Heated cans may burst.

SPECIAL FIREFIGHTING PROCEDURE:  
Aerosol cans may rupture when heated.

SECTION V - REACTIVITY DATA

STABILITY: STABLE

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

HAZARD DECOMPOSITION PRODUCTS:  
In fire will decompose to carbon dioxide and water.

CONDITIONS TO AVOID:  
Avoid contact with any source of ignition.

INCOMPATIBILITY (MATERIALS TO AVOID):  
Strong oxidizing agents, strong acids or bases.

D.O.T. EMERGENCY RESPONSE INFORMATION:  
\*\*\*NOT APPLICABLE\*\*\*

SECTION VI - HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE:

INHALATION: Shortness of breath, dizziness, and lightheadedness.  
EYE CONTACT: May cause irritation.  
SKIN CONTACT: May cause slight irritation, can lead to dermatitis.  
INGESTION: May cause chemical pneumonia if aspirated into lungs.

PRIMARY ROUTE(S) OF ENTRY: DERMAL INHALATION INGESTION EYES

MEDICAL CONDITIONS PRONE TO OVEREXPOSURE:  
None known.

TARGET ORGANS AFFECTED:  
Kidney, Eye, Liver, and Nervous System (in laboratory animals with chronic overexposure).

CARCINOGENICITY:  
None of the chemicals in this product are list by NTP, IARC, or OSHA as a carcinogen.

EMERGENCY AND FIRST AID PROCEDURES:  
EYES: Flush with large amounts of water and seek medical attention.  
INGESTION: Do not induce vomiting. Give water and seek medical attention.  
SKIN: Remove contaminated clothing and wash with soap and water.  
INHALATION: Move to fresh air.  
\*\*\* If irritation persists, seek medical attention. \*\*\*

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:  
Ventilate area. Remove all sources of ignition. Clean up with inert material and place in a container for disposal.

WASTE DISPOSAL METHOD:  
Dispose of in accordance with local, state, and federal regulations.

SECTION VIII - SAFE HANDLING AND USE INFORMATION

RESPIRATORY PROTECTION:

None necessary under normal conditions. If the TLV is exceeded, a NIOSH/OSHA approved respirator is recommended.

VENTILATION:

Use ventilation as necessary to control vapor concentrations.

PROTECTIVE GLOVES:

Chemical resistant gloves (polyvinyl alcohol, polyethelene) are recommended.

EYE PROTECTION:

Safety glasses or goggles are recommended.

OTHER PROTECTIVE EQUIPMENT:

None known.

HYGIENIC PRACTICES:

WASH HANDS BEFORE EATING OR USING THE WASHROOM. SMOKE ----  
IN SMOKING AREAS ONLY.

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING:

Do not store in direct sunlight, near open flames, or at temperatures exceeding 120°F. Do not smoke while using this product.

OTHER PRECAUTIONS:

Keep out of reach of children. Read entire label prior to use.

SECTION X - OTHER INFORMATION

-----NFPA INDEX-----	PREPARED BY:	Heather Buck
HEALTH 1		Drummond American Corporation
FLAMMABILITY 3		600 Corporate Woods Parkway
REACTIVITY 0		Vernon Hills, Illinois 60061
TLV Threshold Limit Value	ND No Data	..NFPA HAZARD INDEX..
PEL Permissible Exposure Level	LEL Lower Explosive Level	SEVERE HAZARD 4
NFPA National Fire Protection Association	NE Not Established	SERIOUS HAZARD 3
CAS Chemical Abstract Service	PPM Parts Per Million	MODERATE HAZARD 2
NTP National Toxicology Program	D.O.T. Department of Transportation	SLIGHT HAZARD 1
OSHA Occupational Safety and Health Admin.	N/A Not Applicable	MINIMAL HAZARD 0
IARC International Agency for Research on Cancer	M <sup>3</sup> Approximate milligrams of substance per cubic meter of air	
STEL Short Term Exposure Limit, duration is for 15 minutes		

STOP-GAP GRAY  
DN 4520

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

MANUFACTURED FOR:  
Drummond American Corporation  
600 Corporate Woods Pkwy.  
Vernon Hills, IL 60061

IN CASE OF EMERGENCY CALL:  
ROCKY MOUNTAIN POISON & DRUG CENTER  
COLLECT AT: (303) 623-5716

DATE OF PREPARATION:  
02/01/98

INFORMATION TELEPHONE NUMBER  
(847) 913-9313

SECTION I - IDENTITY

PRODUCT NUMBER DN 4520  
PRODUCT NAME STOP-GAP GRAY  
PRODUCT CLASS PATCHING

SECTION II - INGREDIENTS

INGREDIENT	CAS NUMBER	%	ACGIH TLV PPM	MG/ M <sup>3</sup>	PEL PPM	STEL PPM
CALCIUM CARBONATE	1317-65-3		ND	ND	ND	ND
POLYURETHANE RESIN	N/A		ND	ND	ND	ND
DIISODECYL PHTHALATE	26761-40-0		ND	ND	ND	ND
HYDROGENATED CASTOR WAX	N/A		ND	ND	ND	ND
BUTYL ACETATE*	123-86-4	1-3	150	ND	150	200

\* THIS CHEMICAL IS SUBJECT TO  
S.A.R.A. TITLE III, SECTION 313  
REPORTING.

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT (degrees F): N/A  
VAPOR DENSITY: Heavier than air  
EVAPORATION RATE: = n-Butyl Acetate  
PERCENT VOLATILE (By Weight): 2.100 WEIGHT PER GALLON (LBS): 13.50

OPTIONAL INFORMATION:

Appearance/Odor: gray polyurethane paste-like sealant; mild odor.  
Volatiles volume %: 1.3  
Liquid Density: Heavier than Water  
V.O.C: 0.3 lb/gal

STOP-GAP GRAY  
DN 4520

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION: OSHA CLASS N/A  
DOT CLASS N/A  
U.N. CLASSIFICATION: PER DOT N/A  
PER IMCO N/A

FLASH POINT: 72°F

LEL: 1.4

UEL: 7.5

METHOD: TAG CLOSED CUP

EXTINGUISHING MEDIA: FOAM CO2 DRY CHEMICAL SAND

UNUSUAL FIRE AND EXPLOSION HAZARDS:  
None Known.

SPECIAL FIREFIGHTING PROCEDURE:  
Self contained breathing apparatus and protective clothing should be worn in fighting fires involving chemicals.

SECTION V - REACTIVITY DATA

STABILITY: STABLE

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

HAZARD DECOMPOSITION PRODUCTS:  
Thermal decomposition may produce carbon monoxide, carbon dioxide, sulfur dioxide, and nitrogen dioxide.

CONDITIONS TO AVOID:  
Extreme heat, sparks, flames.

INCOMPATIBILITY (MATERIALS TO AVOID):  
Strong oxidizing agents.

D.O.T. EMERGENCY RESPONSE INFORMATION:  
\*\*\*NOT APPLICABLE\*\*\*



# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

01/21/98  
PAGE 1 OF 3

MANUFACTURING COMPANY  
IN MAINTENANCE PRODUCTS

ISSUE DATE: 04/23/90 ZEP CINCINNATI CONSUMER  
SUPERSEDES: 06/15/88 PRODUCT NUMBER: 1783

Reagent - Liquid

SECTION I - EMERGENCY CONTACTS

ZEP MANUFACTURING COMPANY TELEPHONE: (404) 852-1490 BETWEEN 8:00 AM-5:00 PM (EST)  
P.O. BOX 2015 NON-OFFICE HOURS, WEEKENDS, AND HOLIDAYS: AREA CODE 770  
ATLANTA, GEORGIA 30301 432-4200, 392-1480, 485-8160, 552-8886, 432-2873, 424-4789  
LOCAL POISON CONTROL CENTER .....  
TRANSPORTATION EMERGENCY: CHEMTEC: TOLL FREE 1-800-424-9300 ALL CALLS RECORDED  
(770) 922-0923 OR DISTRICT OF COLUMBIA (202) 483-7616 ALL CALLS RECORDED

SECTION II - HAZARDOUS INGREDIENTS

### DESIGNATIONS

	TLV	EFFECTS	% IN
	(PPM)	(SEE REVERSE)	PROD.
** ISOPROPYL ALCOHOL ** ipa; dimethylcarbinol; 2-pro- 400	IRI	FBL	5-10
panol; CASE 67-63-0; RIEDEL N18050000; OSHA PEL-400			
PPM; OSHA/ACGIH STEL-500 PPM			

SECTION III - HEALTH HAZARD DATA

SPECIAL NOTE: MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

### ACUTE EFFECTS OF OVEREXPOSURE:

Eye irritant. Eye contact may produce stinging, burning, inflammation, and in extreme cases may produce corneal damage. Exposure may be irritating to skin, and upper respiratory tract. Accumulation of harmful quantities of vapor is predicted by severe irritation which makes overexposure unlikely. Overexposure can result in mild narcotic effects, including flushing, headache, dizziness, and nausea.

Ingredients in this product may aggravate existing skin, eye, or respiratory disorders.



ES125 -01  
 Effective: 05/13/86

Ethylene Glycol

Page: 1  
 Issued: 05/13/86

SECTION I - PRODUCT IDENTIFICATION

Product Name: Ethylene Glycol  
 Formula: HOCH<sub>2</sub>CH<sub>2</sub>OH  
 Formula Wt: 62.07  
 CAS No.: 00107-21-1  
 NIOSH/RTCS No.: KW2975000  
 Common Synonyms: 1,2-Ethanediol; EG; Glycol; 1,2-Dihydroxyethane  
 Product Codes: 9140, L715, 9300, 5387

PRECAUTIONARY LABELLING

BAKER SAF-T-DATA™ System

HEALTH	1	FLAMMABILITY	1	REACTIVITY	1	CONTACT	1
SLIGHT		SLIGHT		SLIGHT		SLIGHT	

Laboratory Protective Equipment



Precautionary Label Statements

**WARNING!**  
 CAUSES IRRITATION  
 HARMFUL OR FATAL IF SWALLOWED  
 Avoid contact with eyes, skin, clothing.  
 Keep in tightly closed container. Wash thoroughly after handling.

SECTION II - HAZARDOUS COMPONENTS

Component	%	CAS No.
-----------	---	---------

Ethylene Glycol 90-100 00107-21-1

SECTION III - PHYSICAL DATA

Boiling Point: 197°C ( 387°F) Vapor Pressure(mmHg): 0.06  
 Melting Point: -13°C ( 9°F) Vapor Density(air=1): 2.1



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

# MATERIAL SAFETY DATA SHEET AND SAFE HANDLING AND DISPOSAL INFORMATION

1-877-1-BUY-ZEP (1-877-428-9937)

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

SOLD TO:

00652

(3177)  
MISSOURI SURPLUS PROPERTY  
117 N RIVERSIDE DR  
JEFFERSON CITY MO 65101

ISSUE DATE: 05/31/00  
SUPERSEDES: 11/29/89  
ZEP FORMULA 4358 E  
Prod No: 0378 Car Wash - Powder

Date printed: 08/05/00

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680  
MEDICAL EMERGENCY: (770) 439-4200  
(770) 432-2873  
(770) 424-4789  
(770) 424-2048  
(770) 455-8160  
(770) 552-8836  
TRANSPORTATION EMERGENCY: (770) 922-0923  
CHEMTREC: (800) 424-9300  
DISTRICT OF COLUMBIA: (202) 483-7616  
TOLL FREE-CALLS RECORDED  
ALL CALLS RECORDED

A25224

### SECTION II - HAZARDOUS INGREDIENTS

\*\* SODIUM CARBONATE \*\* soda ash; carbonic acid; disodium salt;  
CAS# 497-19-8; RTECS# VZ4050000; OSHA/ACGIH DUST LIMIT =  
15mg/m3  
\*\* SODIUM DODECYLBENZENE SULFONATE \*\* linear alkyl amyl sodium  
sulfonate; CAS# 25155-30-0; RTECS# DB6825000; OSHA PEL/N/D

(PPM) (SEE NOTICE) % IN  
N/D IRR 5-15  
N/D IRR < 5

### SECTION III - HEALTH HAZARD DATA

SPECIAL NOTE: MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.  
ACUTE EFFECTS OF OVEREXPOSURE:  
This product can be an eye irritant. Inflammation of eye tissue is characterized by redness, watering, and/or itching.  
CHRONIC EFFECTS OF OVEREXPOSURE:  
There are no known effects from chronic exposure to this product.  
None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.  
PEL/TLV: Not established. PRIMARY ROUTES OF ENTRY: N/A

Hazus CODES: HEALTH: 0; FLAM: 0; REACT: 0; PERS: PROTECT. A; CHRONIC HAZ: NO

### FIRST AID PROCEDURES

SKIN: Flush contaminated skin with plenty of water. Consult a physician if irritation develops.  
EYES: Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
INHALE: Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
INGEST: If this product is swallowed, do not induce vomiting. If victim is conscious give plenty of water to drink. Get medical attention at once.

### SECTION IV - SPECIAL PROTECTION INFORMATION

PROTECTIVE CLOTHING: The use of neoprene, nitrile or natural rubber gloves is strongly recommended, especially for prolonged contact.  
EYE PROTECTION: Use of light-fitting safety glasses or goggles is strongly recommended, especially when wearing contact lenses.  
RESPIRATORY PROTECTION: No special measures are required.  
VENTILATION: No special measures are required.

### SECTION V - PHYSICAL DATA

BOILING POINT (°F): N/A  
VAPOR PRESSURE (mmHg): N/A  
VAPOR DENSITY(AIR=1): N/A  
SOLUBILITY IN WATER: 12G/100ML MAX.  
VOC CONTENT (CONCENTRATE): N/A  
APPEARANCE AND ODOR: A RED, FREE FLOWING PLEASANTLY SCENTED POWDER.

SPECIFIC GRAVITY: N/A  
EVAPORATION RATE (=1): N/A  
PH(CONCENTRATE): N/A  
PH(USE DILUTION OF 1%): 9.4

### SECTION VI - FIRE AND EXPLOSION DATA

FLASH POINT(F) (METHOD USED): None  
FLAMMABLE LIMITS: LEL: N/A UEL: N/A  
EXTINGUISHING MEDIA: Noncombustible.  
SPECIAL FIRE FIGHTING: None  
UNUSUAL FIRE HAZARDS: None

### SECTION VII - REACTIVITY DATA

STABILITY: Stable  
INCOMPATIBILITY(AVOID): None  
POLYMERIZATION: Will not occur.  
HAZARDOUS DECOMPOSITION: NONE

### SECTION VIII - SPILL AND DISPOSAL PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:  
Observe safety precautions in sections 4 & 9 during clean-up. Sweep up uncontaminated product and place in a container for reuse. Place contaminated materials in a suitable waste container and rinse area well with water.  
WASTE DISPOSAL METHOD:  
Product is not considered a hazardous waste under RCRA. Unusable material should be drummed and taken to a chemical or industrial landfill, or if permitted put into solution with water and flushed into a sanitary sewer. Neutralization of pH may be a prerequisite for sewer disposal. Consult local, state, and federal agencies for proper method of disposal in your area.  
RCRA HAZ. WASTE NOS: N/A

### SECTION IX - SPECIAL PRECAUTIONS

AUTONS TO BE TAKEN WHEN HANDLING AND STORING:  
Do not breathe dust.  
Keep out of the reach of children.

### SECTION X - REGULATORY INFORMATION

DOT PROPER SHIPPING NAME: INDUSTRIAL CLEANERS, NODRY  
NOTE: DOT information applies to larger package sizes of affected products. For some products, DOT may require alternate names and labeling in accordance with packaging group requirements.  
DOT HAZARD CLASS: DOT PACKING GROUP:  
DOT ID NUMBER: DOT LABEL/PLACARD:  
EPA TSCA CHEMICAL INVENTORY - ALL INGREDIENTS ARE LISTED  
(Continued on Page: 2)

# MATERIAL SAFETY DATA SHEET

## AND SAFE HANDLING AND DISPOSAL INFORMATION



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

MISSOURI SURPLUS  
PROPERTY - JANITORIAL  
117 NO RIVERSIDE DR  
JEFFERSON CITY, MO 65101

10/30/92  
ISSUE DATE: 03/03/90  
SUPERSEDES: 06/05/89  
ZEPION  
PRODUCT NO.: 9278

Aerosol Lubricant

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1380 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (404) 433-2973 NON-OFFICE HOURS, WEEKENDS  
(404) 351-2552 AND HOLIDAYS, PLEASE CALL YOUR  
(404) 432-2873 LOCAL POISON CONTROL  
TRANSPORTATION EMERGENCY: (404) 922-0923  
CHEMTREC: 1-800-424-9300 TOLL-FREE - ALL CALLS RECORDED  
DISTRICT OF COLUMBIA: (202) 483-7616 ALL CALLS RECORDED

### SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PROD.
@ ~ 1,1,1-TRICHLOROETHANE ~ methyl chloroform chloroethene, CAS # 71-55-6, RTECS # KJ2975000, OSHA PEL-350	350	IRR CNS	70-80
@ ~ 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE ~ fluorocarbon 113, freon 113, freon II, CAS # 76-13-1, RTECS # KJ4000000, OSHA PEL 1000 PPM	1000	EIR CNS	<5

@ Identifies chemicals listed under SARA-Section 313 for release reporting

### SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

#### Acute Effects of Overexposure:

Inhalation of vapor can produce central nervous system depression, characterized by dizziness, headache, nausea, cardiac and/or respiratory depression, stupor, unconsciousness and death, in extreme cases. Exposure to high concentrations of vapor, by direct contact or inhalation, can be irritating to mucous membranes, such as nose and upper respiratory tract. Severe eye exposure to liquid can cause reversible eye damage. Skin contact may cause a burning sensation and reddening of the skin. Ingestion of solvent to the lungs, as in aspiration of vomitus fluids, may cause chemical pneumonia. Exposure to this product may aggravate existing respiratory and chronic conditions. Inhalation of aerosol mist may produce chemical pneumonia.

#### Chronic Effects of Overexposure:

Repeated or prolonged contact by inhalation or skin absorption may produce liver or kidney damage or damage to the central nervous system, characterized by tingling or numbness in the extremities, blurred vision or confusion. Skin, which is defatted by repeated exposure to solvents, is more susceptible to irritation, infection, and dermatitis. Exposure to some ingredients in this product can aggravate existing liver disease or heart rhythm disorders. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

Est'd PEL/TLV: 350 PPM (NIOSH)

Primary Routes of Entry: inh.

HMIS Codes: HEALTH 2; FLAM 1; REACT 1; PERS PROTECT X; CHRONIC HAZ YES

#### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** Move exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Get medical attention immediately.  
**Ingest:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

### SECTION IV - SPECIAL PROTECTION INFORMATION

**Protective Clothing:** Wear viton gloves or use gloves with demonstrated resistance to the ingredients in this product.  
**Eye Protection:** Use tight-fitting safety glasses. Contact lenses should not be worn when working with this material.  
**Respiratory Protection:** If ventilation is inadequate, wear a properly fitting MSHA or OSHA-approved respirator.  
**Ventilation:** Ventilation should be equal to outdoors. Use exhaust fans and/or exhaust hood in enclosed spaces.

### SECTION V - PHYSICAL DATA

Boiling Point (°F):	165F	Specific Gravity:	1.3	Vapor Pressure (mmHg):	100
Percent Volatile by Volume (%):	98%	Vapor Density (air = 1):	4.6	Evaporation Rate (BUTYL ACETATE = 1):	~ 6
Solubility in Water:	NEGLIGIBLE	pH (concentrate):	N/A	pH (use dilution of N/A.):	N/A
Appearance and Odor:	MILKY-TINNY LIQUID HAVING A MILD SOLVENT ODOR				

### SECTION VI - FIRE AND EXPLOSION DATA

Flash Point (°F) (method used): NOT FLAMMABLE (CSMA)  
Flammable Limits: LEL 6% UEL 16.7%  
Extinguishing Media: NOT COMBUSTIBLE  
Special Fire Fighting: DIRECT STREAM OF WATER ONTO INTACT CONTAINERS  
Unusual Fire Hazards: Wear self-contained positive pres. Breathing apparatus.



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301  
SOLD TO:

(317)  
MISSOURI SURPLUS  
PROPERTY - JANITORIAL  
JEFFERSON CITY MO 65101

# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

ISSUE DATE: 12/03/96  
SUPERSEDES: 06/23/93  
ZEP GROOVY  
Prod No: 0239

Date printed: 09/29/96

Aerosol Anti-Seize Agent

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680  
MEDICAL EMERGENCY: (770) 439-4200  
(770) 432-2873  
(770) 424-4789  
(770) 424-2048  
(770) 455-8160  
(770) 552-8836  
TRANSPORTATION EMERGENCY: (770) 922-0923  
CHEMTRAC: (800) 424-9300  
DISTRICT OF COLUMBIA: (202) 483-7616

BETWEEN 8:00 AM - 5:00 PM (EST)  
NON OFFICE HOURS, WEEKENDS  
AND HOLIDAYS, PLEASE CALL  
LOCAL POISON CONTROL

TOLL FREE-CALLS RECORDED  
ALL CALLS RECORDED

A25224

### SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	(PPM)	EFFECTS (SEE NOTICE)	% IN PROD.
** ISOPARAFFINIC SOLVENT (BOILING RANGE 113-143C) ** Isopar E, hydroreated heavy naphtha (petroleum), CAS# 64742-46-9; RTECS# NONE	400	FBL CNS	< 30
@** COPPER ** copper metal; CAS# 7440-50-8; RTECS# GL5325000; OSHA PEL : TWA (dust/mist): 1 mg/m3; ACGIH TLV (dust, mist): 1 mg/m3		TOX	10-20
** ODORLESS ALIPHATIC NAPHTHA ** heavy alkylate petroleum naphtha; odorless mineral spirits; CAS# 64741-65-7; RTECS# NONE; OSHA PEL - 100ppm	100	CBL CNS	< 5
** HYDROCARBON PELLELANT ** CAS# 64741-65-7; RTECS# NONE; OSHA PEL 1000 ppm	1000	FBL	< 40
@ IDENTIFIED CHEMICALS LISTED UNDER SARA-SECTION 313 FOR RELEASE REPORTING.			

### SECTION III - HEALTH HAZARD DATA

SPECIAL NOTE: MSDS data pertains to the product as dispensed from the container. Adverse health effects will not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are followed.

#### HE EFFECTS OF OVEREXPOSURE:

Some solvents in this product, when inhaled, or absorbed through the skin in harmful quantities, may produce central nervous system depression characterized by headache, nausea, dizziness and stupor. Vapors or spray mists may be irritating to nasal and respiratory tract. Product may be irritating to skin and eyes resulting in redness, itching or burning. Introduction of solvents, as in aspiration of vomitus fluid, may produce chemical pneumonia. Existing respiratory disorders and skin diseases may be aggravated by exposure.

**CHRONIC EFFECTS OF OVEREXPOSURE:**  
Skin which is repeatedly detailed by contact with this product may be more susceptible to irritation, infection, or dermatitis. Some of the ingredients are listed as carcinogens by IARC, NTP, or OSHA. EST'D PEL/TLV: Not established PRIMARY ROUTES OF ENTRY: Skin

HMS CODES: HEALTH 2; FLAM. 4; REACT. 0; PERS. PROTECT. B ; CHRONIC HAZ. NO

#### FIRST AID PROCEDURES:

**SKIN:** Wash contaminated skin with soap or a mild detergent. Get medical attention if irritation develops.  
**EYES:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**INHALE:** Move exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Get medical attention immediately.  
**INGEST:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

### SECTION IV - SPECIAL PROTECTION INFORMATION

**PROTECTIVE CLOTHING:** The use of natural rubber, neoprene, or nitrile gloves is recommended if prolonged skin contact is expected.  
**EYE PROTECTION:** Use of light-fitting safety glasses or goggles is strongly recommended, especially when wearing contact lenses.  
**RESPIRATORY PROTECTION:** Wear a properly fitting MSHA or OSHA-approved respirator when using this product or when working in a use area.  
**VENTILATION:** Provide local exhaust/ventilation as needed to keep concentration of vapors below exposure limits (PEL/TLV).

### SECTION V - PHYSICAL DATA

**BOILING POINT (F):** 102  
**VAPOR PRESSURE (mmHg):** N/D  
**VAPOR DENSITY(AIR=1):** N/D  
**SOLUBILITY IN WATER:** NEGLIGIBLE  
**VOC CONTENT (CONCENTRATE):** 75.0%  
**APPEARANCE AND ODOR:** GRAY; VISCOUS LIQUID WITH MILD, SWEETISH ODOR

**SPECIFIC GRAVITY:** N/D  
**EVAPORATION RATE (N/D=1):** N/A  
**PH(CONCENTRATE):** N/A  
**PH(USE DILUTION OF N/A):** N/A

### SECTION VI - FIRE AND EXPLOSION DATA

**FLASH POINT (C) (METHOD USED):** Extremely Flammable (CSMA)  
**FLAMMABLE LIMITS:** LEL: N/D UEL: N/D  
**EXTINGUISHING MEDIA:** Carbon dioxide, dry chemical and foam.  
**SPECIAL FIRE FIGHTING:** Wear self-contained positive pres. breathing apparatus.  
**UNUSUAL FIRE HAZARDS:** Direct water onto intact containers to prevent bursting.

### SECTION VII - REACTIVITY DATA

**STABILITY:** Stable  
**INCOMPATIBILITY(AVOID):** Strong alkalis, oxidizers, and active metals.  
**POLYMERIZATION:** Will not occur.  
**HAZARDOUS DECOMPOSITION:** Carbon dioxide, carbon monoxide, and other unidentified organic compounds.

### SECTION VIII - SPILL AND DISPOSAL PROCEDURES

**DO NOT BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:**  
Take necessary precautions in sections 4 & 9 during spill clean-up. Large spills are unlikely due to packaging. Spill may be absorbed on an inert absorbent material (eg Zep-O-Zorb), and placed in a suitable container for disposal. Wash area thoroughly with a detergent solution and rinse well with water.  
**WASTE DISPOSAL METHOD:**  
Product is consumed in use. Do not crush, puncture or incinerate spent containers. Large numbers of aerosol containers may require handling as a hazardous waste, but in most states total hazardous waste quantities less than 220 lbs per month may allow disposal in a chemical or industrial waste landfill. Consult local, state and federal agencies for the proper disposal method in your area.  
**HCPRA HAZ. WASTE NOS.:** D001

# MATERIAL SAFETY DATA SHEET

## AND SAFE HANDLING AND DISPOSAL INFORMATION

5205



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

MISSOURI SUPRPLUS (317)  
PROPERTY-JANITORIAL  
1172 RIVERSIDE  
JEFFERSON CITY, MO 65101

1/12/8/96  
ISSUE DATE: 04/07/95  
SUPERSEDES: 11/16/93  
ZEP IRONCLAD  
PRODUCT NO.: 0152

Aerosol Corrosion Inhibitor

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680  
MEDICAL EMERGENCY: (770) 439-4200  
(770) 432-2873  
(770) 424-4789  
(770) 392-1480  
(770) 455-8160  
(770) 552-8836  
TRANSPORTATION EMERGENCY: (770) 922-0923  
CHEMTREC: 1-800-424-9300  
DISTRICT OF COLUMBIA: (202) 483-7616  
TOLL-FREE - ALL CALLS RECORDED  
ALL CALLS RECORDED

### SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS  
\*\* PETROLEUM SPIRITS \*\* w/80 naphtha; refined solvent naphtha; CAS # 8032-32-4; RTECS # O16180000; OSHA PEL-300 PPM; OSHA STEL-400 PPM  
\*\* BLEND OF (ISOBUTANE; CAS # 75-28-5; RTECS # TZ4300001 & [PROPANE; CAS # 74-98-6; RTECS # TX2775000] 800 COR FBL 25-35 & (n-BUTANE; CAS # 106-97-8; RTECS # E14200000) OSHA PEL-1000 ppm \*\*

### SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

#### Acute Effects of Overexposure:

The solvents in this product, when inhaled or absorbed in harmful quantities, may produce central nervous system depression characterized by headache, nausea, dizziness and stupor. Vapors or spray mists may be irritating to nasal and respiratory tract. Product may be irritating to skin and eyes resulting in redness, itching or burning. Introduction of solvents, as in aspiration of vomitus fluid, may produce chemical pneumonia. Existing respiratory disorders and skin diseases may be aggravated by exposure. Existing respiratory disorders or skin diseases may be aggravated by exposure.

#### Chronic Effects of Overexposure:

1) which is repeatedly detailed by contact with this product may be more susceptible to irritation, infection, or dermatitis. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

Est'd PEL/TLV: Not established

Primary Routes of Entry: Inh.

HMS Codes: HEALTH 2;FLAM. 3;REACT. 0;PERS. PROTECT. B ;CHRONIC HAZ. NO

#### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes; occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** Move exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Get medical attention immediately.  
**Ingest:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

### SECTION IV - SPECIAL PROTECTION INFORMATION

**Protective Clothing:** Wear nitrile gloves or use gloves with demonstrated resistance to the ingredients in this product.  
**Eye Protection:** Wear splash-proof safety goggles especially if contact lenses are worn.  
**Respiratory Protection:** In the unlikely event that exposure levels exceed the PEL/TLV, use an organic vapor respirator (eg Zep 2211).  
**Ventilation:** Provide local exhaust/ventilation as needed to keep concentration of vapors below exposure limits (PEL/TLV).

### SECTION V - PHYSICAL DATA

**Boiling Point (°F):** N/D  
**Percent Volatile by Volume (%):** ~ 80  
**Solubility in Water:** NEGLIGIBLE  
**Appearance and Odor:** SLIGHTLY VISCOUS, TAN, OPAQUE LIQUID WITH SOLVENT ODOR  
**Specific Gravity:** 0.845  
**Vapor Density (air = 1):** N/D  
**pH (concentrate):** N/A  
**Vapor Pressure (mmHg):** N/D  
**Evaporation Rate (ND = 1):** N/A  
**pH (use dilution of N/A):** N/A

### SECTION VI - FIRE AND EXPLOSION DATA

**Flash Point (°F) (method used):** Extremely Flammable (CSMA)  
**Flammable Limits:** LEL N/D UEL N/D  
**Extinguishing Media:** Carbon dioxide, dry chemical and foam.  
**Special Fire Fighting:** Wear self-contained positive pres. breathing apparatus.  
**Unusual Fire Hazards:** Direct water onto intact containers to prevent bursting.



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

# MATERIAL SAFETY DATA SHEET AND SAFE HANDLING AND DISPOSAL INFORMATION

1-877-1-BUY-ZEP (1-877-428-9937)

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

SOLD TO:

00020

(317)  
MISSOURI SURPLUS PROPERTY  
117 N RIVERSIDE DR  
JEFFERSON CITY MO 65101

ISSUE DATE: 09/28/00  
SUPERSEDES: 10/06/95  
ZEP 50  
Prod No: 0150  
Aerosol Engine Degreaser

Date printed: 10/28/00

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680  
MEDICAL EMERGENCY: (770) 439-4200  
(770) 432-2873  
(770) 424-4789  
(770) 424-2048  
(770) 455-8160  
(770) 552-8836  
TRANSPORTATION EMERGENCY: (770) 922-0923  
CHEMTRAC: (800) 424-9300  
DISTRICT OF COLUMBIA: (202) 483-7616

BETWEEN 8:00 AM - 5:00 PM (EST)  
NON OFFICE HOURS, WEEKENDS  
AND HOLIDAYS, PLEASE CALL  
LOCAL POISON CONTROL

TOLL FREE CALLS RECORDED  
ALL CALLS RECORDED

A25224

### SECTION II - HAZARDOUS INGREDIENTS

**DESIGNATIONS**

\*\* MONOETHANOLAMINE \*\* 2-aminoethanol; MEA; CAS# 141-43-5;  
RTECS# K15775000; OSHA PEL-3 PPM; OSHA/ACGIH STEL-6 PPM  
\*\* D-LIMONENE \*\* orange distillate; citrus terpene;  
cyclohexene, 1-methyl-4-(1-methyl-2-propenyl)-; (R); CAS#  
5989-27-5; RTECS# GW6360000; OSHA PEL N/D  
\*\* HEAVY AROMATIC NAPHTHA \*\* solvent naphtha (petroleum), heavy  
aromatics; CAS# 64742-94-5; RTECS# NONE; Supplier TWA - 100 ppm;  
OSHA PEL N/D  
\*\* BLEND OF ISOBUTANE; GAS# 75-28-5; RTECS# TZ43000001 &  
[PROPANE; GAS# 74-98-6; RTECS# TX2750001] & [n-BUTANE; GAS#  
106-97-8; RTECS# E14200000] OSHA PEL-1000 ppm

(PPM) EFFECTS (SEE NOTICE) % IN PROD.

3	COR CNS CBL	< 5
N/D	CBL SEN	5-15
N/D	CNS CBL	5-15
800	FBL	< 10

### SECTION III - HEALTH HAZARD DATA

SPECIAL NOTE: MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are followed.

#### EFFECTS OF OVEREXPOSURE:

Characterized with this product may irritate eyes and skin. Inflammation of the eye is characterized by redness, watering, and itching. Skin inflammation is characterized by itching, scaling, reddening, or occasionally, blistering.  
One of the ingredients in this product has caused sensitization reactions in a small percentage of the general population.  
**CHRONIC EFFECTS OF OVEREXPOSURE:**  
Repeated or prolonged exposure by inhalation or skin absorption may produce liver or kidney damage, or damage to the central nervous system. Skin which is repeatedly contacted with this product may be more susceptible to irritation, infection, or dermatitis.  
EST D PEL/TLV: Not established PRIMARY ROUTES OF ENTRY: Inh. Skin.

HMS CODES: HEALTH 1; FLAM; 2; REACT 0; PERS; PROTECT B; CHRONIC HAZ NO

#### FIRST AID PROCEDURES:

**SKIN:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**EYES:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention if irritation persists.  
**INHALE:** Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
**INGEST:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

### SECTION IV - SPECIAL PROTECTION INFORMATION

**PROTECTIVE CLOTHING:** Wear neoprene, nitrile, or natural rubber gloves or gloves with proven resistance to the ingredients listed.  
**EYE PROTECTION:** Wear tight-fitting safety glasses when using or handling this product.  
**RESPIRATORY PROTECTION:** Avoid inhalation of spray mists, and do not direct spray toward people.  
**VENTILATION:** Provide local exhaust/ventilation as needed to keep concentration of vapors below exposure limits (PEL/TLV).

### SECTION V - PHYSICAL DATA

**BOILING POINT (F):** 212  
**VAPOR PRESSURE (mmHg):** N/D  
**VAPOR DENSITY (AIR=1):** N/D  
**SOLUBILITY IN WATER:** N/D  
**VOC CONTENT (CONCENTRATE):** 27.4%  
**APPEARANCE AND ODOR:** A THIN, MILKY LIQUID WITH AN ORANGE/CITRUS ODOR.

**SPECIFIC GRAVITY:** 0.996  
**EVAPORATION RATE (N/D=1):** N/D  
**PH (CONCENTRATE):** N/A  
**PH (USE DILUTION OF):** N/A

### SECTION VI - FIRE AND EXPLOSION DATA

**FLASH POINT (F) (METHOD USED):** Nonflammable  
**FLAMMABLE LIMITS, LEL: N/D UEL: N/D**  
**EXTINGUISHING MEDIA:** Carbon dioxide, dry chemical, water fog, foam.  
**SPECIAL FIRE FIGHTING:** Wear self-contained positive pres. breathing apparatus.  
**UNUSUAL FIRE HAZARDS:** Direct water onto intact containers to prevent bursting.

### SECTION VII - REACTIVITY DATA

**STABILITY:** Stable  
**INCOMPATIBILITY (AVOID):** Heat, open flame, spark, and oxidizing agents.  
**POLYMERIZATION:** Will not occur.  
**HAZARDOUS DECOMPOSITION:** Carbon dioxide, carbon monoxide, and other unidentified organic compounds.

### SECTION VIII - SPILL AND DISPOSAL PROCEDURES

**STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:**  
Use safety precautions in sections 4 & 9 during spill clean-up. Large spills are unlikely due to packaging. Spill may be absorbed on an inert bent material (eg Zep-O-Zorb), and placed in a suitable container for disposal. Wash area thoroughly with a detergent solution and rinse well with water.

#### WASTE DISPOSAL METHOD:

Product is consumed in use.  
Do not crush, puncture or incinerate spent containers. Large numbers of aerosol containers may require handling as a hazardous waste, but in most states total hazardous waste quantities less than 220 lbs per month may allow disposal in a chemical or industrial waste landfill. Consult local state and federal agencies for the proper disposal method in your area.  
RCHA HAZ. WASTE NOS.: N/A

### SECTION IX - SPECIAL PRECAUTIONS

**PRECAUTIONS TO BE TAKEN WHEN HANDLING AND STORING:**  
Do not store at temperatures above 120F (39C) or in direct sunlight. Do not puncture or incinerate container.  
Keep product away from skin and eyes.

(Continued on Page: 2)



CLEAN ACROSS AMERICA AND THROUGHOUT THE WORLD™

# MATERIAL SAFETY DATA SHEET AND SAFE HANDLING AND DISPOSAL INFORMATION

1-877-1-BUY-ZEP (1-877-428-9937)

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

SOLD TO:

01362

(317)  
MISSOURI SURPLUS PROPERTY  
117 N RIVERSIDE DR  
JEFFERSON CITY MO 65101

ISSUE DATE: 01/24/01  
SUPERSEDES: 04/23/90  
ZEP 40  
Prod No: 0144

Date printed: 03/03/01

Aerosol Glass Cleaner

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (770) 439-4200 NON OFFICE HOURS, WEEKENDS AND HOLIDAYS, PLEASE CALL LOCAL POISON CONTROL  
(770) 432-2873  
(770) 424-4789  
(770) 424-2048  
(770) 453-8160  
(770) 552-8836

TRANSPORTATION EMERGENCY: (770) 922-0923

CHEMTREC: (800) 424-9300 TOLL FREE-CALLS RECORDED  
DISTRICT OF COLUMBIA: (202) 483-7616 ALL CALLS RECORDED

A25224

### SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS  
\*\* ISOPROPYL ALCOHOL \*\* ipa, dimethylcarbinol; 2-propanol; CAS# 67-63-0; RTECS# NT8050000; OSHA PEL-400 PPM; OSHA/ACGIH STEL-500 PPM  
@\*\* ETHYLENE GLYCOL MONOETHYL ETHER \*\* 2-butylcellosolve; CAS# 111-76-2; RTECS# K18575000; OSHA PEL (SKIN); 25 ppm  
\*\* BLEND OF ISOBUTANE: CAS # 75-28-5; RTECS# T743000001 & 1-PROPANE: CAS# 74-98-6; RTECS# TX2720000 & n-BUTANE: CAS# 106-97-8; RTECS# E34200000 - OSHA PEL-1000 ppm  
@ IDENTIFIERS CHEMICALS LISTED UNDER SARAA-SECTION 313 FOR RELEASE REPORTING.

### SECTION III - HEALTH HAZARD DATA

SPECIAL NOTE: MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

#### IRITANT EFFECTS OF OVEREXPOSURE:

Irritant: Eye contact may produce stinging, burning, inflammation, and in extreme cases may produce corneal damage. Exposure may be irritating to and upper respiratory tract. Accumulation of harmful quantities of vapor is precluded by severe irritation which makes overexposure unlikely.

Upper exposure can result in mild narcotic effects, including flushing, headache, dizziness, and nausea.

#### CHRONIC EFFECTS OF OVEREXPOSURE:

Repeated or prolonged, skin contact may produce some dryness of skin. Chronic effects from alcohol vapors are rare and would result from severe, prolonged, and repeated contact, which is usually precluded by irritation. In most extreme cases, narcosis, unconsciousness, and death could result. Animal studies indicate a potential for liver, kidney, or red blood cell damage. Relevance of these studies or exposure levels which might produce these effects in humans has not been established.

None of the hazardous ingredients are listed as carcinogens by IARC, NTP, & OSHA ESTD PELTV. Not established. PRIMARY ROUTES OF ENTRY: Inh, Skin

HMS CODES: HEALTH 1; FLAM 1; REACT: 0; PERS. PROTECT. A; CHRONIC HAZ. YES

#### FIRST AID PROCEDURES:

SKIN: Immediately flush contaminated skin with plenty of water for at least 15 minutes. Get medical attention if irritation develops.  
EYES: Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
INHALE: Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
INGEST: If this product is swallowed, do not induce vomiting. If individual is alert, give plenty of water to drink. Get medical attention at once.

### SECTION IV - SPECIAL PROTECTION INFORMATION

PROTECTIVE CLOTHING: As with all chemical products, prolonged skin contact should be avoided. Implement protective measures under conditions of prolonged use or exposure.

EYE PROTECTION: To prevent accidental eye contact, the use of safety glasses or goggles is recommended when using any aerosol product.  
RESPIRATORY PROTECTION: Avoid inhalation of spray mists, and do not direct spray toward people.  
VENTILATION: Ventilation should be equal to outdoors. Use exhaust fans and/or exhaust hood in enclosed spaces.

### SECTION V - PHYSICAL DATA

BOILING POINT (°F): 185-215 SPECIFIC GRAVITY: 1.10  
VAPOR PRESSURE (mmHg): N/D EVAPORATION RATE (WATER=1): 1.0  
VAPOR DENSITY(AIR=1): N/D PH(CONCENTRATE): 10.5-11.0  
SOLUBILITY IN WATER: COMPLETE PH/USE DILUTION OF N/A: N/A  
VOC CONTENT (CONCENTRATE): 27.4%  
APPEARANCE AND ODOR: CLEAR, COLORLESS FOAMY LIQUID HAVING A MILD PLEASANT ODOR

### SECTION VI - FIRE AND EXPLOSION DATA

FLASH POINT(F) (METHOD USED): Nonflammable  
FLAMMABLE LIMITS: LEL: N/D UEL: N/D  
EXTINGUISHING MEDIA: Carbon dioxide, dry chemical and foam.  
SPECIAL FIRE FIGHTING: Wear self-contained positive pres. breathing apparatus.  
UNUSUAL FIRE HAZARDS: Direct water onto inlaid containers to prevent bursting.

### SECTION VII - REACTIVITY DATA

STABILITY: Stable  
INCOMPATIBILITY(AVOID): Strong oxidizing agents.  
POLYMERIZATION: Will not occur.  
ARDOUS DECOMPOSITION: Carbon dioxide, carbon monoxide, and other unidentified organic compounds.

### SECTION VIII - SPILL AND DISPOSAL PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:  
Observe safety precautions in sections 4 & 9 during spill clean-up. Large spills are unlikely due to packaging. Spill may be absorbed on an inert absorbent material (eg Zep-O-Zorb), and placed in a suitable container for disposal. Wash area thoroughly with a detergent solution and rinse well with water.  
WASTE DISPOSAL METHOD:  
Product is consumed in use. Do not crush, puncture or incinerate spent containers. Large numbers of aerosol containers may require handling as a hazardous waste, but in most states total hazardous waste quantities less than 220 lbs per month may allow disposal in a chemical or industrial waste landfill. Consult local, state and federal agencies for the proper disposal method in your area.  
RCRA HAZ. WASTE NOS.: NA



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

3-09

1/12/8/96  
ISSUE DATE: 09/01/95  
SUPERSEDES:  
TIRELESS SHINE  
PRODUCT NO. 0063

Arrested Tire Dressing

## SECTION I - EMERGENCY CONTACTS

MISSOURI SURPLUS (317)  
PROPERTY-JANITORIAL  
1172 RIVERSIDE  
JEFFERSON CITY, MO 65101

TELEPHONE: (404) 352-1680 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (770) 439-4200 NON-OFFICE HOURS, WEEKENDS  
(770) 432-2873 AND HOLIDAYS, PLEASE CALL YOUR  
(770) 424-4789 LOCAL POISON CONTROL  
(770) 392-1480  
(770) 455-8160  
(770) 552-8836  
TRANSPORTATION EMERGENCY: (770) 922-0923  
CHEMTRAC: 1-800-424-9300 TOLL-FREE - ALL CALLS RECORDED  
DISTRICT OF COLUMBIA: (202) 483-7616 ALL CALLS RECORDED

## SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PHOD.
** PROPRIETARY SOLVENT BLEND ** CAS # PROPRIETARY; RTECS # NONE; OSHA PEL- 200 ppm (skin); STEL- 250	200	FBL IRR CNS	70-80

## SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

### Acute Effects of Overexposure:

The solvents in this product, when inhaled or absorbed in harmful quantities, may produce central nervous system depression characterized by headache, nausea, dizziness and stupor. Vapors or spray mists may be irritating to nasal and respiratory tract. Product may be irritating to skin and eyes resulting in redness, itching or burning. Introduction of solvents, as in aspiration of vomitus fluid, may produce chemical pneumonia. Existing respiratory disorders and skin diseases may be aggravated by exposure.

### Chronic Effects of Overexposure:

Skin which is repeatedly defatted by contact with this product may be more susceptible to irritation, infection, or dermatitis. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

std PEL/TLV: Not established

Primary Routes of Entry: Inh.

HMS Codes: HEALTH 2:FLAM. 4:REACT. 0:PERS. PROTECT. B. CHRONIC HAZ. YES

### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** Move exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Get medical attention immediately.  
**Ingest:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

## SECTION IV - SPECIAL PROTECTION INFORMATION

**Protective Clothing:** Wear neoprene, nitrile, or natural rubber gloves or gloves with proven resistance to the ingredients listed.  
**Eye Protection:** Wear light-fitting safety glasses when using or handling this product.  
**Respiratory Protection:** When exposure levels exceed PEL/TLV (likely in confined areas) use an organic vapor respirator (eg Zep 2211).  
**Ventilation:** Provide local exhaust/ventilation as needed to keep concentration of vapors below exposure limits (PEL/TLV).

## SECTION V - PHYSICAL DATA

Boiling Point (°F):	290 INITIAL	Specific Gravity:	0.733	Vapor Pressure (mmHg):	N/D
Percent Volatile by Volume (%):	75	Vapor Density (air = 1):	N/D	Evaporation Rate (BUTYL ACETATE = 1):	> 1
Solubility in Water:	NEGUGIBLE	pH (concentrate):	N/A	pH (use dilution of N/A):	N/A
Appearance and Odor:	A CLEAR, COLORLESS LIQUID WITH A SOLVENT ODOR.				

## SECTION VI - FIRE AND EXPLOSION DATA

**Flash Point (°F) (method used):** Extremely Flammable (CSMA)  
**Flammable Limits:** LEL N/D UEL N/D  
**Extinguishing Media:** Carbon dioxide, dry chemical and foam.  
**Special Fire Fighting:** Wear self-contained positive pres. breathing apparatus.  
**Unusual Fire Hazards:** Direct water onto intact containers to prevent bursting.

# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

3535



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

05/12/93  
ISSUE DATE: 11/25/91  
SUPERSEDES: 04/21/89  
ZEP FORMULA 50  
PRODUCT NO. 0859

General Purpose Cleaner

MISSOURI SURPLUS  
PROPERTY-JANITORIAL  
1172 RIVERSIDE  
JEFFERSON CITY, MO 65101

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (404) 435-2973 NON-OFFICE HOURS, WEEKENDS  
(404) 351-2952 AND HOLIDAYS, PLEASE CALL YOUR  
(404) 432-2873 LOCAL POISON CONTROL  
TRANSPORTATION EMERGENCY: (404) 922-0923  
CHEMTREC: (404) 922-0923  
TOLL-FREE - ALL CALLS RECORDED  
1-800-424-9300  
DISTRICT OF COLUMBIA: ALL CALLS RECORDED  
(202) 483-7616

### SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PROD.
@ * ETHYLENE GLYCOL MONOBUTYL ETHER * 2-butoxyethanol; butyl cellosolve; CAS # 111-76-2; RTECS # KJ8575000;	25	TOX IRR CBL	< 5
* SODIA PEL (SKIN)- 25 ppm			
* SODIUM METASILICATE * silicic acid (H <sub>2</sub> SiO <sub>3</sub> ) disodium salt; water glass; CAS # 6834-92-0; RTECS # VV9275000;	N/D	COR	< 5
OSHA Dust Limit: 2mg/m <sup>3</sup> (for powders only).			
* SODIUM DODECYLBENZENE SULFONATE * linear alkyl aryl sodium sulfonate; CAS # 25155-30-0; RTECS # DB6825000; OSHA PEL N/D	N/D	IRR	< 5

@ Identifies chemicals listed under SARA-Section 313 for release reporting

### SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

**Acute Effects of Overexposure:**  
Product is considered non-toxic orally according to 16 CFR, 1500.3 (Code of Federal Regulations 16, Federal Hazardous Substances Act Regulations, Part 1500.3). However, no product should be intentionally ingested. Ingestion of an excessive amount of the product may cause complications. Product in concentrated form is a severe eye irritant. Overexposure may lead to eye tissue damage which can be permanent. This product may cause slight skin irritation. Overexposure by inhalation may cause respiratory irritation. Existing eye or respiratory disorders may be aggravated by exposure.

**Chronic Effects of Overexposure:**  
Repeated eye exposure may produce chronic inflammation of the eye or corneal damage. Animal studies indicate a potential for liver, kidney, or red blood cell damage. Relevance of these studies or exposure levels which might produce these effects in humans has not been established. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

Est'd PEL/TLV: Not established  
Primary Routes of Entry: inh, Skin.

HMIS Codes: HEALTH 2;FLAM. 0;REACT. 0;PEHS. PROTECT. B. CHRONIC HAZ. YES

### FIRST AID PROCEDURES:

**Skin:** Flush contaminated skin with plenty of water. Consult a physician if irritation develops.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes; occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
**Ingest:** If this product is swallowed, do not induce vomiting. If victim is conscious give plenty of water to drink. Get medical attention at once.

### SECTION IV - SPECIAL PROTECTION INFORMATION

**Protective Clothing:** Wearing neoprene or nitrile gloves is recommended when prolonged excessive contact occurs (eg immersing hands)  
**Eye Protection:** Wear tight-fitting splash-proof safety glasses especially if contact lenses are worn.  
**Respiratory Protection:** In the unlikely event that exposure levels exceed the PEL/TLV, use an organic vapor respirator (eg Zep 2211).  
**Ventilation:** Provide local exhaust/ventilation as needed to keep concentration of vapors below exposure limits (PEL/TLV).

### SECTION V - PHYSICAL DATA

Boiling Point (°F):	~220	Specific Gravity:	1.07	Vapor Pressure (mmHg):	N/D
Percent Volatile by Volume (%):	85%	Vapor Density (air = 1):	N/D	Evaporation Rate (WATER = 1):	1.0
Solubility in Water:	COMPLETE	pH (concentrate):	12.5-13.0	pH (use dilution of 1% SOLUTION):	11.0-11.5
Appearance and Odor:	A THIN, DARK BLUE LIQUID WITH SLIGHT "BUTYL" ODOR.				

### SECTION VI - FIRE AND EXPLOSION DATA

Flash Point (°F) (method used): N/D (TCC)  
Flammable Limits: LEL N/A UEL N/A  
Extinguishing Media: Noncombustible  
Special Fire Fighting: Wear self-contained positive pres. breathing apparatus.  
Unusual Fire Hazards: None



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

# MATERIAL SAFETY DATA SHEET AND SAFE HANDLING AND DISPOSAL INFORMATION

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

SOLD TO:

00006

MISSOURI SURPLUS (317)  
PROPERTY - JANITORIAL  
117 N RIVERSIDE DR  
JEFFERSON CITY MO 65101

ISSUE DATE: 05/06/98

Date printed: 12/08/98

**SUPERSEDES:**  
**ZEP DIESEL FUEL ADDITIVE**  
Prod No.: 0583 Diesel Fuel Additive

**SECTION I - EMERGENCY CONTACTS**

**TELEPHONE:** (404) 352-1680 *BETWEEN 8:00 AM - 5:00 PM (EST)*  
**MEDICAL EMERGENCY:** (770) 439-4200  
(770) 432-2873 *NON OFFICE HOURS, WEEKENDS  
AND HOLIDAYS, PLEASE CALL  
LOCAL POISON CONTROL*  
(770) 424-4789  
(770) 424-2048  
(770) 455-8160  
(770) 552-8836

**TRANSPORTATION EMERGENCY:**  
(770) 922-0923

**CHEMTRAC:** (800) 424-9300 **TOLL FREE-CALLS RECORDED**  
**DISTRICT OF COLUMBIA:** (770) 922-0923  
(202) 483-7616 **ALL CALLS RECORDED**

A25224

**SECTION II - HAZARDOUS INGREDIENTS**

**DESIGNATIONS**  
\*\* ALIPHATIC NAPHTHA \*\* liquid, CAS# 8052-41-3; RTECS#  
WJ895200; OSHA PEL - 100 ppm  
\*\* HEAVY AROMATIC NAPHTHA \*\* solvent naphtha (petroleum), heavy  
aromatics; CAS# 64742-94-5; RTECS# NONE; Supplier TWA - 100 ppm;  
OSHA PEL-N/D.

(PPM)	EFFECTS (SEE NOTICE)	% IN PROD.
100	CNS CBL	50-60
N/D	IRR CBL	20-30

**SECTION III - HEALTH HAZARD DATA**

**SPECIAL NOTE:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

**ACUTE EFFECTS OF OVEREXPOSURE:**

Overexposure to the vapors from this product may produce mucous membrane irritation, particularly of the eye and respiratory tract. Overexposure to vapors may also produce mild central nervous system depression characterized by headache, dizziness, nausea, and stupor, leading to unconsciousness in extreme cases. Introduction of solvents, as in aspiration of vomitus fluid, may produce chemical pneumonia. Existing respiratory disorders and lung diseases may be aggravated by inhalation of vapors.

Ingredients in this product may aggravate existing skin, eye, or respiratory disorders.

Repeated or prolonged inhalation exposure may produce reversible lung damage. Skin which is repeatedly contacted by contact with solvents may be more susceptible to irritation, infection, and dermatitis.

None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.  
ESTD PEL TVL: Not established PRIMARY ROUTES OF ENTRY: Inh, Skin.

HMIS CODES: HEALTH 2; FLAM. 2; REACT. 0; PERS. PROTECT. 8; CHRONIC HAZ. NO

**FIRST AID PROCEDURES:**

**SKIN:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**EYES:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**INHALE:** Move exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Get medical attention immediately.  
**INGEST:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

**SECTION IV - SPECIAL PROTECTION INFORMATION**

**PROTECTIVE CLOTHING:** Wear neoprene, nitrile, or natural rubber gloves or gloves with proven resistance to the ingredients listed.  
**EYE PROTECTION:** Use of light fitting safety glasses or goggles is strongly recommended, especially when wearing contact lenses.  
**RESPIRATORY PROTECTION:** When exposure levels exceed PEL/TLV (likely in confined areas) use an organic vapor respirator (eg Zep 2211).  
**VENTILATION:** Provide local exhaust/ventilation as needed to keep concentration of vapors below exposure limits (PEL/TLV).

**SECTION V - PHYSICAL DATA**

BOILING POINT (F):	355	SPECIFIC GRAVITY:	0.85
VAPOR PRESSURE (mmHg):	N/D	EVAPORATION RATE: (BUTYL ACETATE=1):	< 0.1
VAPOR DENSITY(AIR=1):	> 1.0	PH(CONCENTRATED):	N/A
SOLUBILITY IN WATER:	INSOLUBLE	PH(DILUTION OF NA):	N/A
VOC CONTENT (CONCENTRATED):	82.0%		
APPEARANCE AND ODOR: A CLEAR, AMBER LIQUID WITH A SOLVENT ODOR			

**SECTION VI - FIRE AND EXPLOSION DATA**

**FLASH POINT(G) (METHOD USED):** 110  
**FLAMMABLE LIMITS, LEL:** 1.0 UEL: 6.0  
**EXTINGUISHING MEDIA:** Carbon dioxide, dry chemical, water fog, foam.  
**SPECIAL FIRE FIGHTING:** Wear self-contained positive pres. breathing apparatus.  
**UNUSUAL FIRE HAZARDS:** Fire exposed drums should be cooled with stream of water.

**SECTION VII - REACTIVITY DATA**

**STABILITY:** Stable  
**INCOMPATIBILITY(AVOID):** Heat, open flame, spark, and oxidizing agents.  
**POLYMERIZATION:** Will not occur.  
**HAZARDOUS DECOMPOSITION:** Carbon dioxide, carbon monoxide, and other unidentified organic compounds.

**SECTION VIII - SPILL AND DISPOSAL PROCEDURES**

**STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:**  
Immediately eliminate all flame, ignition and high-heat sources. Absorb spill on inert absorbent material (eg Zep-0-Zorb). Pick up and place residue in a clean, D.O.T. specification container for disposal. Wash area thoroughly with a detergent solution and rinse well with water.  
**WASTE DISPOSAL METHOD:**  
Liquids cannot be sent to landfills unless solidified. Unusable product and collected spent material may require disposal as a hazardous waste at a notified treatment/storage/disposal facility. Solvent wastes may require treatment to meet the appropriate standards before disposal in a chemical industrial waste landfill. Consult local, state, and federal agencies for proper disposal method in your area.

RA HAZ. WASTE NOS.: D001

**SECTION IX - SPECIAL PRECAUTIONS**

**PRECAUTIONS TO BE TAKEN WHEN HANDLING AND STORING:**  
**Combustible:** Store and use away from heat, sparks, open flame, or any source of ignition.  
Store tightly closed container in a dry area at temps. between 40-120 degrees F.  
Keep product away from skin and eyes.  
Do not breathe spray mists or vapors.  
Clothing or shoes which become contaminated with substance should be removed promptly and not re worn until thoroughly cleaned.  
Vapors are heavier than air and will accumulate at low points. Ventilation should include floor level exhausting.

(Continued on Page 2)



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

# MATERIAL SAFETY DATA SHEET

1805

AND SAFE HANDLING AND DISPOSAL INFORMATION

01/07/95

ISSUE DATE: 12/03/93

SUPERSEDES:

DIESEL FUEL ADDITIVE W/O DYE

PRODUCT NO.: 0573

Diesel Fuel Additive

## SECTION I - EMERGENCY CONTACTS

### TELEPHONE:

(404) 352-1680

BETWEEN 8:00 AM - 5:00 PM (EST)

### MEDICAL EMERGENCY:

(404) 435-2973

NON-OFFICE HOURS, WEEKENDS

(404) 432-2873

AND HOLIDAYS, PLEASE CALL YOUR

(404) 424-4789

LOCAL POISON CONTROL

(404) 319-6151

(404) 242-3561

### TRANSPORTATION EMERGENCY:

(404) 922-0923

### CHEMTREC:

1-800-424-9300

DISTRICT OF COLUMBIA:

(202) 483-7616

TOLL-FREE - ALL CALLS RECORDED

ALL CALLS RECORDED

## SECTION II - HAZARDOUS INGREDIENTS

### DESIGNATIONS

™ KEROSENE ™ kerosene; fuel oil # 1; coal oil; CAS # 8008-20-6; RTECS # OAS500000; OSHA PEL-N/D  
™ 2-ETHYLHEXYL NITRATE ™ CAS # 27247-96-7; RTECS # 1 NONE; OSHA PEL-N/D; MANUFACTURER'S TWA:10 PPM

TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PRUD.
N/D	IRR CBL	70-80
N/D	TOX FBL	15-25

## SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

### Acute Effects of Overexposure:

Overexposure to the vapors from this product may produce mucous membrane irritation, particularly of the eye and respiratory tract. Overexposure to vapors may also produce mild central nervous system depression characterized by headache, dizziness, nausea, and stupor, leading to unconsciousness in extreme cases. Introduction of solvents, as in aspiration of vomitus fluid, may produce chemical pneumonia. Existing respiratory disorders and lung diseases may be aggravated by inhalation of vapors.

### Chronic Effects of Overexposure:

Repeated or prolonged inhalation exposure may produce reversible lung damage. Skin which is repeatedly dented by contact with solvents may be more susceptible to raction, infection, and dermatitis. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

™ D PELTLV: Not established

Primary Routes of Entry: Inh

HMIS Codes: HEALTH 2;FLAM. 2;REACT. 0;PERS. PROTECT. B;CHRONIC HAZ. YES

### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.

**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.

**Inhale:** Move exposed person to fresh air. If irritation persists, get medical attention promptly.

**Ingest:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

## SECTION IV - SPECIAL PROTECTION INFORMATION

**Protective Clothing:** Wear neoprene, nitrile, or natural rubber gloves or gloves with proven resistance to the ingredients listed.

**Eye Protection:** Wear tight-fitting splash-proof safety glasses especially if contact lenses are worn.

**Respiratory Protection:** When exposure levels exceed PELTLV (likely in confined areas) use an organic vapor respirator (eg Zep 2211).

**Ventilation:** Provide local exhaust/ventilation as needed to keep concentration of vapors below exposure limits (PELTLV).

## SECTION V - PHYSICAL DATA

**Boiling Point (°F):** 350-500

**Specific Gravity:** 0.84

**Vapor Pressure (mmHg):** 0.4 mmHg

**Percent Volatile by Volume (%):** 95

**Vapor Density (air = 1):** N/D

**Evaporation Rate (BUTYL ACETATE = 1):** <0.1

**Solubility in Water:** EMULSIFIERS

**pH (concentrate):** N/A

**pH (use dilution of N/A):** N/A

**Appearance and Odor:** A CLEAR, THIN AMBER LIQUID WITH A STRONG "SOLVENT" ODOR.

## SECTION VI - FIRE AND EXPLOSION DATA

**Flash Point (°F) (method used):** 126F (TCC)

**LEL 1.0 UEL 8.0**

**Flammable Limits:** Carbon dioxide, dry chemical and foam.

**Extinguishing Media:** Wear self-contained positive pres. breathing apparatus.

**Special Fire Fighting:** Concentrated vapor may ignite if exposed to spark.

**Unusual Fire Hazards:**



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

MISSOURI SURPLUS (317)  
PROPERTY-JANITORIAL  
1172 RIVERSIDE  
JEFFERSON CITY, MO 65101

# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

02/02/96  
ISSUE DATE: 10/20/94  
SUPERSEDES:  
ZEP DYNAMITE  
PRODUCT NO.: 0566

Truck and Trailer Wash

## SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680  
MEDICAL EMERGENCY: (770) 435-4200  
(404) 432-2873  
(404) 424-4789  
(404) 392-1480  
(404) 455-8160  
(404) 552-8836

BETWEEN 8:00 AM - 5:00 PM (EST)  
NON-OFFICE HOURS, WEEKENDS  
AND HOLIDAYS, PLEASE CALL YOUR  
LOCAL POISON CONTROL

## TRANSPORTATION EMERGENCY:

(770) 922-0923

CHEMTREC: 1-800-424-9300  
DISTRICT OF COLUMBIA: TOLL-FREE - ALL CALLS RECORDED  
(202) 483-7616 ALL CALLS RECORDED

## SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	TLV (PPM) N/D	EFFECTS (SEE REVERSE) EIR	% IN PROD. < 5
@ SODIUM LAURYL ETHER SULFATE ~ SODIUM LAURETH SULFATE: CAS # 9004-82-4; RTECS # WB7350000; OSHA PEL N/D	N/D	EIR	< 5
~ ALCOHOLS, C9-11, ETHOXYLATED ~ linear primary alcohol ethoxyate (6 moles) EO); CAS # 68439-46-3; RTECS # NONE; OSHA PEL N/D	N/D	IRR	< 5
~ TETRASODIUM ETHYLENEDIAMINE TETRAACETATE ~ ethylenedinitrilo tetracetic acid, tetrasodium salt; EDTA; CAS # 64-02-8; RTECS # AH4025000; OSHA PEL N/D	N/D	IRR	5-15

@ Identifies chemicals listed under SARA-Section 313 for release reporting

## SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

### Acute Effects of Overexposure:

This product may irritate eyes and skin upon contact. Inflammation of the eye is characterized by redness, watering, and itching. Skin inflammation is characterized by ching, scaling, reddening, or, occasionally, blistering. Overexposure by inhalation may cause respiratory irritation. Ingredients in this product may aggravate existing skin, eye, or respiratory disorders.

### Chronic Effects of Overexposure:

Repeated or prolonged skin contact may produce chronic inflammation or dermatitis characterized by redness, scaling, or itching. Repeated eye exposure may produce chronic inflammation of the eye or corneal damage. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

Est'd PEL/TLV: Not established

Primary Routes of Entry: Inh

HMIS Codes: HEALTH 2:FLAM 2:REACT 0:PERS. PROTECT. B:CHRONIC HAZ NO

### FIRST AID PROCEDURES:

**Skin:** Immediately flush contaminated skin with plenty of water for at least 15 minutes. Get medical attention immediately.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
**Ingest:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

## SECTION IV - SPECIAL PROTECTION INFORMATION

### Protective Clothing:

Wear neoprene, nitrile or natural rubber gloves or gloves with proven resistance to the ingredients listed.

### Eye Protection:

Wear splash-proof safety goggles especially if contact lenses are worn.

### Respiratory Protection:

Provide local exhaust/ventilation as needed to keep concentration of vapors below exposure limits (PEL/TLV).

## SECTION V - PHYSICAL DATA

Boiling Point (°F):	~ 220	Specific Gravity:	1.053	Vapor Pressure (mmHg):	N/D
Percent Volatile by Volume (%):	84	Vapor Density (air = 1):	N/D	Evaporation Rate (WATER = 1):	1.0
Solubility in Water:	COMPLETE	pH (concentrate):	12.9	pH (use dilution of 1 %):	11.2
Appearance and Odor:	A CLEAR, YELLOW-GREEN, THIN LIQUID WITH A DETERGENT ODOR.				

## SECTION VI - FIRE AND EXPLOSION DATA

Flash Point (°F) (method used): 164 (TCC)  
Flammable Limits: LEL N/D UEL N/D  
Extinguishing Media: Carbon dioxide, dry chemical, water, and foam  
Special Fire Fighting: Wear self-contained positive pres. breathing apparatus.  
Unusual Fire Hazards: Fire exposed drums should be cooled with stream of water.

# MATERIAL SAFETY DATA SHEET

## AND SAFE HANDLING AND DISPOSAL INFORMATION



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

06/26/93

ISSUE DATE: 02/14/90  
SUPERSEDES: 08/16/89

ZEP AUTO GLAZE  
PRODUCT NO.: 0458

Auto Polishing Compound

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (404) 435-2973 NON-OFFICE HOURS, WEEKENDS  
(404) 351-2952 AND HOLIDAYS, PLEASE CALL YOUR  
(404) 432-2873 LOCAL POISON CONTROL  
TRANSPORTATION EMERGENCY: (404) 922-0923  
CHEMTREC: 1-800-424-9300 TOLL-FREE - ALL CALLS RECORDED  
DISTRICT OF COLUMBIA: (202) 483-7616 ALL CALLS RECORDED

TAGGART GARY  
117 N RIVERSIDE  
PO DRAWER 1310  
JEFFERSON CITY, MO 65102

### SECTION II - HAZARDOUS INGREDIENTS

#### DESIGNATIONS

™ MINERAL SPIRITS ™ ligroin, aliphatic naphtha. CAS # 8052-41-3. RTECS # WJ8952000. OSHA PEL-100 PPM  
™ HYDRATED ALUMINUM SILICATE ™ kaolin, china clay. CAS # 1332-58-7. RTECS # NONE. OSHA PEL-10 mg/m<sup>3</sup>  
(nuisance dust)

TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PROD.
100	CNS,CBL	20-30
N/D	IRR	5-10

### SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

#### Acute Effects of Overexposure:

Overexposure to the vapors from this product may produce mucous membrane irritation, particularly of the eye and respiratory tract. Overexposure to vapors may also produce mild central nervous system depression characterized by headache, dizziness, nausea, and stupor, leading to unconsciousness in extreme cases. Introduction of solvents, as in aspiration of vomitus fluid, may produce chemical pneumonia. Existing respiratory disorders and lung diseases may be aggravated by vapors. Ingredients in this product may aggravate existing skin, eye, or respiratory disorders.

#### Chronic Effects of Overexposure:

Repeated or prolonged inhalation exposure may produce reversible lung damage. Skin which is repeatedly defatted by contact with solvents may be more susceptible to ation, infection, and dermatitis. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

Est'd PEL/TLV: Not established

Primary Routes of Entry: Inh, Skin

HMIS Codes: HEALTH 1;FLAM: 3;REACT: 0;PERS: PROTECT B ;CHRONIC HAZ: YES

#### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
**Ingest:** If swallowed, do not induce vomiting. If vomiting occurs, keep head below hip level. Get emergency medical attention immediately.

### SECTION IV - SPECIAL PROTECTION INFORMATION

#### Protective Clothing:

Wear neoprene, nitrile, or natural rubber gloves or gloves with proven resistance to the ingredients listed.

#### Eye Protection:

Wear tight-fitting splash-proof safety glasses especially if contact lenses are worn.

#### Respiratory Protection:

Use NIOSH-approved dust mask if dust is present. Ventilation should be equivalent to outdoors. Use exhaust fans and open windows in enclosed spaces.

### SECTION V - PHYSICAL DATA

Boiling Point (°F):	220 (INITIAL)	Specific Gravity:	0.98	Vapor Pressure (mmHg):	N/D
Percent Volatile by Volume (%):	87	Vapor Density (air = 1):	N/D	Evaporation Rate (WATER = 1):	>1.0
Solubility in Water:	EMULSIFIES	pH (concentrate):	9.0-9.5	pH (use dilution of):	N/A
Appearance and Odor:	A WHITE, THICK CREAMY LIQUID WITH SOLVENT ODOR.				

### SECTION VI - FIRE AND EXPLOSION DATA

Flash Point (°F) (method used): 98F (TCC )  
Flammable Limits: LEL 1.0% UEL 7.0%  
Extinguishing Media: CO<sub>2</sub>, DRY CHEMICAL, WATER FOG  
Special Fire Fighting: Wear self-contained positive pres. Breathing apparatus.  
Unusual Fire Hazards: Concentrated vapor may ignite if exposed to spark.



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

04-07-94  
ISSUE DATE: 04-23-90  
SUPERSEDES: 07-09-89  
ZEP PRO FINISH  
PRODUCT NO.: 0428

Auto Polishing Compound

## SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (404) 435-2973 NON-OFFICE HOURS, WEEKENDS  
(404) 351-2952 AND HOLIDAYS, PLEASE CALL YOUR  
(404) 432-2873 LOCAL POISON CONTROL  
TRANSPORTATION EMERGENCY: (404) 922-0923  
CHEMTREC: 1-800-424-9300 TOLL-FREE - ALL CALLS RECORDED  
DISTRICT OF COLUMBIA: (202) 483-7616 ALL CALLS RECORDED

MISSOURI SURPLUS  
PROPERTY-JANITORIAL  
1172 RIVERSIDE  
JEFFERSON CITY, MO 65101

## SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PROD.
~ LOW ODOR PARAFFINIC SOLVENT ~ odorless base oil; dispersol; CAS # 64742-47-8; RTECS # NONE; OSHA PEL-500 ppm	500	CNS CBL	5-10
~ MINERAL SEAL OIL ~ (mineral oil); petrolatum; CAS # 64741-44-2; RTECS # PY8030000; ACGIH/OSHA OIL MIST LIMIT = 5mg/M3	N/A	IRR	1-5
~ ISOPROPYL ALCOHOL ~ ipa; dimethylcarbinol; 2-propanol; CAS # 67-63-0; RTECS # NT8050000; OSHA PEL-400 ppm; OSHA/ACGIH STEL-500 PPM	400	IRR FBL	1-5

## SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

### Acute Effects of Overexposure:

This product may irritate eyes and skin upon contact. Inflammation of the eye is characterized by redness, watering, and itching. Skin inflammation is characterized by itching, scaling, reddening, or, occasionally, blistering. This product is not sufficiently volatile to constitute a significant inhalation hazard. Severe overexposure to concentrated vapor may produce mild central nervous system depression, characterized by headache and stupor. Introduction of solvents, as in aspiration of vomitus, may produce chemical pneumonia.

### Chronic Effects of Overexposure:

Contact, especially if prolonged or repeated, may cause redness, itching, or blistering of the skin. Skin which is repeatedly irritated by contact with this product may be more susceptible to irritation, infection, or dermatitis. None of the ingredients are listed as carcinogens by IARC, NTP, or OSHA.

EST'D PEL/TLV: Not established

Primary Routes of Entry: Inh.

HMS Codes: HEALTH 2;FLAM 2;REACT 0;PERS PROTECT B;CHRONIC HAZ YES

### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhale:** Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
**Ingest:** If this product is swallowed, do not induce vomiting. If victim is conscious give plenty of water to drink. Get medical attention at once.

## SECTION IV - SPECIAL PROTECTION INFORMATION

**Protective Clothing:** The use of neoprene, nitrile or natural rubber gloves is strongly recommended, especially for prolonged contact.  
**Eye Protection:** Use of tight-fitting safety glasses or goggles is strongly recommended, especially when wearing contact lenses.  
**Respiratory Protection:** If ventilation is inadequate, wear a properly fitting MSHA or OSHA-approved respirator.  
**Ventilation:** If vapors are detected, ventilate work area by opening windows and using exhaust fans.

## SECTION V - PHYSICAL DATA

Boiling Point (°F):	N/D	Specific Gravity:	0.97	Vapor Pressure (mmHg):	N/D
Percent Volatile by Volume (%):	~ 87	Vapor Density (air = 1):	> 1	Evaporation Rate (ETHYL ETHER = 1):	>> 1
Solubility in Water:	DISPERSIBLE	pH (concentrate):	9.2	pH (use dilution of N/A):	N/A
Appearance and Odor: OPAQUE, VISCIOUS, YELLOWISH LIQUID WITH SOLVENT ODOR					

## SECTION VI - FIRE AND EXPLOSION DATA

Flash Point (°F) (method used): 185 (TCC)  
Flammable Limits: LEL N/D UEL N/D  
Extinguishing Media: CO2, DRY CHEMICALS, FOAM  
Special Fire Fighting: Direct water onto intact containers to prevent bursting  
Unusual Fire Hazards: Wear self-contained positive pres. Breathing apparatus



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

# MATERIAL SAFETY DATA SHEET

AND SAFE HANDLING AND DISPOSAL INFORMATION

12:28:94

ISSUE DATE: 06 20 94  
SUPERSEDES: 07 12 89  
ZEP BIG ORANGE  
PRODUCT NO.: 0415

Industrial Solvent Degreaser

MISSOURI SURPLUS  
PROPERTY-JANITORIAL  
1172 RIVERSIDE  
JEFFERSON CITY, MO 65101

## SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680 BETWEEN 8:00 AM - 5:00 PM (EST)  
MEDICAL EMERGENCY: (404) 435-2973 NON-OFFICE HOURS, WEEKENDS  
(404) 432-2873 AND HOLIDAYS, PLEASE CALL YOUR  
(404) 424-4789 LOCAL POISON CONTROL  
(404) 319-6151  
(404) 242-3561  
TRANSPORTATION EMERGENCY: (404) 922-0923  
CHEMTREC: 1-800-424-9300 TOLL-FREE - ALL CALLS RECORDED  
DISTRICT OF COLUMBIA: (202) 483-7616 ALL CALLS RECORDED

## SECTION II - HAZARDOUS INGREDIENTS

DESIGNATIONS	TLV (PPM)	EFFECTS (SEE REVERSE)	% IN PROD.
** D-LIMONENE ** orange distillate; citrus terpene; cyclohexene, 1-methyl-4-(1-methylethyl)-; (R)-CAS # 5989-27-5;	N/D	CBL SEN	> 90
RTECS # GW6360000; OSHA PEL N/D			
** ALCOHOLS, C11-C15-SECONDARY, ETHOXYLATED ** CAS # 68131-40-8; RTECS # WZ5200000; OSHA PEL N/D	N/D	EIR	< 5
** NONYLPHENOXYPOLYETHYLENEOXYETHANOL ** poly(oxy-1,2-ethanediyl), alpha-(nonylphenyl)-omega-hydroxy;	N/D	EIR	< 5
CAS # 9016-45-9; RTECS # MD905000; OSHA PEL-N/D			

## SECTION III - HEALTH HAZARD DATA

**Special Note:** MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

### Acute Effects of Overexposure:

This product can be an eye irritant. Inflammation of eye tissue is characterized by redness, watering, and/or itching. One of the ingredients in this product has caused sensitization reactions in a small percentage of the general population.

### Chronic Effects of Overexposure:

contact, especially if prolonged or repeated, may cause redness, itching, or blistering of the skin. None of the hazardous ingredients are listed as carcinogens by IARC, I.P. & OSHA

Est'd PEL/TLV: Not established

Primary Routes of Entry: N/A

HMS Codes: HEALTH 1:FLAM, 2:REACT, 0:PERS, PROTECT A, CHRONIC HAZ, NO

### FIRST AID PROCEDURES:

**Skin:** Wash contaminated skin thoroughly with soap or a mild detergent. Apply a skin cream with lanolin. Get medical attention if irritation persists.  
**Eyes:** Immediately flush eyes with plenty of water for at least 15 minutes; occasionally lifting upper and lower lids. Get medical attention at once.  
**Inhalation:** Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
**Ingest:** If this product is swallowed, do not induce vomiting. If victim is conscious give plenty of water to drink. Get medical attention at once.

## SECTION IV - SPECIAL PROTECTION INFORMATION

**Protective Clothing:** Wear nitrile gloves or use gloves with demonstrated resistance to the ingredients in this product.  
**Eye Protection:** Wear tight-fitting splash-proof safety glasses especially if contact lenses are worn.  
**Respiratory Protection:** No special measures are required.  
**Ventilation:** No special measures are required.

## SECTION V - PHYSICAL DATA

Boiling Point (°F):	338-375	Specific Gravity:	0.853	Vapor Pressure (mmHg):	N/A
Percent Volatile b. volume (%):	93.8	Vapor Density (air = 1):	N/A	Evaporation Rate (CCL4 = 1):	~33
Solubility in Water:	EMULSIFIES	pH (concentrate):	N/A	pH (use dilution of 1:20):	7.6
Appearance and Odor:	ORANGE LIQUID WITH A CITRUS ODOR				

## SECTION VI - FIRE AND EXPLOSION DATA

Flash Point (°F) (method used): 121 (TCC)  
Flammable Limits: LEL N/A UEL N/A  
Extinguishing Media: Carbon dioxide, dry chemical and foam  
Special Fire Fighting: Fire exposed drums should be cooled with stream of water.  
Unusual Fire Hazards: None



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

# MATERIAL SAFETY DATA SHEET AND SAFE HANDLING AND DISPOSAL INFORMATION

1-877-1-BUY-ZEP (1-877-428-9937)

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

SOLD TO:

00820

(317)  
MISSOURI SURPLUS PROPERTY  
117 N RIVERSIDE DR  
JEFFERSON CITY MO 65101

ISSUE DATE: 10/02/00  
SUPERSEDES: 10/04/89  
ZEP FAST GASKET BLUE  
Prod No: 0413  
Silicone Gasket Compound and Sealant

Date printed: 10/29/00

### SECTION I - EMERGENCY CONTACTS

TELEPHONE: (404) 352-1680  
MEDICAL EMERGENCY: (770) 439-4200  
(770) 432-2873  
(770) 424-4789  
(770) 424-2048  
(770) 455-8160  
(770) 552-8836  
TRANSPORTATION EMERGENCY: (770) 922-0923  
CHEMTRAC: (800) 424-9300  
DISTRICT OF COLUMBIA: (202) 483-7616

BETWEEN 8:00 AM - 5:00 PM (EST)  
NON OFFICE HOURS, WEEKENDS  
AND HOLIDAYS, PLEASE CALL  
LOCAL POISON CONTROL

TOLL FREE CALLS RECORDED  
TOLL FREE CALLS RECORDED  
ALL CALLS RECORDED

A25224

### SECTION II - HAZARDOUS INGREDIENTS

\*\* METHYLTRIACTOXYSILOXANE \*\* acetoxy silane; CAS# 4253-34-3;  
OSHA/ACGIH PEL/TLV 10 PPM (for acetic acid only)  
\*\* ETHYLTRIACTOXYSILOXANE \*\* acetoxy silane; CAS# 17689-77-9;  
OSHA/ACGIH PEL/TLV 10 PPM (for acetic acid only)  
\*\* SILICA AMORPHOUS \*\* CAS# 7631-86-9; OSHA PEL: TWA 20 MPPCF;  
ACGIH TLV 10 mg/m3

(PPM)	EFFECTS (SEE NOTICE)	% IN PROD.
N/D	IRR	< 10
N/D	IRR	< 10
N/D	IRR	5-15

### SECTION III - HEALTH HAZARD DATA

SPECIAL NOTE: MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

#### ACUTE EFFECTS OF OVEREXPOSURE:

This product can be an eye irritant. Inflammation of eye tissue is characterized by redness, watering, and/or itching. Overexposure to the vapors from this product may produce mucous membrane irritation, particularly of the eye and respiratory tract.

#### CHRONIC EFFECTS OF OVEREXPOSURE:

Some of the hazardous ingredients are listed as carcinogens by IARC, NTP & OSHA.

ESTD PEL/TLV: Not established PRIMARY ROUTES OF ENTRY: inh, Skin.

HMS CODES: HEALTH 1; FLAM: 1; REACT: 0; PERS: PROTECT; CHRONIC HAZ: NO

#### FIRST AID PROCEDURES:

**SKIN:** Wash contaminated skin with soap or a mild detergent. Get medical attention if irritation develops.  
**EYES:** Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
**INHALE:** Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
**INGEST:** If this product is swallowed, do not induce vomiting. If victim is conscious give plenty of water to drink. Get medical attention at once.

### SECTION IV - SPECIAL PROTECTION INFORMATION

**PROTECTIVE CLOTHING:** The use of neoprene, nitrile or natural rubber gloves is strongly recommended, especially for prolonged contact.  
**EYE PROTECTION:** Use of tight-fitting safety glasses or goggles is strongly recommended, especially when wearing contact lenses.  
**RESPIRATORY PROTECTION:** If ventilation is inadequate, wear a properly fitting MSHA or OSHA-approved respirator.  
**VENTILATION:** Ventilation should be equivalent to outdoors. Use exhaust fans and open windows in enclosed spaces.

### SECTION V - PHYSICAL DATA

**BOILING POINT (F):** ~ 300  
**VAPOR PRESSURE (mmHg):** N/D  
**VAPOR DENSITY(AIR=1):** N/A  
**SOLUBILITY IN WATER:** <0.1%  
**VOC CONTENT (CONCENTRATE):** 0.09%  
**APPEARANCE AND ODOR:** BLUE PASTE WITH ACETIC ACID-TYPE ODOR

**SPECIFIC GRAVITY:**  
**EVAPORATION RATE (BUTYL ACETATE=1):**  
**PH (CONCENTRATE):**  
**PH (USE DILUTION OF N/A):**

1.04  
<1  
N/A  
N/A

### SECTION VI - FIRE AND EXPLOSION DATA

**FLASH POINT(F) (METHOD USED):** 212  
**FLAMMABLE LIMITS:** LEL: N/A UEL: N/A  
**EXTINGUISHING MEDIA:** Carbon dioxide, dry chemical, and water fog.  
**SPECIAL FIRE FIGHTING:** Wear self-contained positive pres. breathing apparatus.  
**UNUSUAL FIRE HAZARDS:** Direct water onto intact containers to prevent bursting.

### SECTION VII - REACTIVITY DATA

**STABILITY:** Stable  
**INCOMPATIBILITY(AVOID):** Strong oxidizing agents.  
**POLYMERIZATION:** Will not occur.  
**HAZARDOUS DECOMPOSITION:** Carbon dioxide and fumes of acetic acid and silicon dioxide.

### SECTION VIII - SPILL AND DISPOSAL PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:  
Observe safety precautions in sections 4 & 9 during spill clean-up. Large spills are unlikely due to packaging. Spill may be absorbed on an inert absorbent material (eg Zep-O-Zorb), and placed in a suitable container for disposal. Wash area thoroughly with a detergent solution and rinse well with water.

#### WASTE DISPOSAL METHOD:

Product is consumed in use. Large numbers of small containers may require handling as a hazardous waste, but in most states, total hazardous waste of less than 220 lbs. per month may be disposed of in a chemical or industrial waste landfill. Consult local, state and federal agencies for proper disposal method in your area.  
HAZ WASTE NOS: N/A

### SECTION IX - SPECIAL PRECAUTIONS

**PRECAUTIONS TO BE TAKEN WHEN HANDLING AND STORING:**  
Do not store at temperatures above 120F (50C) or in direct sunlight. Do not puncture or incinerate container.  
Avoid direct inhalation of vapors.  
Clothing or shoes which become contaminated with substance should be removed promptly and not re-worn until thoroughly cleaned.  
Keep product out of eyes.  
Keep out of the reach of children.



CLEAN ACROSS AMERICA AND  
THROUGHOUT THE WORLD™

# MATERIAL SAFETY DATA SHEET

## AND SAFE HANDLING AND DISPOSAL INFORMATION

ZEP MANUFACTURING COMPANY  
P.O. BOX 2015  
ATLANTA, GEORGIA 30301

SOLD TO:

MISSOURI SURPLUS (317)  
PROPERTY - JANITORIAL  
117 N RIVERSIDE DR  
JEFFERSON CITY MO 65101

ISSUE DATE: 06/15/88  
SUPERSEDES: 06/06/88

Date printed: 12/08/98

ZEP-O-SHINE  
Prod No: 0382

Car Wash - Liquid

SECTION I - EMERGENCY CONTACTS	
TELEPHONE: (404) 352-1680	BETWEEN 8:00 AM - 5:00 PM (EST)
MEDICAL EMERGENCY: (770) 439-4200	NON OFFICE HOURS, WEEKENDS AND HOLIDAYS, PLEASE CALL LOCAL POISON CONTROL
(770) 432-2873	
(770) 424-4789	
(770) 424-2048	
(770) 455-8160	
(770) 552-8836	
TRANSPORTATION EMERGENCY: (770) 922-0923	
CHEMTRAC: (800) 424-9300	TOLL FREE CALLS RECORDED
DISTRICT OF COLUMBIA: (202) 483-7616	ALL CALLS RECORDED

A25224

### DESIGNATIONS

\*\* NONYL PHENOXYPOLYETHYLENEOXYETHANOL \*\* npe:  
Poly(oxy-1,2-ethanediyl)-alpha-(nonylphenyl)-omega-hydroxy;  
CAS# 9016-45-9; RTECS# MD0900000; OSHA PEL- M/D

### SECTION II - HAZARDOUS INGREDIENTS

(PPM)	EFFECTS (SEE NOTICE)	% IN PROD.
ND	EIR	20-30

### SECTION III - HEALTH HAZARD DATA

SPECIAL NOTE: MSDS data pertains to the product as dispensed from the container. Adverse health effects would not be expected under recommended conditions of use (diluted) so long as prescribed safety precautions are practiced.

#### ACUTE EFFECTS OF OVEREXPOSURE:

This product in concentrated form may be an eye irritant. Inflammation of eye tissue is characterized by redness, watering, and/or itching.

#### CHRONIC EFFECTS OF OVEREXPOSURE:

There are no known effects from chronic exposure to this product.  
None of the hazardous ingredients are listed as carcinogens by IARC, NTP, & OSHA  
ESTD PELTV: Not established. PRIMARY ROUTES OF ENTRY: N/A

MS CODES: HEALTH 0; FLAM 0; REACT 0; PERS PROTECT A ; CHRONIC HAZ NO

#### FIRST AID PROCEDURES:

SKIN: Flush contaminated skin with plenty of water. Consult a physician if irritation develops.  
EYES: Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting upper and lower lids. Get medical attention at once.  
INHALE: Move exposed person to fresh air. If irritation persists, get medical attention promptly.  
INGEST: If this product is swallowed, do not induce vomiting. If victim is conscious give plenty of water to drink. Get medical attention at once.

### SECTION IV - SPECIAL PROTECTION INFORMATION

PROTECTIVE CLOTHING: No special measures are required.  
EYE PROTECTION: Use of light-tinting safety glasses or goggles is strongly recommended, especially when wearing contact lenses.  
RESPIRATORY PROTECTION: No special measures are required.  
VENTILATION: No special measures are required.

### SECTION V - PHYSICAL DATA

BOILING POINT (F):	215	SPECIFIC GRAVITY:	1.01
VAPOR PRESSURE (mmHg):	N/A	EVAPORATION RATE (WATER=1):	1
VAPOR DENSITY(AIR=1):	N/A	PH(CONCENTRATE):	6.5-7.0
SOLUBILITY IN WATER:	COMPLETE	PH(USE DILUTION OF 1%):	7.0

### SECTION VI - FIRE AND EXPLOSION DATA

FLASH POINT(O) (METHOD USED): None  
FLAMMABLE LIMITS: LEL: N/A UEL: N/A  
EXTINGUISHING MEDIA: Noncombustible.  
SPECIAL FIRE FIGHTING: None  
UNUSUAL FIRE HAZARDS: None

### SECTION VII - REACTIVITY DATA

STABILITY: Stable  
INCOMPATIBILITY(AVOID): None  
POLYMERIZATION: Will not occur.  
HAZARDOUS DECOMPOSITION: NONE

### SECTION VIII - SPILL AND DISPOSAL PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:  
Observe safety procedures in section 4 & 9 during clean-up. Absorb spill on inert absorbent material (eg Zep-O-Zorb). Pick up and place residue in a suitable waste container or, if permitted, flush to sewer. Thoroughly rinse spill area with water.  
WASTE DISPOSAL METHOD:  
Liquid wastes are not permitted in landfills. This product is not considered a hazardous waste under RCRA. Unusable liquid may be absorbed on an inert absorbent material (eg Zep-O-Zorb), drummed, and taken to a chemical or industrial landfill in some areas disposal by flushing into a sanitary sewer with plenty of water may be permissible. Consult local, state, and federal agencies for proper disposal method in your area.  
RCRA HAZ. WASTE NOS.: N/A

### SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN WHEN HANDLING AND STORING:  
"Keep product out of eyes.  
ep out of the reach of children.

### SECTION X - REGULATORY INFORMATION

DOT PROPER SHIPPING NAME: INDUSTRIAL CLEANERS N.O.L.LIQUID KEEP FROM FREEZING  
NOTE: DOT information applies to larger package sizes of affected products. For some products, DOT may require alternate names and labeling in accordance with packaging group requirements.  
DOT HAZARD CLASS: DOT PACKING GROUP:  
DOT I.D. NUMBER: DOT LABEL/PLACARD:  
DOT HAZARD CLASS: DOT PACKING GROUP:  
EPA TSCA CHEMICAL INVENTORY - ALL INGREDIENTS ARE LISTED  
EPA CWA 40CFR PART 117 SUBSTANCE(R) IN A SINGLE CONTAINER: NONE  
(Continued on Page: 2)

OPEN & SHUT  
DA 6151

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

MANUFACTURED FOR:  
Drummond American Corporation  
600 Corporate Woods Pkwy.  
Vernon Hills, IL 60061

IN CASE OF EMERGENCY CALL:  
ROCKY MOUNTAIN POISON & DRUG CENTER  
COLLECT AT: (303) 623-5716

DATE OF PREPARATION:  
02/01/98

INFORMATION TELEPHONE NUMBER  
(847) 913-9313

SECTION I - IDENTITY

PRODUCT NUMBER DA 6151  
PRODUCT NAME OPEN & SHUT  
PRODUCT CLASS SOLVENTS

SECTION II - INGREDIENTS

INGREDIENT	CAS NUMBER	%	ACGIH TLV PPM	MG/ M <sup>3</sup>	PEL PPM	STEL PPM
PETROLEUM DISTILLATE	64742-47-8	5-20	500	ND	ND	ND
PETROLEUM OIL	64742-52-5	5-20	ND	5	ND	ND
TRICHLOROETHYLENE *	79-01-6	50-75	50	ND	50	100
CARBON DIOXIDE	124-38-9	1-5	5000	ND	10M	30M

\* THIS CHEMICAL IS SUBJECT TO  
S.A.R.A TITLE III SECTION 313  
REPORTING

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT (degrees F): 165  
VAPOR DENSITY: Heavier than air  
EVAPORATION RATE: > Butyl Acetate  
PERCENT VOLATILE (By Weight): N/A WEIGHT PER GALLON (LBS): 10.33

OPTIONAL INFORMATION:

Appearance/ Odor: Clear brown liquid, sweet odor.  
Specific Gravity (Water=1): 1.24  
Solubility in Water: Negligible  
Vapor Pressure (mm Hg): 89

CALIFORNIA PROPOSITION 65 WARNING: THIS PRODUCT CONTAINS A CHEMICAL  
KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER.

OPEN & SHUT  
DA 6151

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION: OSHA CLASS N/A  
DOT CLASS ORM-D U.N. CLASSIFICATION:  
PER DOT N/A  
PER IMCO N/A

FLASH POINT: N/A

LEL: 7.0

UEL: 13.0

METHOD: TAG CLOSED CUP

AEROSOL PRODUCT: TREAT AS CYLINDER OF COMPRESSED GAS

EXTINGUISHING MEDIA: WATER FOG

UNUSUAL FIRE AND EXPLOSION HAZARDS:

At elevated temperatures (over 120°F) containers may vent, rupture,  
or burst.

SPECIAL FIREFIGHTING PROCEDURE:

Keep containers cool. Use shielding to protect personnel against  
bursting, rupturing or venting containers. Wear a positive pressure  
self-contained breathing apparatus.

SECTION V - REACTIVITY DATA

STABILITY: STABLE

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

HAZARD DECOMPOSITION PRODUCTS:

Hydrogen chloride, oxides of carbon, and minute traces of phosgene  
and chlorine may be formed upon combustion or thermal decomposition.

CONDITIONS TO AVOID:

None Known.

INCOMPATIBILITY (MATERIALS TO AVOID):

Strong bases, oxidizing materials, metallic aluminum, and zinc  
powders.

D.O.T. EMERGENCY RESPONSE INFORMATION:

\*\*\*NOT APPLICABLE\*\*\*

LIVE-WIRE  
DA 6030

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

MANUFACTURED FOR:  
Drummond American Corporation  
600 Corporate Woods Pkwy.  
Vernon Hills, IL 50061

IN CASE OF EMERGENCY CALL:  
ROCKY MOUNTAIN POISON & DRUG CENTER  
COLLECT AT: (303) 623-5716

DATE OF PREPARATION:  
09/01/95

INFORMATION TELEPHONE NUMBER  
(847) 913-9313

SECTION I - IDENTITY

PRODUCT NUMBER DA 6030  
PRODUCT NAME LIVE-WIRE  
PRODUCT CLASS CLEANERS

SECTION II - INGREDIENTS

INGREDIENT	CAS NUMBER	%	ACGIH TLV PPM	MG/ M <sup>3</sup>	PEL PPM	STEL PPM
2-BUTOXYETHANOL *	111-76-2	1-5	25	N/D	50	N/D
PROPELLANT: C3-C4 ALKANE BLEND	68475-59-2	1-10	N/D	N/D	ND	N/D

\* THIS CHEMICAL IS SUBJECT TO  
S.A.R.A TITLE III SECTION 313  
REPORTING. THE REMAINING  
INGREDIENTS AND THEIR  
PERCENTAGES ARE PROPRIETARY.

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT (degrees F): 212  
VAPOR DENSITY: LIGHTER THAN AIR  
EVAPORATION RATE: SLOWER THAN ETHER  
PERCENT VOLATILE (By Weight): N/A WEIGHT PER GALLON (LBS): N/A

OPTIONAL INFORMATION:

Appearance/Odor: clear, thin liquid with a mild ammonia odor.  
Specific Gravity: 1.01 Soluble in water: complete. Vapor Density: <1  
Evaporation Rate (Butyl Acetate=1): <1. Vapor Pressure: 18

LIVE-WIRE  
DA 6030

MATERIAL SAFETY DATA SHEET  
ESSENTIALLY SIMILAR TO OSHA FORM 174

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION: OSHA CLASS N/A DOT CLASS N/A U.N. CLASSIFICATION: PER DOT N/A PER IMCO N/A

FLASH POINT: N/A

LEL: N/A

UEL: N/A

METHOD: TAG CLOSED CUP

AEROSOL PRODUCT: TREAT AS CYLINDER OF COMPRESSED GAS

EXTINGUISHING MEDIA: WATER FOG

UNUSUAL FIRE AND EXPLOSION HAZARDS:  
At elevated temperatures (over 130 degrees Fahrenheit) containers  
may vent, rupture or burst.

SPECIAL FIREFIGHTING PROCEDURE:  
Keep containers cool. Use shielding to protect personnel against  
bursting, rupturing or venting containers.

SECTION V - REACTIVITY DATA

STABILITY: STABLE

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

HAZARD DECOMPOSITION PRODUCTS:  
Thermal decomposition may produce oxides of carbon and nitrogen.

CONDITIONS TO AVOID:  
Avoid heating to abnormal temperatures.

INCOMPATIBILITY (MATERIALS TO AVOID):  
NONE.

D.O.T. EMERGENCY RESPONSE INFORMATION:  
\*\*\*NOT APPLICABLE\*\*\*



Appendix D

Ameren UE Correspondence



CAPITAL DISTRICT  
 AMERENUE  
 P.O. BOX 1558  
 JEFFERSON CITY, MO 65102-1558

DATE: 6-22-01

PLEASE DELIVER TO: RICK WHITNEY

COMPANY: TSI

FACSIMILE NUMBER: 314-644-3135

FROM: MARK LUCKENHOFF

FACSIMILE NUMBER: 573-681-7510

TELEPHONE NUMBER: 573-681-7530

PAGES TO FOLLOW: 1

MESSAGE: TRANSFORMER INFO AT SURPLUS PROPERTY

117 N. RIVERSIDE DR, JEFFERSON CITY, MO

Are You Feb TRANSFORMERS AT THE 3 LOCATIONS

WITHE OWNER By AMEREN UE





# Appendix B

**M S P**

## OBSERVATION OF THE ENCLOSURE WALLS

MSP

Jefferson City, MO

On the date of April 17, 2002, I visited the site of the Jefferson City Correctional Center in Jefferson City, Missouri. The purpose of the trip was to observe the condition of the enclosure walls on the east and south sides of the facility, which are experiencing some signs of deterioration as well as a partial collapse. The wall is built of locally quarried limestone and is approximately 30-36 inches thick. No testing of the material was done. In visual observation the stone is fairly dense with naturally occurring, thin visible seams in it. The height varies, but is generally in the range of 20-25 feet in height. It is three wythes thick, with the outer two wythes being cut stone and the inner wythe being rough uncoursed stone. At each coursed level of the inner and outer wythe there is a thick mortar layer which bonds the three wythes together. This can be seen as a horizontal white line in photos of the collapsed wall section. The top of the wall on the south has been extended vertically about 68 inches with a reinforced concrete section. There is a stone veneer on the exterior face of the concrete. The wall in this area is said to have been built about 1885; the extension was done at a later date. The wall is capped with a sloped layer of concrete parging, which varies from 0 to 3 inches thick. It is curved on top for drainage. For the purposes of identification, the wythe of stone on the interior of the prison will be referred to as the interior wythe and the wythe on the public side of the wall will be referred to as the exterior wythe.


The wall has two areas of concern, water infiltration and horizontal earth pressure. The two types of deterioration can be best exemplified by the damage on the east and south walls. The east wall shows several areas of water infiltration damage. The water infiltration shows up as two distinct types of damage. The stone in several areas have had the faces spalled off. Also, several portions show the entire interior face wythe to be delaminated from the inner wythe. The stone, which is laid with the natural seams running horizontally, shows less distress than those seams laid vertically. This is because the pressure of the wall weight is holding the seams in compression. The water appears to be entering the wall through the cap parging and eroded mortar joints. The water then moves vertically between wythes and is trapped inside and saturates the stone. The water inside the wall will freeze and push the outer wythe away from the inner wythe. Where the stones are spalling, the saturated stone has split at a natural seam where the water has collected and frozen.



**Spalled Stone Face**



**Area of Wall Delamination**



**Cracked Concrete Cap**



### **Cross Section of Wall Showing Construction**

The wall on the south side of the facility has a large area of localized collapse. The collapse is only of the inner wythe of the stone wall. In this area the wall shows both rotation about the axis of the wall footing and a horizontal displacement between the two guard towers in the southwest corner of the facility. The wall is failing in overturning as well as possibly horizontal sliding. The damage appears to have been ongoing for many years. There are cracks associated with this movement which have been tuckpointed several years ago. The wall in this area retains 6 – 8 feet of soil; the grade being higher on the exterior side. There have been several types of utility work on the outside of the wall, which are in the influence zone of the backfill. It is possible that this utility work could have increased horizontal earth pressure on the wall, due to backfill compaction or water entering an open excavation. The wall is currently stable and is being restrained by the reinforced concrete band on the top acting as a tension strut. The portion of the wall,

which fell, appears to have delaminated from the middle and exterior wythes, which are still intact. The delamination would have been a consequence of the water infiltration as discussed in previous portions of this report. After the inner wythe was loose, it became unstable due to the angle of rotation of the entire wall. This wall should have a temporary bracing system installed to prevent overturning and complete collapse.



**Collapsed Wall Section with Concrete on Top**



**Horizontal Displacement of Wall at Grade**




### **Wall Rotation**

To conclude, the primary cause of distress in the wall is water infiltration of the wall. The horizontal earth pressure has caused a section of the wall to rotate to the point where the loose wythe of stone collapsed. The portion of the south wall, which has partially collapsed, should be braced with a temporary frame to ensure public safety until a permanent bracing system is installed and repairs can be made. From the standpoint of economy and site logistics a steel frame on the interior side of the wall would seem to be the optimal solution. Care should be taken during the installation of the bracing to ensure the safety of the construction crew. Work should proceed from the guard towers towards the center and the concrete beam at the top should not be disturbed until the shoring is in place.

Hopefully this addresses the concerns of all regarding this structure. If you have any questions please do not hesitate to call.

Sincerely,  
Wallace Engineering

Steven Huey, P.E.  
Principal



# Appendix C

**M S P**

February 11, 2003

MSP Redevelopment Project

## A Presentation To The Citizens of

Jefferson City , Cole County and The State of Missouri

A Review and Discussion of the Framework Plan  
For The  
MSP Redevelopment Project

Jefferson City, Missouri




The State of Missouri . Division of Design & Construction

Framework Plan

MSP Redevelopment Project

## Review

- The Planning Process
- The Consensus Plan
- Market Analysis
- Architectural Elements
- Engineering Elements
- Environmental Elements
- The Master Plan



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Process Definition Plan

MSP Redevelopment Project

## *The Preamble*

**“The Planning Process is On-going”**



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Process Definition Plan

MSP Redevelopment Project

## *Consensus Plan*

### **Task Force Results Concepts, Values and Priorities**

- Part A – Historic Value of the Property
- Part B – Historic Value of the Buildings
- Part C – Planning Values
- Part D – Potential Uses

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Process Definition Plan  
**Consensus Plan**

MSP Redevelopment Project

**Review & Input**

- Task Force Review & Input
- Public Comment
- Planning Advisory Team



**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Process Definition Plan  
**Consensus Plan** Program Statement

MSP Redevelopment Project

**Program Statement**



- Historic Area
- Judicial Center Area
- Community Area
- Office Area
- Landing Area
- Entertainment Area
- Natural Resources Area
- Additional Program Items



**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

## Market Analysis

### Market Analysis



**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

## Market Analysis

### Methodology and Rationale

- Realistic basis for planning and financing
- Projections of market absorption and timing
- Analysis of regional, state & national economic context
- Interviews of public and private officials
- Correlations of past growth with data indicators
- Projections of growth based on indicators
- Conversion of trends to building and land area needs

**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

## Market Analysis

### Cole County Office & Related Projections

- **Mid-Missouri should continue to attract population and job holders.**  
~Attraction is key because of low unemployment rate.
- **Impetus is continued growth of state government employment.**  
~Strong multiplier effect creates jobs in other sectors.
- **State government will grow because state population will grow.**  
~More government jobs will be needed to support more residents.
- **Net state office space growth in Cole County should range from 755,000 to 935,000 square feet by 2025.**  
~Total state office space in the county would be around 3.3 million square feet by 2025.  
~Possibly more square feet if historic trends prevail.
- **Private market would add 600,000 sf of office space.**

## Market Analysis

### Conditions for Success: Public Assembly Facility

- **Center of State Government**
- **Statewide and Mid-America associations growth**
  - ~ Religious
  - ~ Social
  - ~ Professional
  - ~ Athletic
  - ~ Political
- **Central location, Ease of Access**
- **State economic growth: More reasons to meet**
- **Sufficient and convenient hotel rooms**

## Market Analysis

### Public Assembly Facility

- **Single Open Floor Space to Accommodate up to 2,500 participants**
  - ~ Exhibits
  - ~ Ballroom
  - ~ Large group meetings
- **Separate, Divisible Meeting Areas**
  - ~ 10-15 rooms
  - ~ Combinable
- **Possible performing arts venue**
- **Full service kitchen**
- **Large and well-appointed lobby and pre-event area**
- **Appropriate number of parking spaces**

## Market Analysis

### Conclusions

- **Jefferson City area needs more sites for office development**
  - ~ State government alone could *add* over 750,000 square feet by 2025
  - ~ Private market adds perhaps another 600,000 square feet
  - ~ Plus land for campus settings, parking, road system
- **Public Assembly Facility appears to be a crucial need for accommodating demand & diversifying the local economy**
  - ~ Need to resolve location issues
  - ~ Absolutely need support good quality and walkable hotel rooms
- **MSP site offers solutions to these opportunities**
  - ~ Little else will be ready and available in time
  - ~ Fulfills Governor's order to concentrate state facilities in existing cities (Smart Growth philosophy)

Framework Plan

MSP Redevelopment Project

## Architectural Elements

### Architectural Elements



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

## Architectural Elements

### Task Force Evaluation

- Top 10 Buildings with Historical Value

1. Housing Unit 4
2. Housing Unit 1
3. Housing Unit 3A & 3B
4. The Wall & Towers (Upper Yard)
5. Gas Chamber
6. Centennial Cells
7. I-Hall
8. The Wall & Towers (Lower Yard)
9. Shoe Factory
10. Potato House




**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# Architectural Elements

## Buildings Analyzed



- Housing Unit 1
- Housing Unit 2
- Housing Unit 3
- Housing Unit 4
- Housing Unit 5
- Shoe Factory
- Furniture Factory
- Metal Working Plant
- Centennial Cells
- Gas Chamber
- Potato House
- Education Building & Maintenance Building
- Stone Walls

**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# Architectural Elements

## Buildings Re-Use

- 3 APPROACHES TO BUILDING RE-USE
  - ~ Preserve & Restore (HU 4)
  - ~ Combination Restore and Adaptive Re-Use (HU 1)
  - ~ Adaptive Re-Use (HU 2)



**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates


# Architectural Elements

## Housing Unit 4

### Existing Information



View of typical window



Existing First Floor Plan  
0' 25' 50'

**Preservation Zones**

- **Level 1 - Preservation Zone**  
The character & qualities of this zone should be maintained & preserved as the highest priority.
- **Level 2 - Preservation Zone**  
Every effort should be made to maintain and preserve the character and qualities of this zone.
- **Level 3 - Rehabilitation Zone**  
Undertake all work in this zone as sensitive as possible. However, contemporary methods, materials, & designs may be selectively incorporated.
- **Level 4 - Free Zone**  
Treatments in this zone, while sympathetic to the historic qualities & character of the building, may incorporate extensive changes or total replacement through the introduction of contemporary methods, materials & designs.



Interior View



View from Northwest

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

# Architectural Elements

## Housing Unit 4 Possible Uses

### Redevelopment Issues


1. What period should the building be restored? Many modifications have occurred to the building since it's construction.
2. It appears that the roof overhang and soffits were removed exposing brick backup material above the stone walls, these should be restored.
3. Stone restoration will be necessary. There are crushed stones at various locations and missing stone mullions in the window openings that should be restored.
4. Integrating modern mechanical systems could be completely hidden. The extent to which this is done will be dependant on the interpretive philosophy for this building.

### Potential Uses

1. Prison Museum / Interpretive Center. Each floor level could be restored and furnished to represent distinct time periods of prison life as shown in the Alternate Section above.

**Possible Use Zones**

- **Primary Use**  
This area identifies the primary use for the building.
- **Secondary Use**  
This area identifies additional uses for the building beyond the primary use.
- **Circulation**  
This area identifies a zone for potential hallways, new required stairs, lobbies and elevator cores.
- **Possible Addition**  
This area identifies a zone for potential development attached to this historic building and suggestions as to how it could be done in a sensitive manner.



Proposed First Floor Plan  
EACH CELL OR CELL LEVEL COULD BE RESTORED TO REPRESENT VARIOUS PERIODS UP TO DECOMMISSIONING  
0' 25' 50'



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

# Architectural Elements

## Architectural Summary

- 1. Preserving the context of the site from a “public” view and a “user” view
- 2. Preserving the “Essence of the Prison”
- 3. Potential Building Uses Based On:
  - Structural Considerations
  - Architectural/Historic Value
  - Consensus Plan Proposed Land Uses



# Engineering Elements

## Engineering Elements



Framework Plan

MSP Redevelopment Project

# Engineering Elements

## Findings

- Existing Infrastructure Minimal and Antiquated
- Building Systems (MEPF) are not suitable for commercial development



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# Engineering Elements

## Findings

- New Utility Infrastructure required
  - Electric
  - Gas
  - Water
  - Sewer
  - Data/Communications



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

## Environmental Elements

### Environmental Elements

...Understanding the basics



The Built Environment

The Natural Resources

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

## Environmental Elements

### Environmental Investigations ...the Built Environment

- Site Investigations
- Building Investigations
- HazMat Testing
- Records Search
- Interviews
- Phase I Environmental Assessment



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Process Definition Plan  
**Consensus Plan** Program Statement

MSP Redevelopment Project

**Program Statement**

- Historic Area
- Judicial Center Area
- Community Area
- Office Area
- Landing Area
- Entertainment Area
- Natural Resources Area
- Additional Program Items



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan  
**The Master Plan** Updated Program Statement

MSP Redevelopment Project

**Program Statement**

- **MSP Historic Area**  
(Historic Area & Community Area)
- **Public Service Campus**  
(Judicial Center Area)
- **Public Assembly Campus**  
(Entertainment Area & Landing Area)
- **Office Campus**  
(Office Area)
- **Natural Resources Area**



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

**The Master Plan** Program Statement

---

Public Service Campus

Public Assembly Campus  
Entertainment Area & Landing Area

MSP Historic Area  
& Community Area

Office Campus

Natural Resources Area

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

**The Master Plan** Vehicular Circulation

---

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

## The Master Plan *Parking*

---



The site plan illustrates the parking layout for the project. It features several colored zones: a yellow zone with 485 spaces, a purple zone with 1250 spaces, a red zone with 400 spaces, a blue zone with 250 spaces, a green zone with 850 spaces, and a red zone with 600 spaces. A small red circle with the number 15 is located near the bottom right. A legend on the right side of the plan lists various site features and their corresponding symbols.

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

## The Master Plan

---



The site plan shows the building footprints and site layout. A red arrow points to a specific area on the left side of the plan, likely indicating a key feature or entrance. A legend on the right side of the plan lists various site features and their corresponding symbols.

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan *Vehicular Circulation*



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

**The Master Plan** Program Statement

---

## Program Statement Summary

Master Plan District	Proposed/Reuse Area	Master Plan Parking	
• <b>MSP Historic Area</b>	310,048 GFA	600 Structured Spaces	P-2
• <b>Public Service Campus</b>	225,000 GFA	485 Structured Spaces	P-1
• <b>Public Assembly Campus</b>	605,500 GFA	650 Structured Spaces 100 Structured Spaces 300 Structured Spaces 250 Surface Spaces	P-2 P-3 P-3 P-4
• <b>Office Campus</b>	1,000,000 GFA	850 Structured Spaces 600 Structured Spaces	P-5 P-7
• <b>Natural Resources Area</b>	NA	15 Surface Spaces	P-6
<b>Total Master Plan</b>	<b>2,140,548 GFA</b>	<b>3,850 Spaces</b>	

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

**The Master Plan** Program Statement

---

## MSP Historic Area

<b>Administration Building (HU #1)</b> Museum/Interpretative MSP Commission Offices Redevelopment Office Support Retail / Commercial Tourist Information Center Film Site or Studio Educational	<b>Office Building (HU #3)</b> State Offices Record Storage Prison Museum (40%)	<b>The Gas Chamber</b>  <b>Community Area</b> MSP Interpretative Garden Pedestrian Linkages Open Space Urban Plaza (interpretative plaza)
<b>Office Building (HU #2)</b> Corrections Offices New Building Addition	<b>MSP Museum (HU #4)</b>  <b>Conference Center</b> Historic Dining Hall (Basement) Power Plant (Basement) Dining Rooms & Kitchen Conference Center	
<b>Centennial Cells</b> Historic Display	<b>The Wall</b> Guard Tower Reconstruction The Old Wall Pedestrian Openings Vehicular Openings	
<b>Total - MSP Historic Area 310,048 GFA 600 Structured Spaces P-2</b>		

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

*The Master Plan* MSP Historic Area

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

*The Master Plan* MSP Historic Area

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan Program Statement

## Public Service Campus

**Justice/Office Center**  
 Court Rooms  
 Offices  
 Holding Space

**Justice/Office Center Annex**  
 Administrative Offices  
 Library  
 Museum

**Public Service Office Building**  
 Private Office Space  
 Support Retail/Commercial  
 Art Gallery  
 Science Center

**Other**  
 Streetscape  
 Pedestrian Entry Plaza

Total - Public Service Campus 225,000 GFA 485 Structured Spaces P-1

PARSONS HBA in association with Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan Public Service Campus



PARSONS HBA in association with Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

**The Master Plan** Program Statement

**Public Assembly Campus**

**Hotel #1 (HU #5)**  
Hotel (250 Rooms)

**Hotel #1 Conference Center**  
Building Addition  
Meeting Rooms

**Hotel #2**  
Hotel (275 Rooms)

**Hotel #3**  
Hotel (275 Rooms)

**Public Assembly Facility**  
Auditorium (25,000 sf)  
Exhibition (70,000 sf)  
Multi-Purpose Space (25,000 sf)  
Support (5,000 sf)

**The Landing**  
Support Tourism Retail Shops  
Restaurants  
Excursion / Riverboat Landing  
Observation Deck / Tower (Pedestrian Only)  
Amtrak Station  
Pedestrian Linkages & Access to Adrian's Island

**Potato House**  
Commercial / Retail  
Farmers Market  
Interpretative Center  
Trail Head  
Greenway Trail Connection

**Other**  
Streetscape  
Public Plaza & Pedestrian Linkages  
Open Space, Lakes & Fountains

**Total – Public Assembly Campus 605,500 GFA 1300 Spaces**

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

**The Master Plan** Public Assembly Campus




**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan *Public Assembly Campus*



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan *Program Statement*

## Office Campus

**State Government Office (750,000 GFA)**  
General Office Space (550,000 sf)  
DNR Green Building (120,000 sf)  
Health Lab (80,000 sf)  
Support Commercial / Retail  
Service Area  
Shuttle Access

**Private Business Office (250,000 GFA)**  
General Office Space  
Support Commercial / Retail  
Service Area  
Shuttle Access

**Other**  
Streetscape  
Public Plaza  
Pedestrian Linkages  
Transportation Linkages

**Total – Office Campus 1,000,000 GFA 1450 Spaces**

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

## The Master Plan Office Campus

---



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan MSP Redevelopment Project

## The Master Plan Office Campus

---



The exterior profile of the green office building helps capture and reflect light into the building significantly reducing the need for interior lighting.

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan Program Statement

## Natural Resources Area

- Grounds Maintenance
- Riverfront Park
- Active and Passive Recreation
- Picnic Areas
- Public Land Open Space
- Greenway Trail Connection
- Botanical Gardens
- Amphitheater
- Reserve Land For Future

Total – Natural Resources Area	NA	15 Surface Spaces P-6
--------------------------------	----	-----------------------

**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan Natural Resources Area



**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan



**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Next Steps

## The Next Steps Planning + Design



- Archeological Investigations (I & II)**  
DNR Site  
Lab Site  
Remaining Site
- Phase II Archeological Investigations**  
Remaining Site
- Natural Resource Analysis**  
Flora & Fauna  
Threatened & Endangered
- Historic Designations**  
Section 106 - Districts, Buildings & The Wall
- Environmental Investigation (I & II)**  
Remaining Site

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

## The Next Steps

### The Next Steps

#### Planning + Design



#### Decommission Existing Facility

Demolition Phasing Plan (timeline / strategies)

#### Site & Building Demolition Plan

Demolition Material Recycle  
Wall Stabilization

#### New & Existing Infrastructure

New & Existing Infrastructure Implementation Plan

#### Historic District Heating/Cooling

#### Site Improvements

On-site Road Plan  
Parking Plan  
Grading Plan  
Landscape Plan

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

## The Next Steps

### The Next Steps

#### Planning + Design



#### Implementation Strategies & Planning

Site & Architectural Design Guidelines  
Delivery Systems Guidelines  
Design / Build  
Lease Purchase  
Conventional  
Phasing Plan  
Facility Interim Use  
Public Access  
Decision Timeline

#### Financial Guidelines & Planning

Project Feasibility  
Development Fees  
Development Incentives  
Funding  
Revenue Generation

#### Surplus Property Relocation

Relocation Program  
Site Selection

**PARSONS HBA** in association with  
Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# Questions & Answers



**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates

Framework Plan

MSP Redevelopment Project

# The Master Plan




**PARSONS HBA** in association with  
 Development Strategies . Trivers Associates . TSI Engineering . William Tao & Associates . George Dickie Associates



# Appendix D

**M S P**

**The Master Plan**



DATE: October 2022  
REVISIONS:

Prepared by:  
Parsons HBA  
450 Woods Mill Road South, Suite 300  
St. Louis, Missouri 63107-1027  
In Collaboration with:  
Development Strategies, Inc.  
Trivers Associates, Inc.  
TSi Engineering, Inc.  
William Tao & Associates, Inc.  
George Dickie Associates

State of Missouri  
800 HICKORY GROVE  
Office of Administration  
Division of Design and Construction  
Reedy Hill, Jefferson City  
P.O. Box 609  
Jefferson City, Missouri 65102

STRUCTURES TO REMAIN  
MSP REDEVELOPMENT PROJECT  
JEFFERSON CITY, MISSOURI  
PROJECT NUMBER: 0-000-01  
PARSONS HBA PROJECT NUMBER: 750008

0 200 400

SHEET:  
**M-3**



**The Master Plan**



**The Master Plan**



Proposed Master Plan Looking West